

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-2/15/07	030704871-0001	Southwest Area (sidewalk bridge level)	2/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST2-2/15/07	030704871-0002	Southeast Area (sidewalk bridge level)	2/15/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST4-2/15/07	030704871-0003	Northwest Area (street-level)	2/15/07	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST5-2/15/07	030704871-0004	Firehouse #10 (roof level)	2/15/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST11-2/15/07	030704871-0005	90 Trinity Place (roof level)	2/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST12-2/15/07	030704871-0006	110 Greenwich Street (roof level)	2/15/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST13-2/15/07	030704871-0007	Marriott Hotel, 38th Floor (roof level)	2/15/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST14-2/15/07	030704871-0008	West Face - South end at corner (scaffolding level)	2/15/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST15-2/15/07	030704871-0009	South Face - East end at corner (scaffolding level)	2/15/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST16-2/15/07	030704871-0010	East Face - North end at corner (scaffolding level)	2/15/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST17-2/15/07	030704871-0011	North Face - West end at corner (scaffolding level)	2/15/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/16/07	< 13.00	No	No		
ASBESTOS-ST1-2/16/07	030705102-0001	Southwest Area (sidewalk bridge level)	2/16/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST2-2/16/07	030705102-0002	Southeast Area (sidewalk bridge level)	2/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST4-2/16/07	030705102-0003	Northwest Area (street-level)	2/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST5-2/16/07	030705102-0004	Firehouse #10 (roof level)	2/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST10-2/16/07	030705102-0005	North Side Sidewalk Bridge	2/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST100-2/16/07	030705102-0013	Station 10 Field Duplicate	2/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST11-2/16/07	030705102-0006	90 Trinity Place (roof level)	2/16/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST12-2/16/07	030705102-0007	110 Greenwich Street (roof level)	2/16/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST13-2/16/07	030705102-0008	Marriott Hotel, 38th Floor (roof level)	2/16/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST14-2/16/07	030705102-0009	West Face - South end at corner (scaffolding level)	2/16/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST15-2/16/07	030705102-0010	South Face - East end at corner (scaffolding level)	2/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST16-2/16/07	030705102-0011	East Face - North end at corner (scaffolding level)	2/16/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST17-2/16/07	030705102-0012	North Face - West end at corner (scaffolding level)	2/16/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST1-2/17/07	030705103-0001	Southwest Area (sidewalk bridge level)	2/17/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST2-2/17/07	030705103-0002	Southeast Area (sidewalk bridge level)	2/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST4-2/17/07	030705103-0003	Northwest Area (street-level)	2/17/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST5-2/17/07	030705103-0004	Firehouse #10 (roof level)	2/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST10-2/17/07	030705103-0005	North Side Sidewalk Bridge	2/17/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST11-2/17/07	030705103-0006	90 Trinity Place (roof level)	2/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST12-2/17/07	030705103-0007	110 Greenwich Street (roof level)	2/17/07	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST13-2/17/07	030705103-0008	Marriott Hotel, 38th Floor (roof level)	2/17/07	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST14-2/17/07	030705103-0009	West Face - South end at corner (scaffolding level)	2/17/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST15-2/17/07	030705103-0010	South Face - East end at corner (scaffolding level)	2/17/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST16-2/17/07	030705103-0011	East Face - North end at corner (scaffolding level)	2/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST17-2/17/07	030705103-0012	North Face - West end at corner (scaffolding level)	2/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST1-2/18/07	030705104-0001	Southwest Area (sidewalk bridge level)	2/18/07	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST2-2/18/07	030705104-0002	Southeast Area (sidewalk bridge level)	2/18/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST4-2/18/07	030705104-0003	Northwest Area (street-level)	2/18/07	1	2.850	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST5-2/18/07	030705104-0004	Firehouse #10 (roof level)	2/18/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST10-2/18/07	030705104-0005	North Side Sidewalk Bridge	2/18/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST11-2/18/07	030705104-0006	90 Trinity Place (roof level)	2/18/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST12-2/18/07	030705104-0007	110 Greenwich Street (roof level)	2/18/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST13-2/18/07	030705104-0008	Marriott Hotel, 38th Floor (roof level)	2/18/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST14-2/18/07	030705104-0009	West Face - South end at corner (scaffolding level)	2/18/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST15-2/18/07	030705104-0010	South Face - East end at corner (scaffolding level)	2/18/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST16-2/18/07	030705104-0011	East Face - North end at corner (scaffolding level)	2/18/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 15.00	No	No		
ASBESTOS-ST17-2/18/07	030705104-0012	North Face - West end at corner (scaffolding level)	2/18/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/19/07	< 13.00	No	No		
ASBESTOS-ST1-2/19/07	030705209-0001	Southwest Area (sidewalk bridge level)	2/19/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST2-2/19/07	030705209-0002	Southeast Area (sidewalk bridge level)	2/19/07	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST4-2/19/07	030705209-0003	Northwest Area (street-level)	2/19/07	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST5-2/19/07	030705209-0004	Firehouse #10 (roof level)	2/19/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST10-2/19/07	030705209-0005	North Side Sidewalk Bridge	2/19/07	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST11-2/19/07	030705209-0006	90 Trinity Place (roof level)	2/19/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST12-2/19/07	030705209-0007	110 Greenwich Street (roof level)	2/19/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST13-2/19/07	030705209-0008	Marriott Hotel, 38th Floor (roof level)	2/19/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST14-2/19/07	030705209-0009	West Face - South end at corner (scaffolding level)	2/19/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST15-2/19/07	030705209-0010	South Face - East end at corner (scaffolding level)	2/19/07	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST16-2/19/07	030705209-0011	East Face - North end at corner (scaffolding level)	2/19/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		
ASBESTOS-ST17-2/19/07	030705209-0012	North Face - West end at corner (scaffolding level)	2/19/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/20/07	< 13.00	No	No		

Note:

1. Asbestos sample at Station 10 (North Side Sidewalk Bridge) on February 15, 2007 was not available for analysis on account of pump failure.