

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-4/20/07	030712361-0001	Southwest Area (sidewalk bridge level)	4/20/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST2-4/20/07	030712361-0002	Southeast Area (sidewalk bridge level)	4/20/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST4-4/20/07	030712361-0003	Northwest Area (street-level)	4/20/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST5-4/20/07	030712361-0004	Firehouse #10 (roof level)	4/20/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST10-4/20/07	030712361-0005	North Side Sidewalk Bridge	4/20/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST11-4/20/07	030712361-0006	90 Trinity Place (roof level)	4/20/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST12-4/20/07	030712361-0007	110 Greenwich Street (roof level)	4/20/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST13-4/20/07	030712361-0008	Marriott Hotel, 38th Floor (roof level)	4/20/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST14-4/20/07	030712361-0009	West Face - South end at corner (scaffolding level)	4/20/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST15-4/20/07	030712361-0010	South Face - East end at corner (scaffolding level)	4/20/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST16-4/20/07	030712361-0011	East Face - North end at corner (scaffolding level)	4/20/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST17-4/20/07	030712361-0012	North Face - West end at corner (scaffolding level)	4/20/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST1-4/21/07	030712362-0001	Southwest Area (sidewalk bridge level)	4/21/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST2-4/21/07	030712362-0002	Southeast Area (sidewalk bridge level)	4/21/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST4-4/21/07	030712362-0003	Northwest Area (street-level)	4/21/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST5-4/21/07	030712362-0004	Firehouse #10 (roof level)	4/21/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST10-4/21/07	030712362-0005	North Side Sidewalk Bridge	4/21/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST11-4/21/07	030712362-0006	90 Trinity Place (roof level)	4/21/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST12-4/21/07	030712362-0007	110 Greenwich Street (roof level)	4/21/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST13-4/21/07	030712362-0008	Marriott Hotel, 38th Floor (roof level)	4/21/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST14-4/21/07	030712362-0009	West Face - South end at corner (scaffolding level)	4/21/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST15-4/21/07	030712362-0010	South Face - East end at corner (scaffolding level)	4/21/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST16-4/21/07	030712362-0011	East Face - North end at corner (scaffolding level)	4/21/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST17-4/21/07	030712362-0012	North Face - West end at corner (scaffolding level)	4/21/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST1-4/22/07	030712363-0001	Southwest Area (sidewalk bridge level)	4/22/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST2-4/22/07	030712363-0002	Southeast Area (sidewalk bridge level)	4/22/07	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST5-4/22/07	030712363-0003	Firehouse #10 (roof level)	4/22/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST10-4/22/07	030712363-0004	North Side Sidewalk Bridge	4/22/07	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST11-4/22/07	030712363-0005	90 Trinity Place (roof level)	4/22/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST12-4/22/07	030712363-0006	110 Greenwich Street (roof level)	4/22/07	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST13-4/22/07	030712363-0007	Marriott Hotel, 38th Floor (roof level)	4/22/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST14-4/22/07	030712363-0008	West Face - South end at corner (scaffolding level)	4/22/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST15-4/22/07	030712363-0009	South Face - East end at corner (scaffolding level)	4/22/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST16-4/22/07	030712363-0010	East Face - North end at corner (scaffolding level)	4/22/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	
ASBESTOS-ST17-4/22/07	030712363-0011	North Face - West end at corner (scaffolding level)	4/22/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/23/07	< 13.00	No	No	

Note:

- Asbestos sample at Station 4 (Northwest Area [street-level]) on April 22, 2007 was not available for analysis on account of timer failure.