

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-2/13/06	06BR0209-01	Southwest Area (sidewalk bridge level)	2/13/06	0.50	Mercury	EPA 324/1631	BRL	2/15/06	< 30.0	No	No	
TotalHg-ST2-2/13/06	06BR0209-02	Southeast Area (sidewalk bridge level)	2/13/06	0.49	Mercury	EPA 324/1631	BRL	2/15/06	< 31.0	No	No	
TotalHg-ST4-2/13/06	06BR0209-03	Northwest Area (street-level)	2/13/06	0.51	Mercury	EPA 324/1631	BRL	2/15/06	< 29.0	No	No	
TotalHg-ST5-2/13/06	06BR0209-04	Firehouse #10 (roof level)	2/13/06	0.57	Mercury	EPA 324/1631	BRL	2/15/06	< 26.0	No	No	
TotalHg-ST10-2/13/06	06BR0209-05	North Side Sidewalk Bridge	2/13/06	0.52	Mercury	EPA 324/1631	BRL	2/15/06	< 29.0	No	No	
TotalHg-ST11-2/13/06	06BR0209-06	90 Trinity Place (roof level)	2/13/06	0.57	Mercury	EPA 324/1631	BRL	2/15/06	< 26.0	No	No	
TotalHg-ST12-2/13/06	06BR0209-07	110 Greenwich Street (roof level)	2/13/06	0.55	Mercury	EPA 324/1631	BRL	2/15/06	< 27.0	No	No	
TotalHg-ST13-2/13/06	06BR0209-08	Marriott Hotel, 38th Floor (roof level)	2/13/06	0.53	Mercury	EPA 324/1631	BRL	2/15/06	< 28.0	No	No	
TotalHg-ST14-2/13/06	06BR0209-09	West Face - South end at corner (scaffolding level)	2/13/06	0.54	Mercury	EPA 324/1631	BRL	2/15/06	< 28.0	No	No	
TotalHg-ST15-2/13/06	06BR0209-10	South Face - East end at corner (scaffolding level)	2/13/06	0.54	Mercury	EPA 324/1631	BRL	2/15/06	< 28.0	No	No	
TotalHg-ST16-2/13/06	06BR0209-11	East Face - North end at corner (scaffolding level)	2/13/06	0.54	Mercury	EPA 324/1631	BRL	2/15/06	< 28.0	No	No	
TotalHg-ST17-2/13/06	06BR0209-12	North Face - West end at corner (scaffolding level)	2/13/06	0.54	Mercury	EPA 324/1631	BRL	2/15/06	< 28.0	No	No	
TotalHg-ST1-2/14/06	06BR0218-01	Southwest Area (sidewalk bridge level)	2/14/06	0.58	Mercury	EPA 324/1631	BRL	2/16/06	< 26.0	No	No	
TotalHg-ST2-2/14/06	06BR0218-02	Southeast Area (sidewalk bridge level)	2/14/06	0.58	Mercury	EPA 324/1631	BRL	2/16/06	< 26.0	No	No	
TotalHg-ST4-2/14/06	06BR0218-03	Northwest Area (street-level)	2/14/06	0.57	Mercury	EPA 324/1631	BRL	2/16/06	< 26.0	No	No	
TotalHg-ST5-2/14/06	06BR0218-04	Firehouse #10 (roof level)	2/14/06	0.57	Mercury	EPA 324/1631	BRL	2/16/06	< 26.0	No	No	
TotalHg-ST10-2/14/06	06BR0218-05	North Side Sidewalk Bridge	2/14/06	0.56	Mercury	EPA 324/1631	BRL	2/16/06	< 27.0	No	No	
TotalHg-ST11-2/14/06	06BR0218-06	90 Trinity Place (roof level)	2/14/06	0.57	Mercury	EPA 324/1631	BRL	2/16/06	< 26.0	No	No	
TotalHg-ST12-2/14/06	06BR0218-07	110 Greenwich Street (roof level)	2/14/06	0.57	Mercury	EPA 324/1631	BRL	2/16/06	< 26.0	No	No	
TotalHg-ST13-2/14/06	06BR0218-08	Marriott Hotel, 38th Floor (roof level)	2/14/06	0.58	Mercury	EPA 324/1631	BRL	2/16/06	< 26.0	No	No	
TotalHg-ST14-2/14/06	06BR0218-09	West Face - South end at corner (scaffolding level)	2/14/06	0.57	Mercury	EPA 324/1631	BRL	2/16/06	< 26.0	No	No	
TotalHg-ST16-2/14/06	06BR0218-10	East Face - North end at corner (scaffolding level)	2/14/06	0.58	Mercury	EPA 324/1631	BRL	2/16/06	< 26.0	No	No	
TotalHg-ST17-2/14/06	06BR0218-11	North Face - West end at corner (scaffolding level)	2/14/06	0.57	Mercury	EPA 324/1631	BRL	2/16/06	< 26.0	No	No	

Notes:

- Mercury sample at Station 15 (South Face - East end at corner [scaffolding level]) on February 14, 2006 was not available for analysis on account of pump failure.