TRC Field Sample No.	Sample No. San	mpling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	d Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	
	get Air Quality Levels						300	Air Quality	Site Specific	Comments		
EPA Site Specific Trigger Levels									3,000	Levels	Trigger Levels]
TotalHg-ST1-7/14/06	06BR1093-01 Southwest Area (side	lewalk bridge level)	7/14/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST2-7/14/06	06BR1093-02 Southeast Area (side	ewalk bridge level)	7/14/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST4-7/14/06	06BR1093-03 Northwest Area (stre	eet-level)	7/14/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST5-7/14/06	06BR1093-04 Firehouse #10 (roof I	level)	7/14/06	0.54	Mercury	EPA 324/1631	BRL	7/18/06	< 28.0	No	No	
TotalHg-ST6-7/14/06	06BR1094-01 Southwest Area (roo	of level)	7/14/06	0.59	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
TotalHg-ST7-7/14/06	06BR1094-02 Southeast Area (roof	f level)	7/14/06	0.59	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
TotalHg-ST8-7/14/06	06BR1094-03 Northeast Area (roof	f level)	7/14/06	0.59	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
	06BR1094-04 Northwest Area (roof		7/14/06	0.59	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
TotalHg-ST10-7/14/06	06BR1093-05 North Side Sidewalk	Bridge	7/14/06	0.55	Mercury	EPA 324/1631	BRL	7/18/06	< 27.0	No	No	
TotalHg-ST11-7/14/06	06BR1093-06 90 Trinity Place (roof	f level)	7/14/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST12-7/14/06	06BR1093-07 110 Greenwich Stree	et (roof level)	7/14/06	0.59	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
TotalHg-ST13-7/14/06	06BR1093-08 Marriott Hotel, 38th F	Floor (roof level)	7/14/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST14-7/14/06	06BR1093-09 West Face - South e	end at corner (scaffolding level)	7/14/06	0.55	Mercury	EPA 324/1631	BRL	7/18/06	< 27.0	No	No	
TotalHg-ST15-7/14/06	06BR1093-10 South Face - East er	nd at corner (scaffolding level)	7/14/06	0.56	Mercury	EPA 324/1631	BRL	7/18/06	< 27.0	No	No	
TotalHg-ST16-7/14/06	06BR1093-11 East Face - North en	nd at corner (scaffolding level)	7/14/06	0.56	Mercury	EPA 324/1631	BRL	7/18/06	< 27.0	No	No	
TotalHg-ST17-7/14/06	06BR1093-12 North Face - West er	nd at corner (scaffolding level)	7/14/06	0.55	Mercury	EPA 324/1631	BRL	7/18/06	< 27.0	No	No	
TotalHg-ST1-7/15/06	06BR1095-01 Southwest Area (side	lewalk bridge level)	7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST2-7/15/06	06BR1095-02 Southeast Area (side	ewalk bridge level)	7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST4-7/15/06	06BR1095-03 Northwest Area (stre	eet-level)	7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST5-7/15/06	06BR1095-04 Firehouse #10 (roof I	level)	7/15/06	0.59	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
TotalHg-ST6-7/15/06	06BR1096-01 Southwest Area (roo	of level)	7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST7-7/15/06	06BR1096-02 Southeast Area (roof	f level)	7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST9-7/15/06	06BR1096-04 Northwest Area (roof	f level)	7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST10-7/15/06	06BR1095-05 North Side Sidewalk	Bridge	7/15/06	0.56	Mercury	EPA 324/1631	BRL	7/18/06	< 27.0	No	No	
TotalHg-ST11-7/15/06	06BR1095-06 90 Trinity Place (roof	f level)	7/15/06	0.58	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST12-7/15/06	06BR1095-07 110 Greenwich Stree	et (roof level)	7/15/06	0.56	Mercury	EPA 324/1631	BRL	7/18/06	< 27.0	No	No	
TotalHg-ST13-7/15/06	06BR1095-08 Marriott Hotel, 38th F	Floor (roof level)	7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST14-7/15/06	06BR1095-09 West Face - South e	end at corner (scaffolding level)	7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST15-7/15/06	06BR1095-10 South Face - East er	nd at corner (scaffolding level)	7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
	06BR1095-11 East Face - North en		7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
	06BR1095-12 North Face - West er		7/15/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST1-7/16/06	06BR1097-01 Southwest Area (side	lewalk bridge level)	7/16/06	0.59	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
TotalHg-ST2-7/16/06	06BR1097-02 Southeast Area (side	ewalk bridge level)	7/16/06	0.59	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
	06BR1097-03 Northwest Area (stre		7/16/06	0.59	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
TotalHg-ST5-7/16/06	06BR1097-04 Firehouse #10 (roof I	,	7/16/06	0.58	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
TotalHg-ST6-7/16/06	06BR1098-01 Southwest Area (roo	,	7/16/06	0.56	Mercury	EPA 324/1631	BRL	7/18/06	< 27.0	No	No	
	06BR1098-03 Northeast Area (roof	,	7/16/06	0.56	Mercury	EPA 324/1631	BRL	7/18/06	< 27.0	No	No	
TotalHg-ST11-7/16/06	06BR1097-06 90 Trinity Place (roof	,	7/16/06	0.57	Mercury	EPA 324/1631	BRL	7/18/06	< 26.0	No	No	
	06BR1097-08 Marriott Hotel, 38th F	,	7/16/06	0.59	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
	06BR1097-10 South Face - East er		7/16/06	0.60	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	
	06BR1097-11 East Face - North en	`	7/16/06	0.60	Mercury	EPA 324/1631	BRL	7/18/06	< 25.0	No	No	

- Mercury result at Station 8 (Northeast Area [roof level]) on July 15, 2006 was not available as the sample was accidentally damaged during preparation in the laboratory.
 Mercury sample at Station 7 (Southeast Area [roof level]) on July 16, 2006 was not available for analysis as the sample was broken in transit to the laboratory.
 Mercury results at Station 9 (Northwest Area [roof level]), Station 10 (North Side Sidewalk Bridge), Station 12 (110 Greenwich Street [roof level]), Station 14 (West Face South end at corner [scaffolding level]), and Station 17 (North Face West end at corner [scaffolding level]) on July 16, 2006 were not available as the samples were accidentally damaged during preparation in the laboratory.

lentally damaged during preparation in the laboratory