

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-10/18/06	06BR1699-01	Southwest Area (sidewalk bridge level)	10/18/06	0.58	Mercury	EPA 324/1631	BRL	10/20/06	< 26.0	No	No	
TotalHg-ST2-10/18/06	06BR1699-02	Southeast Area (sidewalk bridge level)	10/18/06	0.58	Mercury	EPA 324/1631	BRL	10/20/06	< 26.0	No	No	
TotalHg-ST4-10/18/06	06BR1699-03	Northwest Area (street-level)	10/18/06	0.60	Mercury	EPA 324/1631	BRL	10/20/06	< 25.0	No	No	
TotalHg-ST5-10/18/06	06BR1699-04	Firehouse #10 (roof level)	10/18/06	0.60	Mercury	EPA 324/1631	BRL	10/20/06	< 25.0	No	No	
TotalHg-ST10-10/18/06	06BR1699-05	North Side Sidewalk Bridge	10/18/06	0.58	Mercury	EPA 324/1631	BRL	10/20/06	< 26.0	No	No	
TotalHg-ST11-10/18/06	06BR1699-06	90 Trinity Place (roof level)	10/18/06	0.54	Mercury	EPA 324/1631	BRL	10/20/06	< 28.0	No	No	
TotalHg-ST12-10/18/06	06BR1699-07	110 Greenwich Street (roof level)	10/18/06	0.57	Mercury	EPA 324/1631	BRL	10/20/06	< 26.0	No	No	
TotalHg-ST13-10/18/06	06BR1699-08	Marriott Hotel, 38th Floor (roof level)	10/18/06	0.58	Mercury	EPA 324/1631	BRL	10/20/06	< 26.0	No	No	
TotalHg-ST14-10/18/06	06BR1699-09	West Face - South end at corner (scaffolding level)	10/18/06	0.57	Mercury	EPA 324/1631	BRL	10/20/06	< 26.0	No	No	
TotalHg-ST15-10/18/06	06BR1699-10	South Face - East end at corner (scaffolding level)	10/18/06	0.59	Mercury	EPA 324/1631	BRL	10/20/06	< 25.0	No	No	
TotalHg-ST16-10/18/06	06BR1699-11	East Face - North end at corner (scaffolding level)	10/18/06	0.58	Mercury	EPA 324/1631	BRL	10/20/06	< 26.0	No	No	
TotalHg-ST17-10/18/06	06BR1699-12	North Face - West end at corner (scaffolding level)	10/18/06	0.59	Mercury	EPA 324/1631	BRL	10/20/06	< 25.0	No	No	
TotalHg-ST1-10/19/06	06BR1702-01	Southwest Area (sidewalk bridge level)	10/19/06	0.57	Mercury	EPA 324/1631	BRL	10/21/06	< 26.0	No	No	
TotalHg-ST2-10/19/06	06BR1702-02	Southeast Area (sidewalk bridge level)	10/19/06	0.56	Mercury	EPA 324/1631	BRL	10/21/06	< 27.0	No	No	
TotalHg-ST4-10/19/06	06BR1702-03	Northwest Area (street-level)	10/19/06	0.61	Mercury	EPA 324/1631	BRL	10/21/06	< 25.0	No	No	
TotalHg-ST10-10/19/06	06BR1702-04	North Side Sidewalk Bridge	10/19/06	0.58	Mercury	EPA 324/1631	BRL	10/21/06	< 26.0	No	No	
TotalHg-ST11-10/19/06	06BR1702-05	90 Trinity Place (roof level)	10/19/06	0.60	Mercury	EPA 324/1631	BRL	10/21/06	< 25.0	No	No	
TotalHg-ST12-10/19/06	06BR1702-06	110 Greenwich Street (roof level)	10/19/06	0.59	Mercury	EPA 324/1631	BRL	10/21/06	< 25.0	No	No	
TotalHg-ST13-10/19/06	06BR1702-07	Marriott Hotel, 38th Floor (roof level)	10/19/06	0.57	Mercury	EPA 324/1631	BRL	10/21/06	< 26.0	No	No	
TotalHg-ST14-10/19/06	06BR1702-08	West Face - South end at corner (scaffolding level)	10/19/06	0.54	Mercury	EPA 324/1631	BRL	10/21/06	< 28.0	No	No	
TotalHg-ST15-10/19/06	06BR1702-09	South Face - East end at corner (scaffolding level)	10/19/06	0.53	Mercury	EPA 324/1631	BRL	10/21/06	< 28.0	No	No	
TotalHg-ST16-10/19/06	06BR1702-10	East Face - North end at corner (scaffolding level)	10/19/06	0.57	Mercury	EPA 324/1631	BRL	10/21/06	< 26.0	No	No	
TotalHg-ST17-10/19/06	06BR1702-11	North Face - West end at corner (scaffolding level)	10/19/06	0.53	Mercury	EPA 324/1631	BRL	10/21/06	< 28.0	No	No	

Note:

- Mercury sample at Station 5 (Firehouse #10 [roof level]) on October 19, 2006 was not available for analysis on account of pump failure.