

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments	
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000				
									14,000	5,000	200	400	600	100,000	5,000	500	28,000	160,000	Air Quality	Site Specific	Comments	
									Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels
METALS-ST11-1/19/08	G8A230173001	Southwest Area (sidewalk bridge level)	1/19/08	1734.9	Metals	6020	STL-SAC	1/23/08	2.9	< 69.2	< 0.69	< 0.69	< 6.9	79.9	9.0	11.3	5.8	46.8	No	No		
METALS-ST2-1/19/08	G8A230173002	Southeast Area (sidewalk bridge level)	1/19/08	1737.2	Metals	6020	STL-SAC	1/23/08	3.1	< 69.1	< 0.69	< 0.69	< 6.9	48.3	10.7	22.1	7.0	117	No	No		
METALS-ST4-1/19/08	G8A230173003	Northwest Area (street-level)	1/19/08	1725.4	Metals	6020	STL-SAC	1/23/08	2.5	< 69.5	< 0.70	< 0.70	< 7.0	36.8	10.2	17.1	6.1	60.7	No	No		
METALS-ST5-1/19/08	G8A230173004	Firehouse #10 (roof level)	1/19/08	1731.4	Metals	6020	STL-SAC	1/23/08	2.6	< 69.3	< 0.69	< 0.69	< 6.9	87.4	12.9	47.6	8.6	160	No	No		
METALS-ST10-1/19/08	G8A230173005	North Side Sidewalk Bridge	1/19/08	1731.9	Metals	6020	STL-SAC	1/23/08	2.2	< 69.3	< 0.69	< 0.69	< 6.9	56.8	8.1	48.6	6.8	128	No	No		
METALS-ST11-1/19/08	G8A230173006	90 Trinity Place (roof level)	1/19/08	1725.6	Metals	6020	STL-SAC	1/23/08	2.6	< 69.5	< 0.70	< 0.70	< 7.0	447	21.2	9.8	5.8	46.6	No	No		
METALS-ST12-1/19/08	G8A230173007	110 Greenwich Street (roof level)	1/19/08	1750.5	Metals	6020	STL-SAC	1/23/08	2.7	< 68.6	< 0.68	< 0.68	< 6.8	75.7	18.3	9.1	5.4	50.3	No	No		
METALS-ST13-1/19/08	G8A230173008	Mariotti Hotel, 38th Floor (roof level)	1/19/08	1721.9	Metals	6020	STL-SAC	1/23/08	1.9	< 69.7	< 0.70	< 0.70	< 7.0	72.7	6.2	6.9	5.5	28.6	No	No		
METALS-ST14-1/19/08	G8A230173009	West Face - South end at corner (scaffolding level)	1/19/08	1742.2	Metals	6020	STL-SAC	1/23/08	2.2	< 68.9	< 0.69	< 0.69	< 6.9	270	9.4	6.1	40.6	No	No			
METALS-ST15-1/19/08	G8A230173010	South Face - East end at corner (scaffolding level)	1/19/08	1756.7	Metals	6020	STL-SAC	1/23/08	2.2	< 68.3	< 0.68	< 0.68	< 6.8	56.5	7.3	7.9	5.6	30.5	No	No		
METALS-ST16-1/19/08	G8A230173011	East Face - North end at corner (scaffolding level)	1/19/08	1719.4	Metals	6020	STL-SAC	1/23/08	2.2	< 69.8	< 0.70	< 0.70	< 7.0	173	13.0	21.4	5.9	70.4	No	No		
METALS-ST17-1/19/08	G8A230173012	North Face - West end at corner (scaffolding level)	1/19/08	1727.6	Metals	6020	STL-SAC	1/23/08	2.0	< 69.5	< 0.69	< 0.69	< 6.9	94.4	7.4	22.5	5.8	60.1	No	No		
METALS-ST1-1/20/08	G8A230170001	Southwest Area (sidewalk bridge level)	1/20/08	1745.3	Metals	6020	STL-SAC	1/23/08	2.3	< 68.8	< 0.69	< 0.69	< 6.9	39.4	7.6	10.8	9.2	46.8	No	No		
METALS-ST2-1/20/08	G8A230170002	Southeast Area (sidewalk bridge level)	1/20/08	1739	Metals	6020	STL-SAC	1/23/08	2.3	< 69.0	< 0.69	< 0.69	< 6.9	36.5	7.1	10.2	8.9	43.8	No	No		
METALS-ST4-1/20/08	G8A230170003	Northwest Area (street-level)	1/20/08	1697.5	Metals	6020	STL-SAC	1/23/08	2.2	< 70.7	< 0.71	< 0.71	< 7.1	55.0	23.4	9.0	77.8	No	No			
METALS-ST5-1/20/08	G8A230170004	Firehouse #10 (roof level)	1/20/08	1760	Metals	6020	STL-SAC	1/23/08	2.4	< 68.2	< 0.68	< 0.68	< 6.8	43.8	6.6	25.2	9.6	55.2	No	No		
METALS-ST10-1/20/08	G8A230170005	North Side Sidewalk Bridge	1/20/08	1731.6	Metals	6020	STL-SAC	1/23/08	1.7	< 69.3	< 0.69	< 0.69	< 6.9	155	11.2	33.5	8.4	101	No	No		
METALS-ST11-1/20/08	G8A230170006	90 Trinity Place (roof level)	1/20/08	1742.7	Metals	6020	STL-SAC	1/23/08	2.1	< 68.8	< 0.69	< 0.69	< 6.9	492	6.7	8.9	9.4	40.9	No	No		
METALS-ST12-1/20/08	G8A230170007	110 Greenwich Street (roof level)	1/20/08	1786.6	Metals	6020	STL-SAC	1/23/08	2.5	< 67.2	< 0.67	< 0.67	< 6.7	80.5	7.5	9.7	10.8	34.8	No	No		
METALS-ST13-1/20/08	G8A230170008	Mariotti Hotel, 38th Floor (roof level)	1/20/08	1743.3	Metals	6020	STL-SAC	1/23/08	2.0	< 68.8	< 0.69	< 0.69	< 6.9	69.7	5.2	8.8	26.1	No	No			
METALS-ST14-1/20/08	G8A230170009	West Face - South end at corner (scaffolding level)	1/20/08	1855.7	Metals	6020	STL-SAC	1/23/08	2.4	< 64.7	< 0.65	< 0.65	< 6.5	61.2	11.1	10.5	9.8	37.1	No	No		
METALS-ST15-1/20/08	G8A230170010	South Face - East end at corner (scaffolding level)	1/20/08	1862.6	Metals	6020	STL-SAC	1/23/08	3.1	< 64.4	< 0.64	< 0.64	< 6.4	196	10.6	12.3	12.9	51.8	No	No		
METALS-ST16-1/20/08	G8A230170011	East Face - North end at corner (scaffolding level)	1/20/08	1851.3	Metals	6020	STL-SAC	1/23/08	2.5	< 64.8	< 0.65	< 0.65	< 6.5	57.5	9.5	15.2	10.4	51.8	No	No		
METALS-ST17-1/20/08	G8A230170012	North Face - West end at corner (scaffolding level)	1/20/08	1853.3	Metals	6020	STL-SAC	1/23/08	1.6	< 64.7	< 0.65	< 0.65	< 6.5	88.5	7.2	16.2	7.3	58.6	No	No		