

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m3)	Barium Concentration (ng/m3)	Beryllium Concentration (ng/m3)	Cadmium Concentration (ng/m3)	Chromium (Total) Concentration (ng/m3)	Copper Concentration (ng/m3)	Lead Concentration (ng/m3)	Manganese Concentration (ng/m3)	Nickel Concentration (ng/m3)	Zinc Concentration (ng/m3)	Exceeds Target Air Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST1-7/5/06	G6G070167001	Southwest Area (sidewalk bridge level)	7/5/06	1763	Metals	6020	STL-SAC	7/7/06	3.3	< 67.3	< 0.67	< 0.67	< 6.7	153	14.1	17.3	8.8	109	No	No	
METALS-ST4-7/5/06	G6G070167003	Northwest Area (street-level)	7/5/06	1707.3	Metals	6020	STL-SAC	7/7/06	3.4	< 70.3	< 0.70	< 0.70	< 7.0	205	15.9	13.8	7.5	84.2	No	No	
METALS-ST5-7/5/06	G6G070167004	Firehouse #10 (roof level)	7/5/06	1749.6	Metals	6020	STL-SAC	7/7/06	2.8	< 68.6	< 0.68	< 0.68	< 6.8	146	8.3	16.3	7.9	48.0	No	No	
METALS-ST10-7/5/06	G6G070167005	North Side Sidewalk Bridge	7/5/06	1766.1	Metals	6020	STL-SAC	7/7/06	3.2	< 67.9	< 0.68	< 0.68	< 6.8	72.6	14.4	36.8	16.8	259	No	No	
METALS-ST100-7/5/06	G6G070167013	Station 10 Field Duplicate	7/5/06	1817.5	Metals	6020	STL-SAC	7/7/06	2.5	< 66.0	< 0.66	< 0.66	< 6.6	135	32.9	26.3	9.2	260	No	No	
METALS-ST11-7/5/06	G6G070167006	90 Trinity Place (roof level)	7/5/06	1774.7	Metals	6020	STL-SAC	7/7/06	2.6	< 67.6	< 0.68	< 0.68	< 6.8	85.6	8.5	11.7	6.5	42.2	No	No	
METALS-ST12-7/5/06	G6G070167007	110 Greenwich Street (roof level)	7/5/06	1751.3	Metals	6020	STL-SAC	7/7/06	2.4	< 68.5	< 0.68	< 0.68	< 6.8	48.1	8.2	11.7	6.0	38.2	No	No	
METALS-ST13-7/5/06	G6G070167008	Marront Hotel, 38th Floor (roof level)	7/5/06	1853.7	Metals	6020	STL-SAC	7/7/06	2.6	< 64.7	< 0.65	< 0.65	< 6.5	78.8	7.3	9.5	7.8	36.0	No	No	
METALS-ST14-7/5/06	G6G070167009	West Face - South end at corner (scaffolding level)	7/5/06	1745.9	Metals	6020	STL-SAC	7/7/06	2.6	< 68.9	< 0.69	< 0.69	< 6.9	129	7.4	9.9	9.4	36.1	No	No	
METALS-ST15-7/5/06	G6G070167010	South Face - East end at corner (scaffolding level)	7/5/06	1796.3	Metals	6020	STL-SAC	7/7/06	2.7	< 66.8	< 0.67	< 0.67	< 6.7	290	7.5	11.3	9.6	49.2	No	No	
METALS-ST16-7/5/06	G6G070167011	East Face - North end at corner (scaffolding level)	7/5/06	1773.5	Metals	6020	STL-SAC	7/7/06	2.8	< 67.7	< 0.68	< 0.68	< 6.8	228	8.1	12.6	9.4	39.9	No	No	
METALS-ST17-7/5/06	G6G070167012	North Face - West end at corner (scaffolding level)	7/5/06	1776.5	Metals	6020	STL-SAC	7/7/06	2.7	< 67.5	< 0.68	< 0.68	< 6.8	220	7.1	12.6	9.3	35.1	No	No	
METALS-ST1-7/6/06	G6G080194001	Southwest Area (sidewalk bridge level)	7/6/06	1685.8	Metals	6020	STL-SAC	7/8/06	2.2	< 71.2	< 0.71	< 0.71	< 7.1	58.1	59.7	19.4	4.6	40.7	No	No	
METALS-ST2-7/6/06	G6G080194002	Southeast Area (sidewalk bridge level)	7/6/06	1677	Metals	6020	STL-SAC	7/8/06	3.5	< 69.8	< 0.72	< 0.72	< 7.2	107	15.2	58.7	6.6	64.8	No	No	
METALS-ST4-7/6/06	G6G080194003	Northwest Area (street-level)	7/6/06	1666.9	Metals	6020	STL-SAC	7/8/06	2.2	< 67.2	< 0.72	< 0.72	< 7.2	47.2	13.2	15.7	3.7	34.3	No	No	
METALS-ST5-7/6/06	G6G080194004	Firehouse #10 (roof level)	7/6/06	1768	Metals	6020	STL-SAC	7/8/06	2.1	< 67.9	< 0.68	< 0.68	< 6.8	86.2	6.4	12.7	4.0	28.7	No	No	
METALS-ST6-7/6/06	G6G080193001	Southwest Area (roof level)	7/6/06	1853.9	Metals	6020	STL-SAC	7/8/06	1.4	< 64.7	< 0.65	< 0.65	< 6.5	39.4	6.2	7.4	3.2	16.4	No	No	
METALS-ST7-7/6/06	G6G080193002	Southeast Area (roof level)	7/6/06	1798.4	Metals	6020	STL-SAC	7/8/06	1.6	< 66.7	< 0.67	< 0.67	< 6.7	21.9	5.2	8.2	3.6	19.8	No	No	
METALS-ST8-7/6/06	G6G080193003	Northeast Area (roof level)	7/6/06	1737.3	Metals	6020	STL-SAC	7/8/06	1.5	< 69.1	< 0.69	< 0.69	< 6.9	37.2	12.8	7.9	< 3.4	28.7	No	No	
METALS-ST9-7/6/06	G6G080193004	Northwest Area (roof level)	7/6/06	1786.2	Metals	6020	STL-SAC	7/8/06	1.5	< 67.2	< 0.67	< 0.67	< 6.7	19.6	4.2	7.6	< 3.4	19.1	No	No	
METALS-ST10-7/6/06	G6G080194005	North Side Sidewalk Bridge	7/6/06	1709.9	Metals	6020	STL-SAC	7/8/06	2.0	< 70.2	< 0.70	< 0.70	< 7.0	28.0	7.6	14.3	3.9	31.6	No	No	
METALS-ST11-7/6/06	G6G080194006	90 Trinity Place (roof level)	7/6/06	1738.2	Metals	6020	STL-SAC	7/8/06	1.8	< 69.0	< 0.69	< 0.69	< 6.9	46.7	5.4	10.4	4.4	21.6	No	No	
METALS-ST12-7/6/06	G6G080194007	110 Greenwich Street (roof level)	7/6/06	1772.8	Metals	6020	STL-SAC	7/8/06	1.9	< 67.7	< 0.68	< 0.68	< 6.8	40.5	5.0	11.3	4.3	20.9	No	No	
METALS-ST13-7/6/06	G6G080194008	Marront Hotel, 38th Floor (roof level)	7/6/06	1687.8	Metals	6020	STL-SAC	7/8/06	1.8	< 71.1	< 0.71	< 0.71	< 7.1	56.6	3.8	9.1	< 3.6	17.6	No	No	
METALS-ST14-7/6/06	G6G080194009	West Face - South end at corner (scaffolding level)	7/6/06	1701.5	Metals	6020	STL-SAC	7/8/06	1.5	< 70.5	< 0.70	< 0.70	< 7.0	47.9	4.0	9.1	< 3.5	16.8	No	No	
METALS-ST15-7/6/06	G6G080194010	South Face - East end at corner (scaffolding level)	7/6/06	1699.5	Metals	6020	STL-SAC	7/8/06	1.8	< 70.6	< 0.71	< 0.71	< 7.1	441	5.6	14.0	< 3.5	22.8	No	No	
METALS-ST16-7/6/06	G6G080194011	East Face - North end at corner (scaffolding level)	7/6/06	1701.4	Metals	6020	STL-SAC	7/8/06	1.5	< 70.5	< 0.70	< 0.70	< 7.0	209	5.2	9.4	< 3.5	22.7	No	No	
METALS-ST17-7/6/06	G6G080194012	North Face - West end at corner (scaffolding level)	7/6/06	1732.4	Metals	6020	STL-SAC	7/8/06	1.5	< 69.3	< 0.69	< 0.69	< 6.9	39.7	3.8	8.4	< 3.5	19.2	No	No	

Notes:
1. Metals sample at Station 2 (Southeast Area [sidewalk bridge level]) on July 5, 2006 was not available for analysis on account of pump failure.