

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Air Quality	Site Specific	Comments
METALS-ST11-10/13/08	GBJ150170001	Southwest Area (sidewalk bridge level)	10/13/08	1704.6	Metals	6020	STL-SAC	10/15/08	5.2	< 70.4	< 0.70	< 0.70	< 7.0	339	32.5	39.1	7.2	396	No	No	
METALS-ST2-10/13/08	GBJ150170002	Southwest Area (sidewalk bridge level)	10/13/08	1737.5	Metals	6020	STL-SAC	10/15/08	5.1	77.7	< 0.69	< 0.69	8.6	150	24.6	45.4	7.3	268	No	No	
METALS-ST4-10/13/08	GBJ150170003	Northwest Area (street-level)	10/13/08	1746.5	Metals	6020	STL-SAC	10/15/08	4.7	< 68.7	< 0.69	< 0.69	< 6.9	188	30.8	36.1	6.9	308	No	No	
METALS-ST5-10/13/08	GBJ150170004	Firehouse #10 (roof level)	10/13/08	1755	Metals	6020	STL-SAC	10/15/08	5.0	< 68.4	< 0.68	< 0.68	< 6.8	87.6	22.6	46.7	7.7	205	No	No	
METALS-ST10-10/13/08	GBJ150170005	North Side Sidewalk Bridge	10/13/08	1732.4	Metals	6020	STL-SAC	10/15/08	4.8	< 68.3	< 0.69	< 0.69	< 6.9	47.9	17.2	44.6	7.0	232	No	No	
METALS-ST11-10/13/08	GBJ150170006	90 Trinity Place (roof level)	10/13/08	1751.8	Metals	6020	STL-SAC	10/15/08	3.9	< 68.5	< 0.68	< 0.68	< 6.8	112	26.6	19.8	5.6	89.3	No	No	
METALS-ST12-10/13/08	GBJ150170007	110 Greenwich Street (roof level)	10/13/08	1783.2	Metals	6020	STL-SAC	10/15/08	4.2	< 67.3	< 0.67	< 0.67	< 6.7	45.1	37.0	23.4	5.9	99.2	No	No	
METALS-ST13-10/13/08	GBJ150170008	Marrion Hotel, 38th Floor (roof level)	10/13/08	1750.6	Metals	6020	STL-SAC	10/15/08	3.6	< 68.5	< 0.68	< 0.68	< 6.8	120	13.9	15.1	4.8	62.0	No	No	
METALS-ST14-10/13/08	GBJ150170009	West Face - South end at corner (scaffolding level)	10/13/08	1762.2	Metals	6020	STL-SAC	10/15/08	4.0	< 68.1	< 0.68	< 0.68	< 6.8	168	21.3	109	3.9	109	No	No	
METALS-ST15-10/13/08	GBJ150170010	South Face - East end at corner (scaffolding level)	10/13/08	1778.8	Metals	6020	STL-SAC	10/15/08	3.8	< 67.5	< 0.67	< 0.67	< 6.7	227	13.6	27.0	4.3	95.2	No	No	
METALS-ST16-10/13/08	GBJ150170011	East Face - North end at corner (scaffolding level)	10/13/08	1769.6	Metals	6020	STL-SAC	10/15/08	3.3	< 67.8	< 0.68	< 0.68	< 6.8	215	10.9	24.4	4.2	92.2	No	No	
METALS-ST17-10/13/08	GBJ150170012	North Face - West end at corner (scaffolding level)	10/13/08	1771.3	Metals	6020	STL-SAC	10/15/08	3.4	< 67.7	< 0.68	< 0.68	< 6.8	153	11.1	28.3	4.1	131	No	No	
METALS-ST1-10/14/08	GBJ160154001	Southwest Area (sidewalk bridge level)	10/14/08	1729.1	Metals	6020	STL-SAC	10/16/08	3.3	< 69.4	< 0.69	< 0.69	< 6.9	230	19.7	28.5	8.4	112	No	No	
METALS-ST2-10/14/08	GBJ160154002	Southwest Area (sidewalk bridge level)	10/14/08	1753.7	Metals	6020	STL-SAC	10/16/08	4.3	79.5	< 0.68	< 0.68	< 6.8	170	27.2	61.9	11.1	221	No	No	
METALS-ST4-10/14/08	GBJ160154003	Northwest Area (street-level)	10/14/08	1728.4	Metals	6020	STL-SAC	10/16/08	3.4	< 69.4	< 0.69	< 0.69	< 6.9	155	45.9	33.7	7.9	346	No	No	
METALS-ST5-10/14/08	GBJ160154004	Firehouse #10 (roof level)	10/14/08	1759	Metals	6020	STL-SAC	10/16/08	3.3	< 68.2	< 0.68	< 0.68	7.5	130	18.2	54.0	9.6	140	No	No	
METALS-ST10-10/14/08	GBJ160154005	North Side Sidewalk Bridge	10/14/08	1739.5	Metals	6020	STL-SAC	10/16/08	3.2	< 69.0	< 0.69	< 0.69	7.6	57.6	17.1	59.6	9.0	256	No	No	
METALS-ST11-10/14/08	GBJ160154006	90 Trinity Place (roof level)	10/14/08	1757.7	Metals	6020	STL-SAC	10/16/08	2.6	< 68.3	< 0.68	< 0.68	< 6.8	167	17.2	20.4	7.0	70.1	No	No	
METALS-ST12-10/14/08	GBJ160154007	110 Greenwich Street (roof level)	10/14/08	1778.9	Metals	6020	STL-SAC	10/16/08	2.5	< 67.4	< 0.67	< 0.67	< 6.7	123	30.6	26.0	11.6	87.0	No	No	
METALS-ST13-10/14/08	GBJ160154008	Marrion Hotel, 38th Floor (roof level)	10/14/08	1769.2	Metals	6020	STL-SAC	10/16/08	2.1	< 67.8	< 0.68	< 0.68	< 6.8	151	10.0	11.2	5.8	53.8	No	No	
METALS-ST14-10/14/08	GBJ160154009	West Face - South end at corner (scaffolding level)	10/14/08	1777.9	Metals	6020	STL-SAC	10/16/08	2.1	< 67.5	< 0.67	< 0.67	7.6	138	11.6	19.8	5.6	57.2	No	No	
METALS-ST15-10/14/08	GBJ160154010	South Face - East end at corner (scaffolding level)	10/14/08	1768.3	Metals	6020	STL-SAC	10/16/08	2.3	< 67.9	< 0.68	< 0.68	< 6.8	141	12.2	32.7	6.3	80.8	No	No	
METALS-ST16-10/14/08	GBJ160154011	East Face - North end at corner (scaffolding level)	10/14/08	1736.1	Metals	6020	STL-SAC	10/16/08	2.4	< 69.1	< 0.69	< 0.69	< 6.9	233	11.9	23.0	6.3	67.8	No	No	
METALS-ST17-10/14/08	GBJ160154012	North Face - West end at corner (scaffolding level)	10/14/08	1761.1	Metals	6020	STL-SAC	10/16/08	2.5	< 68.1	< 0.68	< 0.68	< 6.8	278	11.0	29.9	6.4	96.5	No	No	