

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm <sup>3</sup> )	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-1/30/08	030802596-0001	Southwest Area (sidewalk bridge level)	1/30/08	1	2.850	Asbestos	PCME	EMSL	1/31/08	< 0.00087	No	No	
ASBESTOS-ST2-1/30/08	030802596-0002	Southeast Area (sidewalk bridge level)	1/30/08	1	2.900	Asbestos	PCME	EMSL	1/31/08	< 0.00085	No	No	
ASBESTOS-ST4-1/30/08	030802596-0003	Northwest Area (street-level)	1/30/08	1	2.990	Asbestos	PCME	EMSL	1/31/08	< 0.00083	No	No	
ASBESTOS-ST5-1/30/08	030802596-0004	Firehouse #10 (roof level)	1/30/08	1	3.020	Asbestos	PCME	EMSL	1/31/08	< 0.00082	No	No	
ASBESTOS-ST10-1/30/08	030802596-0005	North Side Sidewalk Bridge	1/30/08	1	2.940	Asbestos	PCME	EMSL	1/31/08	< 0.00084	No	No	
ASBESTOS-ST100-1/30/08	030802596-0013	Station 10 Field Duplicate	1/30/08	1	2.710	Asbestos	PCME	EMSL	1/31/08	< 0.00084	No	No	Note 1
ASBESTOS-ST11-1/30/08	030802596-0006	90 Trinity Place (roof level)	1/30/08	1	3.040	Asbestos	PCME	EMSL	1/31/08	< 0.00081	No	No	
ASBESTOS-ST12-1/30/08	030802596-0007	110 Greenwich Street (roof level)	1/30/08	1	3.010	Asbestos	PCME	EMSL	1/31/08	< 0.00082	No	No	
ASBESTOS-ST13-1/30/08	030802596-0008	Marriott Hotel, 38th Floor (roof level)	1/30/08	1	2.970	Asbestos	PCME	EMSL	1/31/08	< 0.00083	No	No	
ASBESTOS-ST14-1/30/08	030802596-0009	West Face - South end at corner (scaffolding level)	1/30/08	1	3.010	Asbestos	PCME	EMSL	1/31/08	< 0.00082	No	No	
ASBESTOS-ST15-1/30/08	030802596-0010	South Face - East end at corner (scaffolding level)	1/30/08	1	3.180	Asbestos	PCME	EMSL	1/31/08	< 0.00078	No	No	
ASBESTOS-ST16-1/30/08	030802596-0011	East Face - North end at corner (scaffolding level)	1/30/08	1	2.990	Asbestos	PCME	EMSL	1/31/08	< 0.00083	No	No	
ASBESTOS-ST17-1/30/08	030802596-0012	North Face - West end at corner (scaffolding level)	1/30/08	1	2.990	Asbestos	PCME	EMSL	1/31/08	< 0.00083	No	No	
ASBESTOS-ST1-1/31/08	030802729-0001	Southwest Area (sidewalk bridge level)	1/31/08	1	2.830	Asbestos	PCME	EMSL	2/1/08	< 0.00087	No	No	
ASBESTOS-ST2-1/31/08	030802729-0002	Southeast Area (sidewalk bridge level)	1/31/08	1	3.020	Asbestos	PCME	EMSL	2/1/08	< 0.00082	No	No	
ASBESTOS-ST4-1/31/08	030802729-0003	Northwest Area (street-level)	1/31/08	1	2.890	Asbestos	PCME	EMSL	2/1/08	< 0.00085	No	No	
ASBESTOS-ST5-1/31/08	030802729-0004	Firehouse #10 (roof level)	1/31/08	1	2.970	Asbestos	PCME	EMSL	2/1/08	< 0.00083	No	No	
ASBESTOS-ST10-1/31/08	030802729-0005	North Side Sidewalk Bridge	1/31/08	1	3.090	Asbestos	PCME	EMSL	2/1/08	< 0.00080	No	No	
ASBESTOS-ST11-1/31/08	030802729-0006	90 Trinity Place (roof level)	1/31/08	1	3.010	Asbestos	PCME	EMSL	2/1/08	< 0.00082	No	No	
ASBESTOS-ST12-1/31/08	030802729-0007	110 Greenwich Street (roof level)	1/31/08	1	3.000	Asbestos	PCME	EMSL	2/1/08	< 0.00082	No	No	
ASBESTOS-ST13-1/31/08	030802729-0008	Marriott Hotel, 38th Floor (roof level)	1/31/08	1	3.020	Asbestos	PCME	EMSL	2/1/08	< 0.00082	No	No	
ASBESTOS-ST15-1/31/08	030802729-0009	South Face - East end at corner (scaffolding level)	1/31/08	1	2.990	Asbestos	PCME	EMSL	2/1/08	< 0.00083	No	No	
ASBESTOS-ST16-1/31/08	030802729-0010	East Face - North end at corner (scaffolding level)	1/31/08	1	3.000	Asbestos	PCME	EMSL	2/1/08	< 0.00082	No	No	
ASBESTOS-ST17-1/31/08	030802729-0011	North Face - West end at corner (scaffolding level)	1/31/08	1	3.060	Asbestos	PCME	EMSL	2/1/08	< 0.00081	No	No	
ASBESTOS-ST1-2/1/08	030802823-0001	Southwest Area (sidewalk bridge level)	2/1/08	1	3.090	Asbestos	PCME	EMSL	2/2/08	< 0.00080	No	No	
ASBESTOS-ST2-2/1/08	030802823-0002	Southeast Area (sidewalk bridge level)	2/1/08	1	2.970	Asbestos	PCME	EMSL	2/2/08	< 0.00083	No	No	
ASBESTOS-ST4-2/1/08	030802823-0003	Northwest Area (street-level)	2/1/08	1	3.060	Asbestos	PCME	EMSL	2/2/08	< 0.00081	No	No	
ASBESTOS-ST5-2/1/08	030802823-0004	Firehouse #10 (roof level)	2/1/08	1	3.170	Asbestos	PCME	EMSL	2/2/08	< 0.00078	No	No	
ASBESTOS-ST10-2/1/08	030802823-0005	North Side Sidewalk Bridge	2/1/08	1	2.940	Asbestos	PCME	EMSL	2/2/08	< 0.00084	No	No	
ASBESTOS-ST11-2/1/08	030802823-0006	90 Trinity Place (roof level)	2/1/08	1	3.010	Asbestos	PCME	EMSL	2/2/08	< 0.00082	No	No	
ASBESTOS-ST12-2/1/08	030802823-0007	110 Greenwich Street (roof level)	2/1/08	1	3.000	Asbestos	PCME	EMSL	2/2/08	< 0.00082	No	No	
ASBESTOS-ST13-2/1/08	030802823-0008	Marriott Hotel, 38th Floor (roof level)	2/1/08	1	3.000	Asbestos	PCME	EMSL	2/2/08	< 0.00082	No	No	
ASBESTOS-ST14-2/1/08	030802996-0001	West Face - South end at corner (scaffolding level)	2/1/08	1	2.850	Asbestos	PCME	EMSL	2/4/08	< 0.00087	No	No	Note 3
ASBESTOS-ST15-2/1/08	030802996-0002	South Face - East end at corner (scaffolding level)	2/1/08	1	2.820	Asbestos	PCME	EMSL	2/4/08	< 0.00088	No	No	Note 3
ASBESTOS-ST16-2/1/08	030802996-0003	East Face - North end at corner (scaffolding level)	2/1/08	1	2.840	Asbestos	PCME	EMSL	2/4/08	< 0.00087	No	No	Note 3
ASBESTOS-ST17-2/1/08	030802996-0004	North Face - West end at corner (scaffolding level)	2/1/08	1	2.870	Asbestos	PCME	EMSL	2/4/08	< 0.00086	No	No	Note 3
ASBESTOS-ST1-2/2/08	030802998-0001	Southwest Area (sidewalk bridge level)	2/2/08	1	3.090	Asbestos	PCME	EMSL	2/4/08	< 0.00080	No	No	
ASBESTOS-ST2-2/2/08	030802998-0002	Southeast Area (sidewalk bridge level)	2/2/08	1	3.030	Asbestos	PCME	EMSL	2/4/08	< 0.00081	No	No	
ASBESTOS-ST4-2/2/08	030802998-0003	Northwest Area (street-level)	2/2/08	1	3.000	Asbestos	PCME	EMSL	2/4/08	< 0.00082	No	No	
ASBESTOS-ST5-2/2/08	030802998-0004	Firehouse #10 (roof level)	2/2/08	1	3.060	Asbestos	PCME	EMSL	2/4/08	< 0.00081	No	No	
ASBESTOS-ST10-2/2/08	030802998-0005	North Side Sidewalk Bridge	2/2/08	1	3.090	Asbestos	PCME	EMSL	2/4/08	< 0.00080	No	No	
ASBESTOS-ST11-2/2/08	030802998-0006	90 Trinity Place (roof level)	2/2/08	1	3.090	Asbestos	PCME	EMSL	2/4/08	< 0.00080	No	No	
ASBESTOS-ST12-2/2/08	030802998-0007	110 Greenwich Street (roof level)	2/2/08	1	3.020	Asbestos	PCME	EMSL	2/4/08	< 0.00082	No	No	
ASBESTOS-ST13-2/2/08	030802998-0008	Marriott Hotel, 38th Floor (roof level)	2/2/08	1	3.040	Asbestos	PCME	EMSL	2/4/08	< 0.00081	No	No	
ASBESTOS-ST14-2/2/08	030802998-0009	West Face - South end at corner (scaffolding level)	2/2/08	1	2.700	Asbestos	PCME	EMSL	2/4/08	< 0.00084	No	No	Note 3
ASBESTOS-ST15-2/2/08	030802998-0010	South Face - East end at corner (scaffolding level)	2/2/08	1	2.700	Asbestos	PCME	EMSL	2/4/08	< 0.00084	No	No	Note 3
ASBESTOS-ST16-2/2/08	030802998-0011	East Face - North end at corner (scaffolding level)	2/2/08	1	2.770	Asbestos	PCME	EMSL	2/4/08	< 0.00082	No	No	Note 3
ASBESTOS-ST17-2/2/08	030802998-0012	North Face - West end at corner (scaffolding level)	2/2/08	1	2.770	Asbestos	PCME	EMSL	2/4/08	< 0.00082	No	No	Note 3
ASBESTOS-ST1-2/3/08	030802997-0001	Southwest Area (sidewalk bridge level)	2/3/08	1	3.380	Asbestos	PCME	EMSL	2/4/08	< 0.00080	No	No	Note 4
ASBESTOS-ST2-2/3/08	030802997-0002	Southeast Area (sidewalk bridge level)	2/3/08	1	3.140	Asbestos	PCME	EMSL	2/4/08	< 0.00086	No	No	
ASBESTOS-ST4-2/3/08	030802997-0003	Northwest Area (street-level)	2/3/08	1	3.260	Asbestos	PCME	EMSL	2/4/08	< 0.00083	No	No	
ASBESTOS-ST5-2/3/08	030802997-0004	Firehouse #10 (roof level)	2/3/08	1	3.010	Asbestos	PCME	EMSL	2/4/08	< 0.00082	No	No	
ASBESTOS-ST10-2/3/08	030802997-0005	North Side Sidewalk Bridge	2/3/08	1	3.110	Asbestos	PCME	EMSL	2/4/08	< 0.00087	No	No	
ASBESTOS-ST11-2/3/08	030802997-0006	90 Trinity Place (roof level)	2/3/08	1	3.110	Asbestos	PCME	EMSL	2/4/08	< 0.00087	No	No	
ASBESTOS-ST12-2/3/08	030802997-0007	110 Greenwich Street (roof level)	2/3/08	1	3.000	Asbestos	PCME	EMSL	2/4/08	< 0.00082	No	No	
ASBESTOS-ST13-2/3/08	030802997-0008	Marriott Hotel, 38th Floor (roof level)	2/3/08	1	2.870	Asbestos	PCME	EMSL	2/4/08	< 0.00086	No	No	
ASBESTOS-ST14-2/3/08	030802997-0009	West Face - South end at corner (scaffolding level)	2/3/08	1	2.460	Asbestos	PCME	EMSL	2/4/08	< 0.00086	No	No	Note 3
ASBESTOS-ST15-2/3/08	030802997-0010	South Face - East end at corner (scaffolding level)	2/3/08	1	2.450	Asbestos	PCME	EMSL	2/4/08	< 0.00086	No	No	Note 3
ASBESTOS-ST16-2/3/08	030802997-0011	East Face - North end at corner (scaffolding level)	2/3/08	1	2.440	Asbestos	PCME	EMSL	2/4/08	< 0.00087	No	No	Note 3
ASBESTOS-ST17-2/3/08	030802997-0012	North Face - West end at corner (scaffolding level)	2/3/08	1	2.460	Asbestos	PCME	EMSL	2/4/08	< 0.00086	No	No	Note 3

Note:

1. Due to an RPD exceedance (23.3%) at Station 100 (Station 10 Field Duplicate) on January 30, 2008, the sample volume and subsequent sample result are estimated.
2. Asbestos sample at Station 14 (West Face - South end at corner [scaffolding level]) on January 31, 2008 was not available for analysis on account of power failure.
3. Asbestos sample at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on February 1, 2, and 3, 2008 were collected for a reduced time period (approximately 19-20 hours) on account of power failure.
4. Due to an RPD exceedance (21.2%) at Station 1 (Southwest Area [sidewalk bridge level]) on February 3, 2008, the sample volume and subsequent sample result are estimated.