

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-4/06/07	030710862-0001	Southwest Area (sidewalk bridge level)	4/6/07	1	3.020	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST2-4/06/07	030710862-0002	Southeast Area (sidewalk bridge level)	4/6/07	1	3.040	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST4-4/06/07	030710862-0003	Northwest Area (street-level)	4/6/07	1	3.020	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST5-4/06/07	030710862-0004	Firehouse #10 (roof level)	4/6/07	1	3.020	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST10-4/06/07	030710862-0005	North Side Sidewalk Bridge	4/6/07	1	3.030	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST11-4/06/07	030710862-0006	90 Trinity Place (roof level)	4/6/07	1	3.020	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST12-4/06/07	030710862-0007	110 Greenwich Street (roof level)	4/6/07	1	3.040	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST13-4/06/07	030710862-0008	Marriott Hotel, 38th Floor (roof level)	4/6/07	1	3.030	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST14-4/06/07	030710862-0009	West Face - South end at corner (scaffolding level)	4/6/07	1	3.040	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST15-4/06/07	030710862-0010	South Face - East end at corner (scaffolding level)	4/6/07	1	3.020	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST16-4/06/07	030710862-0011	East Face - North end at corner (scaffolding level)	4/6/07	1	3.040	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST17-4/06/07	030710862-0012	North Face - West end at corner (scaffolding level)	4/6/07	1	3.030	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST1-4/07/07	030710842-0001	Southwest Area (sidewalk bridge level)	4/7/07	1	3.010	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST2-4/07/07	030710842-0002	Southeast Area (sidewalk bridge level)	4/7/07	1	3.040	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST4-4/07/07	030710842-0003	Northwest Area (street-level)	4/7/07	1	2.980	Asbestos	PCME	EMSL	4/9/07	< 0.00083	No	No	
ASBESTOS-ST5-4/07/07	030710842-0004	Firehouse #10 (roof level)	4/7/07	1	3.020	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST10-4/07/07	030710842-0005	North Side Sidewalk Bridge	4/7/07	1	2.980	Asbestos	PCME	EMSL	4/9/07	< 0.00083	No	No	
ASBESTOS-ST11-4/07/07	030710842-0006	90 Trinity Place (roof level)	4/7/07	1	3.020	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST12-4/07/07	030710842-0007	110 Greenwich Street (roof level)	4/7/07	1	3.040	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST13-4/07/07	030710842-0008	Marriott Hotel, 38th Floor (roof level)	4/7/07	1	3.020	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST14-4/07/07	030710842-0009	West Face - South end at corner (scaffolding level)	4/7/07	1	3.030	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST15-4/07/07	030710842-0010	South Face - East end at corner (scaffolding level)	4/7/07	1	3.010	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST16-4/07/07	030710842-0011	East Face - North end at corner (scaffolding level)	4/7/07	1	3.040	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST17-4/07/07	030710842-0012	North Face - West end at corner (scaffolding level)	4/7/07	1	3.020	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST1-4/08/07	030710841-0001	Southwest Area (sidewalk bridge level)	4/8/07	1	3.060	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST2-4/08/07	030710841-0002	Southeast Area (sidewalk bridge level)	4/8/07	1	3.050	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST4-4/08/07	030710841-0003	Northwest Area (street-level)	4/8/07	1	2.660	Asbestos	PCME	EMSL	4/9/07	< 0.00086	No	No	Note 2
ASBESTOS-ST5-4/08/07	030710841-0004	Firehouse #10 (roof level)	4/8/07	1	2.850	Asbestos	PCME	EMSL	4/9/07	< 0.00087	No	No	
ASBESTOS-ST10-4/08/07	030710841-0005	North Side Sidewalk Bridge	4/8/07	1	3.170	Asbestos	PCME	EMSL	4/9/07	< 0.00078	No	No	
ASBESTOS-ST11-4/08/07	030710841-0006	90 Trinity Place (roof level)	4/8/07	1	3.020	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST12-4/08/07	030710841-0007	110 Greenwich Street (roof level)	4/8/07	1	3.010	Asbestos	PCME	EMSL	4/9/07	< 0.00076	No	No	
ASBESTOS-ST13-4/08/07	030710841-0008	Marriott Hotel, 38th Floor (roof level)	4/8/07	1	3.110	Asbestos	PCME	EMSL	4/9/07	< 0.00079	No	No	
ASBESTOS-ST14-4/08/07	030710841-0009	West Face - South end at corner (scaffolding level)	4/8/07	1	3.060	Asbestos	PCME	EMSL	4/9/07	< 0.00081	No	No	
ASBESTOS-ST15-4/08/07	030710841-0010	South Face - East end at corner (scaffolding level)	4/8/07	1	3.010	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	
ASBESTOS-ST16-4/08/07	030710841-0011	East Face - North end at corner (scaffolding level)	4/8/07	1	3.010	Asbestos	PCME	EMSL	4/9/07	< 0.00082	No	No	

Note:

1. Asbestos sample at Station 17 (North Face - West end at corner [scaffolding level]) on April 8, 2007 was not available for analysis on account of pump failure.
2. Due to flow rate RPD exceedance (27.5%) for asbestos at Station 4 (Northwest Area [street-level]) on April 8, 2007, the sample volume and subsequent sample result are estimated.