

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Exceeds EPA	
										NA	Levels	Site Specific	Trigger Levels
<b>Target Air Quality Levels</b>													
<b>EPA Site Specific Trigger Levels</b>													
ASBESTOS-ST1-4/17/07	030711788-0001	Southwest Area (sidewalk bridge level)	4/17/07	1	3.020	Asbestos	PCME	EMSL	4/18/07	< 0.00082	No	No	
ASBESTOS-ST2-4/17/07	030711788-0002	Southeast Area (sidewalk bridge level)	4/17/07	1	3.060	Asbestos	PCME	EMSL	4/18/07	< 0.00081	No	No	
ASBESTOS-ST4-4/17/07	030711788-0003	Northwest Area (street-level)	4/17/07	1	3.020	Asbestos	PCME	EMSL	4/18/07	< 0.00082	No	No	
ASBESTOS-ST5-4/17/07	030711788-0004	Firehouse #10 (roof level)	4/17/07	1	3.040	Asbestos	PCME	EMSL	4/18/07	< 0.00081	No	No	
ASBESTOS-ST11-4/17/07	030711788-0005	90 Trinity Place (roof level)	4/17/07	1	3.090	Asbestos	PCME	EMSL	4/18/07	< 0.00080	No	No	
ASBESTOS-ST12-4/17/07	030711788-0006	110 Greenwich Street (roof level)	4/17/07	1	3.110	Asbestos	PCME	EMSL	4/18/07	< 0.00079	No	No	
ASBESTOS-ST13-4/17/07	030711788-0007	Marriott Hotel, 38th Floor (roof level)	4/17/07	1	3.010	Asbestos	PCME	EMSL	4/18/07	< 0.00082	No	No	
ASBESTOS-ST14-4/17/07	030711788-0008	West Face - South end at corner (scaffolding level)	4/17/07	1	3.060	Asbestos	PCME	EMSL	4/18/07	< 0.00081	No	No	
ASBESTOS-ST15-4/17/07	030711788-0009	South Face - East end at corner (scaffolding level)	4/17/07	1	3.020	Asbestos	PCME	EMSL	4/18/07	< 0.00082	No	No	
ASBESTOS-ST16-4/17/07	030711788-0010	East Face - North end at corner (scaffolding level)	4/17/07	1	3.010	Asbestos	PCME	EMSL	4/18/07	< 0.00082	No	No	
ASBESTOS-ST17-4/17/07	030711788-0011	North Face - West end at corner (scaffolding level)	4/17/07	1	3.010	Asbestos	PCME	EMSL	4/18/07	< 0.00082	No	No	

Note:

- Asbestos sample at Station 10 (North Side Sidewalk Bridge) on April 17, 2007 was not available for analysis due to a timer malfunction.