

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-10/5/06	030632771-0001	Southwest Area (sidewalk bridge level)	10/5/06	1	3.020	Asbestos	PCME	EMSL	10/6/06	< 0.00082	No	No	
ASBESTOS-ST2-10/5/06	030632771-0002	Southeast Area (sidewalk bridge level)	10/5/06	1	3.020	Asbestos	PCME	EMSL	10/6/06	< 0.00082	No	No	
ASBESTOS-ST4-10/5/06	030632771-0003	Northwest Area (street-level)	10/5/06	1	2.960	Asbestos	PCME	EMSL	10/6/06	< 0.00083	No	No	
ASBESTOS-ST5-10/5/06	030632771-0004	Firehouse #10 (roof level)	10/5/06	1	3.020	Asbestos	PCME	EMSL	10/6/06	< 0.00082	No	No	
ASBESTOS-ST10-10/5/06	030632771-0005	North Side Sidewalk Bridge	10/5/06	1	2.960	Asbestos	PCME	EMSL	10/6/06	< 0.00083	No	No	
ASBESTOS-ST100-10/5/06	030632771-0013	Station 10 Field Duplicate	10/5/06	1	3.150	Asbestos	PCME	EMSL	10/6/06	< 0.00078	No	No	
ASBESTOS-ST11-10/5/06	030632771-0006	90 Trinity Place (roof level)	10/5/06	1	3.020	Asbestos	PCME	EMSL	10/6/06	< 0.00082	No	No	
ASBESTOS-ST12-10/5/06	030632771-0007	110 Greenwich Street (roof level)	10/5/06	1	3.020	Asbestos	PCME	EMSL	10/6/06	< 0.00082	No	No	
ASBESTOS-ST13-10/5/06	030632771-0008	Marriott Hotel, 38th Floor (roof level)	10/5/06	1	3.020	Asbestos	PCME	EMSL	10/6/06	< 0.00082	No	No	
ASBESTOS-ST14-10/5/06	030632771-0009	West Face - South end at corner (scaffolding level)	10/5/06	1	3.020	Asbestos	PCME	EMSL	10/6/06	< 0.00082	No	No	
ASBESTOS-ST15-10/5/06	030632771-0010	South Face - East end at corner (scaffolding level)	10/5/06	1	3.020	Asbestos	PCME	EMSL	10/6/06	< 0.00082	No	No	
ASBESTOS-ST16-10/5/06	030632771-0011	East Face - North end at corner (scaffolding level)	10/5/06	1	2.770	Asbestos	PCME	EMSL	10/6/06	< 0.00089	No	No	
ASBESTOS-ST17-10/5/06	030632771-0012	North Face - West end at corner (scaffolding level)	10/5/06	1	3.020	Asbestos	PCME	EMSL	10/6/06	< 0.00082	No	No	
ASBESTOS-ST1-10/6/06	030633085-0001	Southwest Area (sidewalk bridge level)	10/6/06	1	2.960	Asbestos	PCME	EMSL	10/9/06	< 0.00083	No	No	
ASBESTOS-ST2-10/6/06	030633085-0002	Southeast Area (sidewalk bridge level)	10/6/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST4-10/6/06	030633085-0003	Northwest Area (street-level)	10/6/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST5-10/6/06	030633085-0004	Firehouse #10 (roof level)	10/6/06	1	3.060	Asbestos	PCME	EMSL	10/9/06	< 0.00081	No	No	
ASBESTOS-ST10-10/6/06	030633085-0005	North Side Sidewalk Bridge	10/6/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST11-10/6/06	030633085-0006	90 Trinity Place (roof level)	10/6/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST12-10/6/06	030633085-0007	110 Greenwich Street (roof level)	10/6/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST13-10/6/06	030633085-0008	Marriott Hotel, 38th Floor (roof level)	10/6/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST14-10/6/06	030633085-0009	West Face - South end at corner (scaffolding level)	10/6/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST15-10/6/06	030633085-0010	South Face - East end at corner (scaffolding level)	10/6/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST16-10/6/06	030633085-0011	East Face - North end at corner (scaffolding level)	10/6/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST17-10/6/06	030633085-0012	North Face - West end at corner (scaffolding level)	10/6/06	1	2.960	Asbestos	PCME	EMSL	10/9/06	< 0.00083	No	No	
ASBESTOS-ST1-10/7/06	030633080-0001	Southwest Area (sidewalk bridge level)	10/7/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST2-10/7/06	030633080-0002	Southeast Area (sidewalk bridge level)	10/7/06	1	3.090	Asbestos	PCME	EMSL	10/9/06	< 0.00080	No	No	
ASBESTOS-ST4-10/7/06	030633080-0003	Northwest Area (street-level)	10/7/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST5-10/7/06	030633080-0004	Firehouse #10 (roof level)	10/7/06	1	3.060	Asbestos	PCME	EMSL	10/9/06	< 0.00081	No	No	
ASBESTOS-ST10-10/7/06	030633080-0005	North Side Sidewalk Bridge	10/7/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST11-10/7/06	030633080-0006	90 Trinity Place (roof level)	10/7/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST12-10/7/06	030633080-0007	110 Greenwich Street (roof level)	10/7/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST13-10/7/06	030633080-0008	Marriott Hotel, 38th Floor (roof level)	10/7/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST14-10/7/06	030633080-0009	West Face - South end at corner (scaffolding level)	10/7/06	1	3.090	Asbestos	PCME	EMSL	10/9/06	< 0.00080	No	No	
ASBESTOS-ST15-10/7/06	030633080-0010	South Face - East end at corner (scaffolding level)	10/7/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST16-10/7/06	030633080-0011	East Face - North end at corner (scaffolding level)	10/7/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST17-10/7/06	030633080-0012	North Face - West end at corner (scaffolding level)	10/7/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST1-10/8/06	030633090-0001	Southwest Area (sidewalk bridge level)	10/8/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST2-10/8/06	030633090-0002	Southeast Area (sidewalk bridge level)	10/8/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST4-10/8/06	030633090-0003	Northwest Area (street-level)	10/8/06	1	2.960	Asbestos	PCME	EMSL	10/9/06	< 0.00083	No	No	
ASBESTOS-ST5-10/8/06	030633090-0004	Firehouse #10 (roof level)	10/8/06	1	2.960	Asbestos	PCME	EMSL	10/9/06	< 0.00083	No	No	
ASBESTOS-ST10-10/8/06	030633090-0005	North Side Sidewalk Bridge	10/8/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST11-10/8/06	030633090-0006	90 Trinity Place (roof level)	10/8/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST12-10/8/06	030633090-0007	110 Greenwich Street (roof level)	10/8/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST13-10/8/06	030633090-0008	Marriott Hotel, 38th Floor (roof level)	10/8/06	1	2.580	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	Note 1
ASBESTOS-ST14-10/8/06	030633090-0009	West Face - South end at corner (scaffolding level)	10/8/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST15-10/8/06	030633090-0010	South Face - East end at corner (scaffolding level)	10/8/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST16-10/8/06	030633090-0011	East Face - North end at corner (scaffolding level)	10/8/06	1	3.010	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	
ASBESTOS-ST17-10/8/06	030633090-0012	North Face - West end at corner (scaffolding level)	10/8/06	1	3.020	Asbestos	PCME	EMSL	10/9/06	< 0.00082	No	No	

Note:

1. Due to a flow rate RPD exceedance (34.2%) for asbestos at Station 13 (Marriott Hotel, 38th Floor [roof level]) on October 8, 2006, the sample volume and subsequent sample result are estimated.