

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality	Exceeds EPA	
										NA	Levels	Site Specific	
											Levels	Trigger Levels	
ASBESTOS-ST1-10/21/05	030531695-0001	Southwest Area (street-level)	10/21/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST2-10/21/05	030531695-0002	Southeast Area (sidewalk bridge level)	10/21/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST4-10/21/05	030531695-0003	Northwest Area (street-level)	10/21/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST5-10/21/05	030531695-0004	Firehouse #10 (roof level)	10/21/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST10-10/21/05	030531695-0005	North Side Sidewalk Bridge	10/21/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST11-10/21/05	030531695-0006	90 Trinity Place (roof level)	10/21/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST12-10/21/05	030531695-0007	110 Greenwich Street (roof level)	10/21/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST13-10/21/05	030531695-0008	Marriott Hotel, 38th Floor (roof level)	10/21/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST1-10/22/05	030531694-0001	Southwest Area (street-level)	10/22/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST2-10/22/05	030531694-0002	Southeast Area (sidewalk bridge level)	10/22/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST4-10/22/05	030531694-0003	Northwest Area (street-level)	10/22/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST5-10/22/05	030531694-0004	Firehouse #10 (roof level)	10/22/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST10-10/22/05	030531694-0005	North Side Sidewalk Bridge	10/22/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST11-10/22/05	030531694-0006	90 Trinity Place (roof level)	10/22/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST12-10/22/05	030531694-0007	110 Greenwich Street (roof level)	10/22/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST13-10/22/05	030531694-0008	Marriott Hotel, 38th Floor (roof level)	10/22/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST1-10/23/05	030531697-0001	Southwest Area (street-level)	10/23/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST2-10/23/05	030531697-0002	Southeast Area (sidewalk bridge level)	10/23/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST4-10/23/05	030531697-0003	Northwest Area (street-level)	10/23/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST5-10/23/05	030531697-0004	Firehouse #10 (roof level)	10/23/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST10-10/23/05	030531697-0005	North Side Sidewalk Bridge	10/23/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST11-10/23/05	030531697-0006	90 Trinity Place (roof level)	10/23/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST12-10/23/05	030531697-0007	110 Greenwich Street (roof level)	10/23/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST13-10/23/05	030531697-0008	Marriott Hotel, 38th Floor (roof level)	10/23/2005	1	3.000	Asbestos	PCME	EMSL	10/24/2005	< 0.00082	No	No	
ASBESTOS-ST1-10/24/05	030531845-0001	Southwest Area (street-level)	10/24/2005	1	2.970	Asbestos	PCME	EMSL	10/25/2005	< 0.00083	No	No	Filter from
ASBESTOS-ST2-10/24/05	030531845-0002	Southeast Area (sidewalk bridge level)	10/24/2005	1	2.970	Asbestos	PCME	EMSL	10/25/2005	< 0.00083	No	No	Station 13
ASBESTOS-ST4-10/24/05	030531845-0003	Northwest Area (street-level)	10/24/2005	1	2.970	Asbestos	PCME	EMSL	10/25/2005	< 0.00083	No	No	(Marriott Hotel,
ASBESTOS-ST5-10/24/05	030531845-0004	Firehouse #10 (roof level)	10/24/2005	1	2.970	Asbestos	PCME	EMSL	10/25/2005	< 0.00083	No	No	38th Floor (roof
ASBESTOS-ST10-10/24/05	030531845-0005	North Side Sidewalk Bridge	10/24/2005	1	2.970	Asbestos	PCME	EMSL	10/25/2005	< 0.00083	No	No	level))was
ASBESTOS-ST100-10/24/05	030531845-0009	Station 10 Field Duplicate	10/24/2005	1	2.970	Asbestos	PCME	EMSL	10/25/2005	< 0.00083	No	No	damaged and
ASBESTOS-ST11-10/24/05	030531845-0006	90 Trinity Place (roof level)	10/24/2005	1	2.970	Asbestos	PCME	EMSL	10/25/2005	< 0.00083	No	No	could not be
ASBESTOS-ST12-10/24/05	030531845-0007	110 Greenwich Street (roof level)	10/24/2005	1	2.970	Asbestos	PCME	EMSL	10/25/2005	< 0.00083	No	No	analyzed.
ASBESTOS-ST1-10/25/05	030531949-0001	Southwest Area (street-level)	10/25/2005	1	2.970	Asbestos	PCME	EMSL	10/26/2005	< 0.00083	No	No	
ASBESTOS-ST2-10/25/05	030531949-0002	Southeast Area (sidewalk bridge level)	10/25/2005	1	2.970	Asbestos	PCME	EMSL	10/26/2005	< 0.00083	No	No	
ASBESTOS-ST4-10/25/05	030531949-0003	Northwest Area (street-level)	10/25/2005	1	2.970	Asbestos	PCME	EMSL	10/26/2005	< 0.00083	No	No	
ASBESTOS-ST5-10/25/05	030531949-0004	Firehouse #10 (roof level)	10/25/2005	1	2.970	Asbestos	PCME	EMSL	10/26/2005	< 0.00083	No	No	
ASBESTOS-ST10-10/25/05	030531949-0005	North Side Sidewalk Bridge	10/25/2005	1	2.970	Asbestos	PCME	EMSL	10/26/2005	< 0.00083	No	No	
ASBESTOS-ST11-10/25/05	030531949-0006	90 Trinity Place (roof level)	10/25/2005	1	2.970	Asbestos	PCME	EMSL	10/26/2005	< 0.00083	No	No	
ASBESTOS-ST12-10/25/05	030531949-0007	110 Greenwich Street (roof level)	10/25/2005	1	2.970	Asbestos	PCME	EMSL	10/26/2005	< 0.00083	No	No	
ASBESTOS-ST13-10/25/05	030531949-0008	Marriott Hotel, 38th Floor (roof level)	10/25/2005	1	2.970	Asbestos	PCME	EMSL	10/26/2005	< 0.00083	No	No	