TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-12/30/05	030600092-0001	Southwest Area (sidewalk bridge level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST2-12/30/05	030600092-0002	Southeast Area (sidewalk bridge level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST4-12/30/05	030600092-0003	Northwest Area (street-level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST5-12/30/05	030600092-0004	Firehouse #10 (roof level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST10-12/30/05	030600092-0005	North Side Sidewalk Bridge	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST11-12/30/05	030600092-0006	90 Trinity Place (roof level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST12-12/30/05	030600092-0007	110 Greenwich Street (roof level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST13-12/30/05	030600092-0008	Marriott Hotel, 38th Floor (roof level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST14-12/30/05	030600092-0009	West Face - South end at corner (scaffolding level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST15-12/30/05	030600092-0010	South Face - East end at corner (scaffolding level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST16-12/30/05	030600092-0011	East Face - North end at corner (scaffolding level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST17-12/30/05	030600092-0012	North Face - West end at corner (scaffolding level)	12/30/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST1-12/31/05	030600093-0001	Southwest Area (sidewalk bridge level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST2-12/31/05	030600093-0002	Southeast Area (sidewalk bridge level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST4-12/31/05	030600093-0003	Northwest Area (street-level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST5-12/31/05	030600093-0004	Firehouse #10 (roof level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST10-12/31/05	030600093-0005	North Side Sidewalk Bridge	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST11-12/31/05	030600093-0006	90 Trinity Place (roof level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST12-12/31/05	030600093-0007	110 Greenwich Street (roof level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST13-12/31/05	030600093-0008	Marriott Hotel, 38th Floor (roof level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST14-12/31/05	030600093-0009	West Face - South end at corner (scaffolding level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST15-12/31/05	030600093-0010	South Face - East end at corner (scaffolding level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST16-12/31/05	030600093-0011	East Face - North end at corner (scaffolding level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST17-12/31/05	030600093-0012	North Face - West end at corner (scaffolding level)	12/31/05	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST1-1/1/06	030600095-0001	Southwest Area (sidewalk bridge level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST2-1/1/06	030600095-0002	Southeast Area (sidewalk bridge level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST4-1/1/06	030600095-0003	Northwest Area (street-level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST5-1/1/06	030600095-0004	Firehouse #10 (roof level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST10-1/1/06	030600095-0005	North Side Sidewalk Bridge	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST11-1/1/06	030600095-0006	90 Trinity Place (roof level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST12-1/1/06	030600095-0007	110 Greenwich Street (roof level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST13-1/1/06	030600095-0008	Marriott Hotel, 38th Floor (roof level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST14-1/1/06	030600095-0009	West Face - South end at corner (scaffolding level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST15-1/1/06	030600095-0010	South Face - East end at corner (scaffolding level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST16-1/1/06	030600095-0011	East Face - North end at corner (scaffolding level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST17-1/1/06	030600095-0012	North Face - West end at corner (scaffolding level)	1/1/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST1-1/2/06	030600096-0001	Southwest Area (sidewalk bridge level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST2-1/2/06	030600096-0002	Southeast Area (sidewalk bridge level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST4-1/2/06	030600096-0003	Northwest Area (street-level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST5-1/2/06	030600096-0004	Firehouse #10 (roof level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST10-1/2/06	030600096-0005	North Side Sidewalk Bridge	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST11-1/2/06	030600096-0006	90 Trinity Place (roof level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST12-1/2/06	030600096-0007	110 Greenwich Street (roof level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST13-1/2/06	030600096-0008	Marriott Hotel, 38th Floor (roof level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST14-1/2/06	030600096-0009	West Face - South end at corner (scaffolding level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST15-1/2/06	030600096-0010	South Face - East end at corner (scaffolding level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST16-1/2/06	030600096-0011	East Face - North end at corner (scaffolding level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST17-1/2/06	030600096-0012	North Face - West end at corner (scaffolding level)	1/2/06	1	2.970	Asbestos	PCME	EMSL	1/3/06	< 0.00083	No	No	
ASBESTOS-ST1-1/3/06	030600169-0001	Southwest Area (sidewalk bridge level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST2-1/3/06	030600169-0002	Southeast Area (sidewalk bridge level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST4-1/3/06	030600169-0003	Northwest Area (street-level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST5-1/3/06	030600169-0004	Firehouse #10 (roof level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST10- 1/3/06	030600169-0005	North Side Sidewalk Bridge	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST11-1/3/06	030600169-0006	90 Trinity Place (roof level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST12-1/3/06	030600169-0007	110 Greenwich Street (roof level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST13-1/3/06	030600169-0008	Marriott Hotel, 38th Floor (roof level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST14-1/3/06	030600169-0009	West Face - South end at corner (scaffolding level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST15-1/3/06	030600169-0010	South Face - East end at corner (scaffolding level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST16-1/3/06	030600169-0011	East Face - North end at corner (scaffolding level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST17-1/3/06	030600169-0012	North Face - West end at corner (scaffolding level)	1/3/06	1	2.970	Asbestos	PCME	EMSL	1/4/06	< 0.00083	No	No	
ASBESTOS-ST1-1/4/06	030600298-0001	Southwest Area (sidewalk bridge level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST2-1/4/06	030600298-0002	Southeast Area (sidewalk bridge level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST4-1/4/06	030600298-0003	Northwest Area (street-level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST5-1/4/06	030600298-0004	Firehouse #10 (roof level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST10-1/4/06	030600298-0005	North Side Sidewalk Bridge	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST11-1/4/06	030600298-0006	90 Trinity Place (roof level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST12-1/4/06	030600298-0007	110 Greenwich Street (roof level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST13-1/4/06	030600298-0008	Marriott Hotel, 38th Floor (roof level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST14-1/4/06	030600298-0009	West Face - South end at corner (scaffolding level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST15-1/4/06	030600298-0010	South Face - East end at corner (scaffolding level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST16-1/4/06	030600298-0011	East Face - North end at corner (scaffolding level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	
ASBESTOS-ST17-1/4/06	030600298-0012	North Face - West end at corner (scaffolding level)	1/4/06	1	2.970	Asbestos	PCME	EMSL	1/5/06	< 0.00083	No	No	