TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-5/1/08	030813538-0001	Southwest Area (sidewalk bridge level)	5/1/08	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST2-5/1/08	030813538-0002	Southeast Area (sidewalk bridge level)	5/1/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST4-5/1/08	030813538-0003	Northwest Area (street-level)	5/1/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST5-5/1/08	030813538-0004	Firehouse #10 (roof level)	5/1/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST10-5/1/08	030813538-0005	North Side Sidewalk Bridge	5/1/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST11-5/1/08	030813538-0006	90 Trinity Place (roof level)	5/1/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST12-5/1/08	030813538-0007	110 Greenwich Street (roof level)	5/1/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST13-5/1/08	030813538-0008	Marriott Hotel, 38th Floor (roof level)	5/1/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST14-5/1/08	030813538-0009	West Face - South end at corner (scaffolding level)	5/1/08	1	2.310	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 11.00	No	No	
ASBESTOS-ST15-5/1/08	030813538-0010	South Face - East end at corner (scaffolding level)	5/1/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST16-5/1/08	030813538-0011	East Face - North end at corner (scaffolding level)	5/1/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST17-5/1/08	030813538-0012	North Face - West end at corner (scaffolding level)	5/1/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST1-5/2/08	030813478-0001	Southwest Area (sidewalk bridge level)	5/2/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST2-5/2/08	030813478-0002	Southeast Area (sidewalk bridge level)	5/2/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST4-5/2/08	030813478-0003	Northwest Area (street-level)	5/2/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST5-5/2/08	030813478-0004	Firehouse #10 (roof level)	5/2/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST10-5/2/08	030813478-0005	North Side Sidewalk Bridge	5/2/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST100-5/2/08	030813478-0013	Station 10 Field Duplicate	5/2/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST11-5/2/08	030813478-0006	90 Trinity Place (roof level)	5/2/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST12-5/2/08	030813478-0007	110 Greenwich Street (roof level)	5/2/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST13-5/2/08	030813478-0008	Marriott Hotel, 38th Floor (roof level)	5/2/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST14-5/2/08	030813478-0009	West Face - South end at corner (scaffolding level)	5/2/08	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST15-5/2/08	030813478-0010	South Face - East end at corner (scaffolding level)	5/2/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST16-5/2/08	030813478-0011	East Face - North end at corner (scaffolding level)	5/2/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST17-5/2/08	030813478-0012	North Face - West end at corner (scaffolding level)	5/2/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/3/08	< 13.00	No	No	
ASBESTOS-ST1-5/3/08	030813665-0001	Southwest Area (sidewalk bridge level)	5/3/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 15.00	No	No	
ASBESTOS-ST2-5/3/08	030813665-0002	Southeast Area (sidewalk bridge level)	5/3/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST4-5/3/08	030813665-0003	Northwest Area (street-level)	5/3/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 15.00	No	No	
ASBESTOS-ST5-5/3/08	030813665-0004	Firehouse #10 (roof level)	5/3/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST10-5/3/08	030813665-0005	North Side Sidewalk Bridge	5/3/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST11-5/3/08	030813665-0006	90 Trinity Place (roof level)	5/3/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST12-5/3/08	030813665-0007	110 Greenwich Street (roof level)	5/3/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST13-5/3/08	030813665-0008	Marriott Hotel, 38th Floor (roof level)	5/3/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST14-5/3/08	030813665-0009	West Face - South end at corner (scaffolding level)	5/3/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	13.00	No	No	
ASBESTOS-ST15-5/3/08	030813665-0010	South Face - East end at corner (scaffolding level)	5/3/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST16-5/3/08	030813665-0011	East Face - North end at corner (scaffolding level)	5/3/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST17-5/3/08	030813665-0012	North Face - West end at corner (scaffolding level)	5/3/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST1-5/4/08	030813667-0001	Southwest Area (sidewalk bridge level)	5/4/08	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST2-5/4/08	030813667-0002	Southeast Area (sidewalk bridge level)	5/4/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST4-5/4/08	030813667-0003	Northwest Area (street-level)	5/4/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST5-5/4/08	030813667-0004	Firehouse #10 (roof level)	5/4/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST10-5/4/08	030813667-0005	North Side Sidewalk Bridge	5/4/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST11-5/4/08	030813667-0006	90 Trinity Place (roof level)	5/4/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST12-5/4/08	030813667-0007	110 Greenwich Street (roof level)	5/4/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST13-5/4/08	030813667-0008	Marriott Hotel, 38th Floor (roof level)	5/4/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST14-5/4/08	030813667-0009	West Face - South end at corner (scaffolding level)	5/4/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST15-5/4/08	030813667-0010	South Face - East end at corner (scaffolding level)	5/4/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST16-5/4/08	030813667-0011	East Face - North end at corner (scaffolding level)	5/4/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST17-5/4/08	030813667-0012	North Face - West end at corner (scaffolding level)	5/4/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/5/08	< 13.00	No	No	
ASBESTOS-ST1-5/5/08	030813778-0001	Southwest Area (sidewalk bridge level)	5/5/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 13.00	No	No	
ASBESTOS-ST2-5/5/08	030813778-0002	Southeast Area (sidewalk bridge level)	5/5/08	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 15.00	No	No	
ASBESTOS-ST4-5/5/08	030813778-0003	Northwest Area (street-level)	5/5/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 13.00	No	No	
ASBESTOS-ST5-5/5/08	030813778-0004	Firehouse #10 (roof level)	5/5/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 13.00	No	No	
ASBESTOS-ST10-5/5/08	030813778-0005	North Side Sidewalk Bridge	5/5/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 13.00	No	No	
ASBESTOS-ST11-5/5/08	030813778-0006	90 Trinity Place (roof level)	5/5/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 15.00	No	No	
ASBESTOS-ST12-5/5/08	030813778-0007	110 Greenwich Street (roof level)	5/5/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 15.00	No	No	
ASBESTOS-ST13-5/5/08	030813778-0008	Marriott Hotel, 38th Floor (roof level)	5/5/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 13.00	No	No	
ASBESTOS-ST14-5/5/08	030813778-0009	West Face - South end at corner (scaffolding level)	5/5/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 13.00	No	No	
ASBESTOS-ST15-5/5/08	030813778-0010	South Face - East end at corner (scaffolding level)	5/5/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 13.00	No	No	
ASBESTOS-ST16-5/5/08	030813778-0011	East Face - North end at corner (scaffolding level)	5/5/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 13.00	No	No	
ASBESTOS-ST17-5/5/08	030813778-0012	North Face - West end at corner (scaffolding level)	5/5/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/08	< 15.00	No	No	