TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-5/25/07	030717113-0001	Southwest Area (sidewalk bridge level)	5/25/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST2-5/25/07	030717113-0002	Southeast Area (sidewalk bridge level)	5/25/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST4-5/25/07	030717113-0003	Northwest Area (street-level)	5/25/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 15.00	No	No	
ASBESTOS-ST5-5/25/07	030717113-0004	Firehouse #10 (roof level)	5/25/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST10-5/25/07	030717113-0005	North Side Sidewalk Bridge	5/25/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 15.00	No	No	
ASBESTOS-ST11-5/25/07	030717113-0006	90 Trinity Place (roof level)	5/25/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST12-5/25/07	030717113-0007	110 Greenwich Street (roof level)	5/25/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST13-5/25/07	030717113-0008	Marriott Hotel, 38th Floor (roof level)	5/25/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 15.00	No	No	
ASBESTOS-ST14-5/25/07	030717113-0009	West Face - South end at corner (scaffolding level)	5/25/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST15-5/25/07	030717113-0010	South Face - East end at corner (scaffolding level)	5/25/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST16-5/25/07	030717113-0011	East Face - North end at corner (scaffolding level)	5/25/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST17-5/25/07	030717113-0012	North Face - West end at corner (scaffolding level)	5/25/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST1-5/26/07	030717121-0001	Southwest Area (sidewalk bridge level)	5/26/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST2-5/26/07	030717121-0002	Southeast Area (sidewalk bridge level)	5/26/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 15.00	No	No	
ASBESTOS-ST4-5/26/07	030717121-0003	Northwest Area (street-level)	5/26/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 15.00	No	No	
ASBESTOS-ST5-5/26/07	030717121-0004	Firehouse #10 (roof level)	5/26/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST10-5/26/07	030717121-0005	North Side Sidewalk Bridge	5/26/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 15.00	No	No	
ASBESTOS-ST11-5/26/07	030717121-0006	90 Trinity Place (roof level)	5/26/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST12-5/26/07	030717121-0007	110 Greenwich Street (roof level)	5/26/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 15.00	No	No	
ASBESTOS-ST13-5/26/07	030717121-0008	Marriott Hotel, 38th Floor (roof level)	5/26/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST14-5/26/07	030717121-0009	West Face - South end at corner (scaffolding level)	5/26/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST15-5/26/07	030717121-0010	South Face - East end at corner (scaffolding level)	5/26/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST16-5/26/07	030717121-0011	East Face - North end at corner (scaffolding level)	5/26/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 15.00	No	No	
ASBESTOS-ST17-5/26/07	030717121-0012	North Face - West end at corner (scaffolding level)	5/26/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 15.00	No	No	
ASBESTOS-ST1-5/27/07	030717123-0001	Southwest Area (sidewalk bridge level)	5/27/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST2-5/27/07	030717123-0002	Southeast Area (sidewalk bridge level)	5/27/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST4-5/27/07	030717123-0003	Northwest Area (street-level)	5/27/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST5-5/27/07	030717123-0004	Firehouse #10 (roof level)	5/27/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST10-5/27/07	030717123-0005	North Side Sidewalk Bridge	5/27/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST11-5/27/07	030717123-0006	90 Trinity Place (roof level)	5/27/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST12-5/27/07	030717123-0007	110 Greenwich Street (roof level)	5/27/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST13-5/27/07	030717123-0008	Marriott Hotel, 38th Floor (roof level)	5/27/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST14-5/27/07	030717123-0009	West Face - South end at corner (scaffolding level)	5/27/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST15-5/27/07	030717123-0010	South Face - East end at corner (scaffolding level)	5/27/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST16-5/27/07	030717123-0011	East Face - North end at corner (scaffolding level)	5/27/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST17-5/27/07	030717123-0012	North Face - West end at corner (scaffolding level)	5/27/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST1-5/28/07	030717128-0001	Southwest Area (sidewalk bridge level)	5/28/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST2-5/28/07	030717128-0002	Southeast Area (sidewalk bridge level)	5/28/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST4-5/28/07	030717128-0003	Northwest Area (street-level)	5/28/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST5-5/28/07	030717128-0004	Firehouse #10 (roof level)	5/28/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST10-5/28/07	030717128-0005	North Side Sidewalk Bridge	5/28/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST11-5/28/07	030717128-0006	90 Trinity Place (roof level)	5/28/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST12-5/28/07	030717128-0007	110 Greenwich Street (roof level)	5/28/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST13-5/28/07	030717128-0008	Marriott Hotel, 38th Floor (roof level)	5/28/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST14-5/28/07	030717128-0009	West Face - South end at corner (scaffolding level)	5/28/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST15-5/28/07	030717128-0010	South Face - East end at corner (scaffolding level)	5/28/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST16-5/28/07	030717128-0011	East Face - North end at corner (scaffolding level)	5/28/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST17-5/28/07	030717128-0012	North Face - West end at corner (scaffolding level)	5/28/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/29/07	< 13.00	No	No	
ASBESTOS-ST1-5/29/07	030717263-0001	Southwest Area (sidewalk bridge level)	5/29/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST2-5/29/07	030717263-0002	Southeast Area (sidewalk bridge level)	5/29/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST4-5/29/07	030717263-0003	Northwest Area (street-level)	5/29/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST5-5/29/07	030717263-0004	Firehouse #10 (roof level)	5/29/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST10-5/29/07	030717263-0005	North Side Sidewalk Bridge	5/29/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST11-5/29/07	030717263-0006	90 Trinity Place (roof level)	5/29/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST12-5/29/07	030717263-0007	110 Greenwich Street (roof level)	5/29/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST13-5/29/07	030717263-0008	Marriott Hotel, 38th Floor (roof level)	5/29/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST14-5/29/07	030717263-0009	West Face - South end at corner (scaffolding level)	5/29/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST15-5/29/07	030717263-0010	South Face - East end at corner (scaffolding level)	5/29/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST16-5/29/07	030717263-0011	East Face - North end at corner (scaffolding level)	5/29/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	
ASBESTOS-ST17-5/29/07	030717263-0012	North Face - West end at corner (scaffolding level)	5/29/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/07	< 13.00	No	No	