TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										**NA**			
EPA Site Specific Trigger Levels										**70**			
ASBESTOS-ST1-7/1/08	030821202-0001	Southwest Area (sidewalk bridge level)	7/1/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST2-7/1/08	030821202-0002	Southeast Area (sidewalk bridge level)	7/1/08	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST4-7/1/08	030821202-0003	Northwest Area (street-level)	7/1/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST5-7/1/08	030821202-0004	Firehouse #10 (roof level)	7/1/08	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST10-7/1/08	030821202-0005	North Side Sidewalk Bridge	7/1/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST100-7/1/08	030821202-0013	Station 10 Field Duplicate	7/1/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST11-7/1/08	030821202-0006	90 Trinity Place (roof level)	7/1/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST12-7/1/08	030821202-0007	110 Greenwich Street (roof level)	7/1/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST13-7/1/08	030821202-0008	Marriott Hotel, 38th Floor (roof level)	7/1/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST14-7/1/08	030821202-0009	West Face - South end at corner (scaffolding level)	7/1/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST15-7/1/08	030821202-0010	South Face - East end at corner (scaffolding level)	7/1/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST16-7/1/08	030821202-0011	East Face - North end at corner (scaffolding level)	7/1/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST17-7/1/08	030821202-0012	North Face - West end at corner (scaffolding level)	7/1/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/08	< 13.00	No	No	
ASBESTOS-ST1-7/2/08	030821349-0001	Southwest Area (sidewalk bridge level)	7/2/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST2-7/2/08	030821349-0002	Southeast Area (sidewalk bridge level)	7/2/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST4-7/2/08	030821349-0003	Northwest Area (street-level)	7/2/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST5-7/2/08	030821349-0004	Firehouse #10 (roof level)	7/2/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST10-7/2/08	030821349-0005	North Side Sidewalk Bridge	7/2/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST11-7/2/08	030821349-0006	90 Trinity Place (roof level)	7/2/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST12-7/2/08	030821349-0007	110 Greenwich Street (roof level)	7/2/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST13-7/2/08	030821349-0008	Marriott Hotel, 38th Floor (roof level)	7/2/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST14-7/2/08	030821349-0009	West Face - South end at corner (scaffolding level)	7/2/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST15-7/2/08	030821349-0010	South Face - East end at corner (scaffolding level)	7/2/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST16-7/2/08	030821349-0011	East Face - North end at corner (scaffolding level)	7/2/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST17-7/2/08	030821349-0012	North Face - West end at corner (scaffolding level)	7/2/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/08	< 13.00	No	No	
ASBESTOS-ST1-7/3/08	030821681-0001	Southwest Area (sidewalk bridge level)	7/3/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST2-7/3/08	030821681-0002	Southeast Area (sidewalk bridge level)	7/3/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST4-7/3/08	030821681-0003	Northwest Area (street-level)	7/3/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST5-7/3/08	030821681-0004	Firehouse #10 (roof level)	7/3/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST10-7/3/08	030821681-0005	North Side Sidewalk Bridge	7/3/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST11-7/3/08	030821681-0006	90 Trinity Place (roof level)	7/3/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST12-7/3/08	030821681-0007	110 Greenwich Street (roof level)	7/3/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST13-7/3/08	030821681-0008	Marriott Hotel, 38th Floor (roof level)	7/3/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST14-7/3/08	030821681-0009	West Face - South end at corner (scaffolding level)	7/3/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST15-7/3/08	030821681-0010	South Face - East end at corner (scaffolding level)	7/3/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST16-7/3/08	030821681-0011	East Face - North end at corner (scaffolding level)	7/3/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST17-7/3/08	030821681-0012	North Face - West end at corner (scaffolding level)	7/3/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST1-7/4/08	030821684-0001	Southwest Area (sidewalk bridge level)	7/4/08	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST2-7/4/08	030821684-0002	Southeast Area (sidewalk bridge level)	7/4/08	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST4-7/4/08	030821684-0003	Northwest Area (street-level)	7/4/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST5-7/4/08	030821684-0004	Firehouse #10 (roof level)	7/4/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST10-7/4/08	030821684-0005	North Side Sidewalk Bridge	7/4/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST11-7/4/08	030821684-0006	90 Trinity Place (roof level)	7/4/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST12-7/4/08	030821684-0007	110 Greenwich Street (roof level)	7/4/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST13-7/4/08	030821684-0008	Marriott Hotel, 38th Floor (roof level)	7/4/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST14-7/4/08	030821684-0009	West Face - South end at corner (scaffolding level)	7/4/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST15-7/4/08	030821684-0010	South Face - East end at corner (scaffolding level)	7/4/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST16-7/4/08	030821684-0011	East Face - North end at corner (scaffolding level)	7/4/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST17-7/4/08	030821684-0012	North Face - West end at corner (scaffolding level)	7/4/08	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST1-7/5/08	030821685-0001	Southwest Area (sidewalk bridge level)	7/5/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 15.00	No	No	
ASBESTOS-ST2-7/5/08	030821685-0002	Southeast Area (sidewalk bridge level)	7/5/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST4-7/5/08	030821685-0003	Northwest Area (street-level)	7/5/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST5-7/5/08	030821685-0004	Firehouse #10 (roof level)	7/5/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST10-7/5/08	030821685-0005	North Side Sidewalk Bridge	7/5/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST11-7/5/08	030821685-0006	90 Trinity Place (roof level)	7/5/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST12-7/5/08	030821685-0007	110 Greenwich Street (roof level)	7/5/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 15.00	No	No	
ASBESTOS-ST13-7/5/08	030821685-0008	Marriott Hotel, 38th Floor (roof level)	7/5/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST14-7/5/08	030821685-0009	West Face - South end at corner (scaffolding level)	7/5/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST15-7/5/08	030821685-0010	South Face - East end at corner (scaffolding level)	7/5/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST16-7/5/08	030821685-0011	East Face - North end at corner (scaffolding level)	7/5/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST17-7/5/08	030821685-0012	North Face - West end at corner (scaffolding level)	7/5/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST1-7/6/08	030821683-0001	Southwest Area (sidewalk bridge level)	7/6/08	1	3.250	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST2-7/6/08	030821683-0002	Southeast Area (sidewalk bridge level)	7/6/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST4-7/6/08	030821683-0003	Northwest Area (street-level)	7/6/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST5-7/6/08	030821683-0004	Firehouse #10 (roof level)	7/6/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST10-7/6/08	030821683-0005	North Side Sidewalk Bridge	7/6/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST11-7/6/08	030821683-0006	90 Trinity Place (roof level)	7/6/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST12-7/6/08	030821683-0007	110 Greenwich Street (roof level)	7/6/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST13-7/6/08	030821683-0008	Marriott Hotel, 38th Floor (roof level)	7/6/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST14-7/6/08	030821683-0009	West Face - South end at corner (scaffolding level)	7/6/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST15-7/6/08	030821683-0010	South Face - East end at corner (scaffolding level)	7/6/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST16-7/6/08	030821683-0011	East Face - North end at corner (scaffolding level)	7/6/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	
ASBESTOS-ST17-7/6/08	030821683-0012	North Face - West end at corner (scaffolding level)	7/6/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/7/08	< 13.00	No	No	