| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume ($m^3$) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Target Air Quality Levels | | | | | | | | | | NA | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | 70 | | | |
| ASBESTOS -ST1-9/1/06 | 030628987-0001 | Southwest Area (sidewalk bridge level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST2-9/1/06 | 030628987-0002 | Southeast Area (sidewalk bridge level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST4-9/1/06 | 030628987-0003 | Northwest Area (street-level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST5-9/1/06 | 030628987-0004 | Firehouse #10 (roof level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST6-9/1/2006 | 030628988-0001 | Southwest Area (roof level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST7-9/1/2006 | 030628988-0002 | Southeast Area (roof level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST8-9/1/2006 | 030628988-0003 | Northeast Area (roof level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST9-9/1/2006 | 030628988-0004 | Northwest Area (roof level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST10-9/1/06 | 030628987-0005 | North Side Sidewalk Bridge | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST100-9/1/06 | 030628987-0013 | Station 10 Field Duplicate | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST11-9/1/06 | 030628987-0006 | 90 Trinity Place (roof level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST12-9/1/06 | 030628987-0007 | 110 Greenwich Street (roof level) | 9/1/06 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST13-9/1/06 | 030628987-0008 | Marriott Hotel, 38th Floor (roof level) | 9/1/06 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST14-9/1/06 | 030628987-0009 | West Face - South end at corner (scaffolding level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST15-9/1/06 | 030628987-0010 | South Face - East end at corner (scaffolding level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST16-9/1/06 | 030628987-0011 | East Face - North end at corner (scaffolding level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS -ST17-9/1/06 | 030628987-0012 | North Face - West end at corner (scaffolding level) | 9/1/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST1-9/2/06 | 030629018-0001 | Southwest Area (sidewalk bridge level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST2-9/2/06 | 030629018-0002 | Southeast Area (sidewalk bridge level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST4-9/2/06 | 030629018-0003 | Northwest Area (street-level) | 9/2/06 | 1 | 3.150 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST5-9/2/06 | 030629018-0004 | Firehouse #10 (roof level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST6-9/2/06 | 030629037-0001 | Southwest Area (roof level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST7-9/2/06 | 030629037-0002 | Southeast Area (roof level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST8-9/2/06 | 030629037-0003 | Northeast Area (roof level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST9-9/2/06 | 030629037-0004 | Northwest Area (roof level) | 9/2/06 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST10-9/2/06 | 030629018-0005 | North Side Sidewalk Bridge | 9/2/06 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST11-9/2/06 | 030629018-0006 | 90 Trinity Place (roof level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST12-9/2/06 | 030629018-0007 | 110 Greenwich Street (roof level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST13-9/2/06 | 030629018-0008 | Marriott Hotel, 38th Floor (roof level) | 9/2/06 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST14-9/2/06 | 030629018-0009 | West Face - South end at corner (scaffolding level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST15-9/2/06 | 030629018-0010 | South Face - East end at corner (scaffolding level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST16-9/2/06 | 030629018-0011 | East Face - North end at corner (scaffolding level) | 9/2/06 | 1 | 2.960 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST17-9/2/06 | 030629018-0012 | North Face - West end at corner (scaffolding level) | 9/2/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST1-9/3/06 | 030628991-0001 | Southwest Area (sidewalk bridge level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST2-9/3/06 | 030628991-0002 | Southeast Area (sidewalk bridge level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST4-9/3/06 | 030628991-0003 | Northwest Area (street-level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST5-9/3/06 | 030628991-0004 | Firehouse #10 (roof level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST6-9/3/06 | 030628992-0001 | Southwest Area (roof level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST7-9/3/06 | 030628992-0002 | Southeast Area (roof level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST8-9/3/06 | 030628992-0003 | Northeast Area (roof level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST9-9/3/06 | 030628992-0004 | Northwest Area (roof level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST10-9/3/06 | 030628991-0005 | North Side Sidewalk Bridge | 9/3/06 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST11-9/3/06 | 030628991-0006 | 90 Trinity Place (roof level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST12-9/3/06 | 030628991-0007 | 110 Greenwich Street (roof level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST13-9/3/06 | 030628991-0008 | Marriott Hotel, 38th Floor (roof level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST14-9/3/06 | 030628991-0009 | West Face - South end at corner (scaffolding level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST15-9/3/06 | 030628991-0010 | South Face - East end at corner (scaffolding level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST16-9/3/06 | 030628991-0011 | East Face - North end at corner (scaffolding level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST17-9/3/06 | 030628991-0012 | North Face - West end at corner (scaffolding level) | 9/3/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST1-9/4/06 | 030628993-0001 | Southwest Area (sidewalk bridge level) | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST2-9/4/06 | 030628993-0002 | Southeast Area (sidewalk bridge level) | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST4-9/4/06 | 030628993-0003 | Northwest Area (street-level) | 9/4/06 | 1 | 3.210 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST5-9/4/06 | 030628993-0004 | Firehouse #10 (roof level) | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST6-9/4/06 | 030628994-0001 | Southwest Area (roof level) | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST7-9/4/06 | 030628994-0002 | Southeast Area (roof level) | 9/4/06 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST8-9/4/06 | 030628994-0003 | Northeast Area (roof level) | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST9-9/4/06 | 030628994-0004 | Northwest Area (roof level) | 9/4/06 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST10-9/4/06 | 030628993-0005 | North Side Sidewalk Bridge | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST11-9/4/06 | 030628993-0006 | 90 Trinity Place (roof level) | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST12-9/4/06 | 030628993-0007 | 110 Greenwich Street (roof level) | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST13-9/4/06 | 030628993-0008 | Marriott Hotel, 38th Floor (roof level) | 9/4/06 | 1 | 2.960 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST14-9/4/06 | 030628993-0009 | West Face - South end at corner (scaffolding level) | 9/4/06 | 1 | 2.900 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST15-9/4/06 | 030628993-0010 | South Face - East end at corner (scaffolding level) | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST16-9/4/06 | 030628993-0011 | East Face - North end at corner (scaffolding level) | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST17-9/4/06 | 030628993-0012 | North Face - West end at corner (scaffolding level) | 9/4/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/5/06 | < 13.00 | No | No | |
| ASBESTOS-ST1-9/5/06 | 030629149-0001 | Southwest Area (sidewalk bridge level) | 9/5/06 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST2-9/5/06 | 030629149-0002 | Southeast Area (sidewalk bridge level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST4-9/5/06 | 030629149-0003 | Northwest Area (street-level) | 9/5/06 | 1 | 3.150 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST5-9/5/06 | 030629149-0004 | Firehouse #10 (roof level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST6-9/5/06 | 030629160-0001 | Southwest Area (roof level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST7-9/5/06 | 030629160-0002 | Southeast Area (roof level) | 9/5/06 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST8-9/5/06 | 030629160-0003 | Northeast Area (roof level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST9-9/5/06 | 030629160-0004 | Northwest Area (roof level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST10-9/5/06 | 030629149-0005 | North Side Sidewalk Bridge | 9/5/06 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST11-9/5/06 | 030629149-0006 | 90 Trinity Place (roof level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST12-9/5/06 | 030629149-0007 | 110 Greenwich Street (roof level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST13-9/5/06 | 030629149-0008 | Marriott Hotel, 38th Floor (roof level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST14-9/5/06 | 030629149-0009 | West Face - South end at corner (scaffolding level) | 9/5/06 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST15-9/5/06 | 030629149-0010 | South Face - East end at corner (scaffolding level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST16-9/5/06 | 030629149-0011 | East Face - North end at corner (scaffolding level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |
| ASBESTOS-ST17-9/5/06 | 030629149-0012 | North Face - West end at corner (scaffolding level) | 9/5/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/6/06 | < 13.00 | No | No | |