TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-11/22/06	030638133-0001	Southwest Area (sidewalk bridge level)	11/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST2-11/22/06	030638133-0002	Southeast Area (sidewalk bridge level)	11/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST4-11/22/06	030638133-0003	Northwest Area (street-level)	11/22/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST5-11/22/06	030638133-0004	Firehouse #10 (roof level)	11/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST10-11/22/06	030638133-0005	North Side Sidewalk Bridge	11/22/06	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST11-11/22/06	030638133-0006	90 Trinity Place (roof level)	11/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST12-11/22/06	030638133-0007	110 Greenwich Street (roof level)	11/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST13-11/22/06	030638133-0008	Marriott Hotel, 38th Floor (roof level)	11/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST14-11/22/06	030638133-0009	West Face - South end at corner (scaffolding level)	11/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST15-11/22/06	030638133-0010	South Face - East end at corner (scaffolding level)	11/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST16-11/22/06	030638133-0011	East Face - North end at corner (scaffolding level)	11/22/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST17-11/22/06	030638133-0012	North Face - West end at corner (scaffolding level)	11/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST1-11/23/06	030638131-0001	Southwest Area (sidewalk bridge level)	11/23/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST2-11/23/06	030638131-0002	Southeast Area (sidewalk bridge level)	11/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST4-11/23/06	030638131-0003	Northwest Area (street-level)	11/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST5-11/23/06	030638131-0004	Firehouse #10 (roof level)	11/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST10-11/23/06	030638131-0005	North Side Sidewalk Bridge	11/23/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST11-11/23/06	030638131-0006	90 Trinity Place (roof level)	11/23/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST12-11/23/06	030638131-0007	110 Greenwich Street (roof level)	11/23/06	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST13-11/23/06	030638131-0008	Marriott Hotel, 38th Floor (roof level)	11/23/06	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST14-11/23/06	030638131-0009	West Face - South end at corner (scaffolding level)	11/23/06	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST15-11/23/06	030638131-0010	South Face - East end at corner (scaffolding level)	11/23/06	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST16-11/23/06	030638131-0011	East Face - North end at corner (scaffolding level)	11/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST17-11/23/06	030638131-0012	North Face - West end at corner (scaffolding level)	11/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/24/06	< 13.00	No	No	
ASBESTOS-ST1-11/24/06	030638323-0001	Southwest Area (sidewalk bridge level)	11/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST2-11/24/06	030638323-0002	Southeast Area (sidewalk bridge level)	11/24/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST4-11/24/06	030638323-0003	Northwest Area (street-level)	11/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST5-11/24/06	030638323-0004	Firehouse #10 (roof level)	11/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST10-11/24/06	030638323-0005	North Side Sidewalk Bridge	11/24/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST11-11/24/06	030638323-0006	90 Trinity Place (roof level)	11/24/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST12-11/24/06	030638323-0007	110 Greenwich Street (roof level)	11/24/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST13-11/24/06	030638323-0008	Marriott Hotel, 38th Floor (roof level)	11/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST14-11/24/06	030638323-0009	West Face - South end at corner (scaffolding level)	11/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST15-11/24/06	030638323-0010	South Face - East end at corner (scaffolding level)	11/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST16-11/24/06	030638323-0011	East Face - North end at corner (scaffolding level)	11/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST17-11/24/06	030638323-0012	North Face - West end at corner (scaffolding level)	11/24/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST1-11/25/06	030638324-0001	Southwest Area (sidewalk bridge level)	11/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST2-11/25/06	030638324-0002	Southeast Area (sidewalk bridge level)	11/25/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST4-11/25/06	030638324-0003	Northwest Area (street-level)	11/25/06	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 15.00	No	No	
ASBESTOS-ST5-11/25/06	030638324-0004	Firehouse #10 (roof level)	11/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST10-11/25/06	030638324-0005	North Side Sidewalk Bridge	11/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST11-11/25/06	030638324-0006	90 Trinity Place (roof level)	11/25/06	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 15.00	No	No	
ASBESTOS-ST12-11/25/06	030638324-0007	110 Greenwich Street (roof level)	11/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST13-11/25/06	030638324-0008	Marriott Hotel, 38th Floor (roof level)	11/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST14-11/25/06	030638324-0009	West Face - South end at corner (scaffolding level)	11/25/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST15-11/25/06	030638324-0010	South Face - East end at corner (scaffolding level)	11/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST16-11/25/06	030638324-0011	East Face - North end at corner (scaffolding level)	11/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST17-11/25/06	030638324-0012	North Face - West end at corner (scaffolding level)	11/25/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST1-11/26/06	030638325-0001	Southwest Area (sidewalk bridge level)	11/26/06	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST2-11/26/06	030638325-0002	Southeast Area (sidewalk bridge level)	11/26/06	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST4-11/26/06	030638325-0003	Northwest Area (street-level)	11/26/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST5-11/26/06	030638325-0004	Firehouse #10 (roof level)	11/26/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST10-11/26/06	030638325-0005	North Side Sidewalk Bridge	11/26/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST11-11/26/06	030638325-0006	90 Trinity Place (roof level)	11/26/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST12-11/26/06	030638325-0007	110 Greenwich Street (roof level)	11/26/06	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST13-11/26/06	030638325-0008	Marriott Hotel, 38th Floor (roof level)	11/26/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST14-11/26/06	030638325-0009	West Face - South end at corner (scaffolding level)	11/26/06	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST15-11/26/06	030638325-0010	South Face - East end at corner (scaffolding level)	11/26/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST16-11/26/06	030638325-0011	East Face - North end at corner (scaffolding level)	11/26/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	
ASBESTOS-ST17-11/26/06	030638325-0012	North Face - West end at corner (scaffolding level)	11/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/27/06	< 13.00	No	No	