TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-12/29/06	030700052-0001	Southwest Area (sidewalk bridge level)	12/29/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST2-12/29/06	030700052-0002	Southeast Area (sidewalk bridge level)	12/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST4-12/29/06	030700052-0003	Northwest Area (street-level)	12/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST5-12/29/06	030700052-0004	Firehouse #10 (roof level)	12/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST10-12/29/06	030700052-0005	North Side Sidewalk Bridge	12/29/06	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST11-12/29/06	030700052-0006	90 Trinity Place (roof level)	12/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST12-12/29/06	030700052-0007	110 Greenwich Street (roof level)	12/29/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST13-12/29/06	030700052-0008	Marriott Hotel, 38th Floor (roof level)	12/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST14-12/29/06	030700052-0009	West Face - South end at corner (scaffolding level)	12/29/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST15-12/29/06	030700052-0010	South Face - East end at corner (scaffolding level)	12/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST16-12/29/06	030700052-0011	East Face - North end at corner (scaffolding level)	12/29/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST17-12/29/06	030700052-0012	North Face - West end at corner (scaffolding level)	12/29/06	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST1-12/30/06	030700057-0001	Southwest Area (sidewalk bridge level)	12/30/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST2-12/30/06	030700057-0002	Southeast Area (sidewalk bridge level)	12/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST4-12/30/06	030700057-0003	Northwest Area (street-level)	12/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST5-12/30/06	030700057-0004	Firehouse #10 (roof level)	12/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST10-12/30/06	030700057-0005	North Side Sidewalk Bridge	12/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST11-12/30/06	030700057-0006	90 Trinity Place (roof level)	12/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST12-12/30/06	030700057-0007	110 Greenwich Street (roof level)	12/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST13-12/30/06	030700057-0008	Marriott Hotel, 38th Floor (roof level)	12/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST14-12/30/06	030700057-0009	West Face - South end at corner (scaffolding level)	12/30/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST15-12/30/06	030700057-0010	South Face - East end at corner (scaffolding level)	12/30/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST16-12/30/06	030700057-0011	East Face - North end at corner (scaffolding level)	12/30/06	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST17-12/30/06	030700057-0012	North Face - West end at corner (scaffolding level)	12/30/06	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST1-12/31/06	030700051-0001	Southwest Area (sidewalk bridge level)	12/31/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST2-12/31/06	030700051-0002	Southeast Area (sidewalk bridge level)	12/31/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST4-12/31/06	030700051-0003	Northwest Area (street-level)	12/31/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST5-12/31/06	030700051-0004	Firehouse #10 (roof level)	12/31/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST10-12/31/06	030700051-0005	North Side Sidewalk Bridge	12/31/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST11-12/31/06	030700051-0006	90 Trinity Place (roof level)	12/31/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST12-12/31/06	030700051-0007	110 Greenwich Street (roof level)	12/31/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST13-12/31/06	030700051-0008	Marriott Hotel, 38th Floor (roof level)	12/31/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST14-12/31/06	030700051-0009	West Face - South end at corner (scaffolding level)	12/31/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST15-12/31/06	030700051-0010	South Face - East end at corner (scaffolding level)	12/31/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST16-12/31/06	030700051-0011	East Face - North end at corner (scaffolding level)	12/31/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST17-12/31/06	030700051-0012	North Face - West end at corner (scaffolding level)	12/31/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST1-1/1/07	030700054-0001	Southwest Area (sidewalk bridge level)	1/1/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST2-1/1/07	030700054-0002	Southeast Area (sidewalk bridge level)	1/1/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST4-1/1/07	030700054-0003	Northwest Area (street-level)	1/1/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST5-1/1/07	030700054-0004	Firehouse #10 (roof level)	1/1/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST10-1/1/07	030700054-0005	North Side Sidewalk Bridge	1/1/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST11-1/1/07	030700054-0006	90 Trinity Place (roof level)	1/1/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST12-1/1/07	030700054-0007	110 Greenwich Street (roof level)	1/1/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST13-1/1/07	030700054-0008	Marriott Hotel, 38th Floor (roof level)	1/1/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST14-1/1/07	030700054-0009	West Face - South end at corner (scaffolding level)	1/1/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST15-1/1/07	030700054-0010	South Face - East end at corner (scaffolding level)	1/1/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 13.00	No	No	
ASBESTOS-ST16-1/1/07	030700054-0011	East Face - North end at corner (scaffolding level)	1/1/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST17-1/1/07	030700054-0012	North Face - West end at corner (scaffolding level)	1/1/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/07	< 15.00	No	No	
ASBESTOS-ST1-1/2/07	030700128-0001	Southwest Area (sidewalk bridge level)	1/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	
ASBESTOS-ST2-1/2/07	030700128-0002	Southeast Area (sidewalk bridge level)	1/2/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	
ASBESTOS-ST4-1/2/07	030700128-0003	Northwest Area (street-level)	1/2/07	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 15.00	No	No	
ASBESTOS-ST5-1/2/07	030700128-0004	Firehouse #10 (roof level)	1/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	
ASBESTOS-ST10-1/2/07	030700128-0005	North Side Sidewalk Bridge	1/2/07	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	
ASBESTOS-ST11-1/2/07	030700128-0006	90 Trinity Place (roof level)	1/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	
ASBESTOS-ST12-1/2/07	030700128-0007	110 Greenwich Street (roof level)	1/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	
ASBESTOS-ST13-1/2/07	030700128-0008	Marriott Hotel, 38th Floor (roof level)	1/2/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	
ASBESTOS-ST14-1/2/07	030700128-0009	West Face - South end at corner (scaffolding level)	1/2/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	
ASBESTOS-ST15-1/2/07	030700128-0010	South Face - East end at corner (scaffolding level)	1/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	
ASBESTOS-ST16-1/2/07	030700128-0011	East Face - North end at corner (scaffolding level)	1/2/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	
ASBESTOS-ST17-1/2/07	030700128-0012	North Face - West end at corner (scaffolding level)	1/2/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/07	< 13.00	No	No	