| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume ($m^3$) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Target Air Quality Levels | | | | | | | | | | 0.0009 | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | NA | | | |
| ASBESTOS-ST1-6/22/06 | 030619209-0001 | Southwest Area (sidewalk bridge level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST2-6/22/06 | 030619209-0002 | Southeast Area (sidewalk bridge level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST4-6/22/06 | 030619209-0003 | Northwest Area (street-level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST5-6/22/06 | 030619209-0004 | Firehouse #10 (roof level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST10-6/22/06 | 030619209-0005 | North Side Sidewalk Bridge | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | 0.00084 | No | No | |
| ASBESTOS-ST11-6/22/06 | 030619209-0006 | 90 Trinity Place (roof level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST12-6/22/06 | 030619209-0007 | 110 Greenwich Street (roof level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST13-6/22/06 | 030619209-0008 | Marriott Hotel, 38th Floor (roof level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST14-6/22/06 | 030619209-0009 | West Face - South end at corner (scaffolding level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST15-6/22/06 | 030619209-0010 | South Face - East end at corner (scaffolding level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST16-6/22/06 | 030619209-0011 | East Face - North end at corner (scaffolding level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST17-6/22/06 | 030619209-0012 | North Face - West end at corner (scaffolding level) | 6/22/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/23/06 | < 0.00084 | No | No | |
| ASBESTOS-ST1-6/23/06 | 030619470-0001 | Southwest Area (sidewalk bridge level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST2-6/23/06 | 030619470-0002 | Southeast Area (sidewalk bridge level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST4-6/23/06 | 030619470-0003 | Northwest Area (street-level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST5-6/23/06 | 030619470-0004 | Firehouse #10 (roof level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST10-6/23/06 | 030619470-0005 | North Side Sidewalk Bridge | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST11-6/23/06 | 030619470-0006 | 90 Trinity Place (roof level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST12-6/23/06 | 030619470-0007 | 110 Greenwich Street (roof level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST13-6/23/06 | 030619470-0008 | Marriott Hotel, 38th Floor (roof level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST14-6/23/06 | 030619470-0009 | West Face - South end at corner (scaffolding level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST15-6/23/06 | 030619470-0010 | South Face - East end at corner (scaffolding level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST16-6/23/06 | 030619470-0011 | East Face - North end at corner (scaffolding level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST17-6/23/06 | 030619470-0012 | North Face - West end at corner (scaffolding level) | 6/23/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST1-6/24/06 | 030619471-0001 | Southwest Area (sidewalk bridge level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST2-6/24/06 | 030619471-0002 | Southeast Area (sidewalk bridge level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST4-6/24/06 | 030619471-0003 | Northwest Area (street-level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST5-6/24/06 | 030619471-0004 | Firehouse #10 (roof level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST10-6/24/06 | 030619471-0005 | North Side Sidewalk Bridge | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST11-6/24/06 | 030619471-0006 | 90 Trinity Place (roof level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST12-6/24/06 | 030619471-0007 | 110 Greenwich Street (roof level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST13-6/24/06 | 030619471-0008 | Marriott Hotel, 38th Floor (roof level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST14-6/24/06 | 030619471-0009 | West Face - South end at corner (scaffolding level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST15-6/24/06 | 030619471-0010 | South Face - East end at corner (scaffolding level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST16-6/24/06 | 030619471-0011 | East Face - North end at corner (scaffolding level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST17-6/24/06 | 030619471-0012 | North Face - West end at corner (scaffolding level) | 6/24/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST1-6/25/06 | 030619468-0001 | Southwest Area (sidewalk bridge level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST2-6/25/06 | 030619468-0002 | Southeast Area (sidewalk bridge level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST4-6/25/06 | 030619468-0003 | Northwest Area (street-level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST5-6/25/06 | 030619468-0004 | Firehouse #10 (roof level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST10-6/25/06 | 030619468-0005 | North Side Sidewalk Bridge | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST11-6/25/06 | 030619468-0006 | 90 Trinity Place (roof level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST12-6/25/06 | 030619468-0007 | 110 Greenwich Street (roof level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST13-6/25/06 | 030619468-0008 | Marriott Hotel, 38th Floor (roof level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST14-6/25/06 | 030619468-0009 | West Face - South end at corner (scaffolding level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST15-6/25/06 | 030619468-0010 | South Face - East end at corner (scaffolding level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST16-6/25/06 | 030619468-0011 | East Face - North end at corner (scaffolding level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST17-6/25/06 | 030619468-0012 | North Face - West end at corner (scaffolding level) | 6/25/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/26/06 | < 0.00084 | No | No | |
| ASBESTOS-ST1-6/26/06 | 030619613-0001 | Southwest Area (sidewalk bridge level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST2-6/26/06 | 030619613-0002 | Southeast Area (sidewalk bridge level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST4-6/26/06 | 030619613-0003 | Northwest Area (street-level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST5-6/26/06 | 030619613-0004 | Firehouse #10 (roof level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST10-6/26/06 | 030619613-0005 | North Side Sidewalk Bridge | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST11-6/26/06 | 030619613-0006 | 90 Trinity Place (roof level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST12-6/26/06 | 030619613-0007 | 110 Greenwich Street (roof level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST13-6/26/06 | 030619613-0008 | Marriott Hotel, 38th Floor (roof level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST14-6/26/06 | 030619613-0009 | West Face - South end at corner (scaffolding level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST15-6/26/06 | 030619613-0010 | South Face - East end at corner (scaffolding level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST16-6/26/06 | 030619613-0011 | East Face - North end at corner (scaffolding level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |
| ASBESTOS-ST17-6/26/06 | 030619613-0012 | North Face - West end at corner (scaffolding level) | 6/26/06 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/27/06 | < 0.00084 | No | No | |