TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										**0.0009**			
EPA Site Specific Trigger Levels										**NA**			
ASBESTOS-ST1-7/27/06	030623891-0001	Southwest Area (sidewalk bridge level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST2-7/27/06	030623891-0002	Southeast Area (sidewalk bridge level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST4-7/27/06	030623891-0003	Northwest Area (street-level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST5-7/27/06	030623891-0004	Firehouse #10 (roof level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST6-7/27/06	030623893-0001	Southwest Area (roof level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST7-7/27/06	030623893-0002	Southeast Area (roof level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST8-7/27/06	030623893-0003	Northeast Area (roof level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST9-7/27/06	030623893-0004	Northwest Area (roof level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST10-7/27/06	030623891-0005	North Side Sidewalk Bridge	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST11-7/27/06	030623891-0006	90 Trinity Place (roof level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST12-7/27/06	030623891-0007	110 Greenwich Street (roof level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST13-7/27/06	030623891-0008	Marriott Hotel, 38th Floor (roof level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST14-7/27/06	030623891-0009	West Face - South end at corner (scaffolding level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST15-7/27/06	030623891-0010	South Face - East end at corner (scaffolding level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST16-7/27/06	030623891-0011	East Face - North end at corner (scaffolding level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST17-7/27/06	030623891-0012	North Face - West end at corner (scaffolding level)	7/27/06	1	2.970	Asbestos	PCME	EMSL	7/28/06	< 0.00083	No	No	
ASBESTOS-ST1-7/28/06	030624195-0001	Southwest Area (sidewalk bridge level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST2-7/28/06	030624195-0002	Southeast Area (sidewalk bridge level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST4-7/28/06	030624195-0003	Northwest Area (street-level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST5-7/28/06	030624195-0004	Firehouse #10 (roof level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST6-7/28/06	030624197-0001	Southwest Area (roof level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST7-7/28/06	030624197-0002	Southeast Area (roof level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST8-7/28/06	030624197-0003	Northeast Area (roof level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	0.00083	No	No	
ASBESTOS-ST9-7/28/06	030624197-0004	Northwest Area (roof level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST10-7/28/06	030624195-0005	North Side Sidewalk Bridge	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST11-7/28/06	030624195-0006	90 Trinity Place (roof level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST12-7/28/06	030624195-0007	110 Greenwich Street (roof level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST13-7/28/06	030624195-0008	Marriott Hotel, 38th Floor (roof level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST14-7/28/06	030624195-0009	West Face - South end at corner (scaffolding level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST15-7/28/06	030624195-0010	South Face - East end at corner (scaffolding level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST16-7/28/06	030624195-0011	East Face - North end at corner (scaffolding level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST17-7/28/06	030624195-0012	North Face - West end at corner (scaffolding level)	7/28/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST1-7/29/06	030624198-0001	Southwest Area (sidewalk bridge level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST2-7/29/06	030624198-0002	Southeast Area (sidewalk bridge level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST4-7/29/06	030624198-0003	Northwest Area (street-level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST5-7/29/06	030624198-0004	Firehouse #10 (roof level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST6-7/29/06	030624199-0001	Southwest Area (roof level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST7-7/29/06	030624199-0002	Southeast Area (roof level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST8-7/29/06	030624199-0003	Northeast Area (roof level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST9-7/29/06	030624199-0004	Northwest Area (roof level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST10-7/29/06	030624198-0005	North Side Sidewalk Bridge	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST11-7/29/06	030624198-0006	90 Trinity Place (roof level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST12-7/29/06	030624198-0007	110 Greenwich Street (roof level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST13-7/29/06	030624198-0008	Marriott Hotel, 38th Floor (roof level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST14-7/29/06	030624198-0009	West Face - South end at corner (scaffolding level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST15-7/29/06	030624198-0010	South Face - East end at corner (scaffolding level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST16-7/29/06	030624198-0011	East Face - North end at corner (scaffolding level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST17-7/29/06	030624198-0012	North Face - West end at corner (scaffolding level)	7/29/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST1-7/30/06	030624200-0001	Southwest Area (sidewalk bridge level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST2-7/30/06	030624200-0002	Southeast Area (sidewalk bridge level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST4-7/30/06	030624200-0003	Northwest Area (street-level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST5-7/30/06	030624200-0004	Firehouse #10 (roof level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST6-7/30/06	030624201-0001	Southwest Area (roof level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST7-7/30/06	030624201-0002	Southeast Area (roof level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST8-7/30/06	030624201-0003	Northeast Area (roof level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST9-7/30/06	030624201-0004	Northwest Area (roof level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST10-7/30/06	030624200-0005	North Side Sidewalk Bridge	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST11-7/30/06	030624200-0006	90 Trinity Place (roof level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST12-7/30/06	030624200-0007	110 Greenwich Street (roof level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST13-7/30/06	030624200-0008	Marriott Hotel, 38th Floor (roof level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST14-7/30/06	030624200-0009	West Face - South end at corner (scaffolding level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST15-7/30/06	030624200-0010	South Face - East end at corner (scaffolding level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST16-7/30/06	030624200-0011	East Face - North end at corner (scaffolding level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	
ASBESTOS-ST17-7/30/06	030624200-0012	North Face - West end at corner (scaffolding level)	7/30/06	1	2.970	Asbestos	PCME	EMSL	7/31/06	< 0.00083	No	No	