TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-7/29/07	030725538-0001	Southwest Area (sidewalk bridge level)	7/29/07	1	3.090	Asbestos	PCME	EMSL	7/30/07	< 0.00087	No	No	
ASBESTOS-ST2-7/29/07	030725538-0002	Southeast Area (sidewalk bridge level)	7/29/07	1	3.090	Asbestos	PCME	EMSL	7/30/07	< 0.00087	No	No	
ASBESTOS-ST4-7/29/07	030725538-0003	Northwest Area (street-level)	7/29/07	1	3.010	Asbestos	PCME	EMSL	7/30/07	< 0.00089	No	No	
ASBESTOS-ST5-7/29/07	030725538-0004	Firehouse #10 (roof level)	7/29/07	1	3.010	Asbestos	PCME	EMSL	7/30/07	< 0.00089	No	No	
ASBESTOS-ST10-7/29/07	030725538-0005	North Side Sidewalk Bridge	7/29/07	1	3.040	Asbestos	PCME	EMSL	7/30/07	< 0.00089	No	No	
ASBESTOS-ST11-7/29/07	030725538-0006	90 Trinity Place (roof level)	7/29/07	1	3.090	Asbestos	PCME	EMSL	7/30/07	< 0.00087	No	No	
ASBESTOS-ST12-7/29/07	030725538-0007	110 Greenwich Street (roof level)	7/29/07	1	2.960	Asbestos	PCME	EMSL	7/30/07	< 0.00083	No	No	
ASBESTOS-ST13-7/29/07	030725538-0008	Marriott Hotel, 38th Floor (roof level)	7/29/07	1	3.010	Asbestos	PCME	EMSL	7/30/07	< 0.00089	No	No	
ASBESTOS-ST14-7/29/07	030725538-0009	West Face - South end at corner (scaffolding level)	7/29/07	1	3.050	Asbestos	PCME	EMSL	7/30/07	< 0.00088	No	No	
ASBESTOS-ST15-7/29/07	030725538-0010	South Face - East end at corner (scaffolding level)	7/29/07	1	3.010	Asbestos	PCME	EMSL	7/30/07	< 0.00089	No	No	
ASBESTOS-ST16-7/29/07	030725538-0011	East Face - North end at corner (scaffolding level)	7/29/07	1	3.010	Asbestos	PCME	EMSL	7/30/07	< 0.00089	No	No	
ASBESTOS-ST17-7/29/07	030725538-0012	North Face - West end at corner (scaffolding level)	7/29/07	1	2.980	Asbestos	PCME	EMSL	7/30/07	< 0.00083	No	No	
ASBESTOS-ST1-7/30/07	030725681-0001	Southwest Area (sidewalk bridge level)	7/30/07	1	3.040	Asbestos	PCME	EMSL	7/31/07	< 0.00089	No	No	
ASBESTOS-ST2-7/30/07	030725681-0002	Southeast Area (sidewalk bridge level)	7/30/07	1	3.040	Asbestos	PCME	EMSL	7/31/07	< 0.00089	No	No	
ASBESTOS-ST4-7/30/07	030725681-0003	Northwest Area (street-level)	7/30/07	1	3.010	Asbestos	SEM	EMSL	7/31/07	< 0.00060	No	No	
ASBESTOS-ST5-7/30/07	030725681-0004	Firehouse #10 (roof level)	7/30/07	1	3.060	Asbestos	PCME	EMSL	7/31/07	< 0.00088	No	No	
ASBESTOS-ST10-7/30/07	030725681-0005	North Side Sidewalk Bridge	7/30/07	1	3.040	Asbestos	PCME	EMSL	7/31/07	< 0.00089	No	No	
ASBESTOS-ST11-7/30/07	030725681-0006	90 Trinity Place (roof level)	7/30/07	1	2.970	Asbestos	PCME	EMSL	7/31/07	< 0.00083	No	No	
ASBESTOS-ST12-7/30/07	030725681-0007	110 Greenwich Street (roof level)	7/30/07	1	2.960	Asbestos	PCME	EMSL	7/31/07	< 0.00083	No	No	
ASBESTOS-ST13-7/30/07	030725681-0008	Marriott Hotel, 38th Floor (roof level)	7/30/07	1	3.020	Asbestos	PCME	EMSL	7/31/07	< 0.00082	No	No	
ASBESTOS-ST14-7/30/07	030725681-0009	West Face - South end at corner (scaffolding level)	7/30/07	1	3.050	Asbestos	PCME	EMSL	7/31/07	< 0.00081	No	No	
ASBESTOS-ST15-7/30/07	030725681-0010	South Face - East end at corner (scaffolding level)	7/30/07	1	3.040	Asbestos	PCME	EMSL	7/31/07	< 0.00081	No	No	
ASBESTOS-ST16-7/30/07	030725681-0011	East Face - North end at corner (scaffolding level)	7/30/07	1	3.090	Asbestos	PCME	EMSL	7/31/07	< 0.00080	No	No	
ASBESTOS-ST17-7/30/07	030725681-0012	North Face - West end at corner (scaffolding level)	7/30/07	1	2.960	Asbestos	PCME	EMSL	7/31/07	< 0.00083	No	No	
ASBETOS-ST1-7/31/07	030725926-0001	Southwest Area (sidewalk bridge level)	7/31/07	1	3.040	Asbestos	PCME	EMSL	8/1/07	< 0.00089	No	No	
ASBETOS-ST2-7/31/07	030725926-0002	Southeast Area (sidewalk bridge level)	7/31/07	1	3.020	Asbestos	SEM	EMSL	8/1/07	< 0.00060	No	No	
ASBETOS-ST4-7/31/07	030725926-0003	Northwest Area (street-level)	7/31/07	1	3.040	Asbestos	PCME	EMSL	8/1/07	< 0.00089	No	No	
ASBETOS-ST5-7/31/07	030725926-0004	Firehouse #10 (roof level)	7/31/07	1	3.040	Asbestos	PCME	EMSL	8/1/07	< 0.00081	No	No	
ASBETOS-ST10-7/31/07	030725926-0005	North Side Sidewalk Bridge	7/31/07	1	3.060	Asbestos	PCME	EMSL	8/1/07	< 0.00088	No	No	
ASBETOS-ST100-7/31/07	030725926-0013	Station 10 Field Duplicate	7/31/07	1	3.070	Asbestos	PCME	EMSL	8/1/07	< 0.00088	No	No	
ASBETOS-ST11-7/31/07	030725926-0006	90 Trinity Place (roof level)	7/31/07	1	3.070	Asbestos	PCME	EMSL	8/1/07	< 0.00088	No	No	
ASBETOS-ST12-7/31/07	030725926-0007	110 Greenwich Street (roof level)	7/31/07	1	2.980	Asbestos	PCME	EMSL	8/1/07	< 0.00083	No	No	
ASBETOS-ST13-7/31/07	030725926-0008	Marriott Hotel, 38th Floor (roof level)	7/31/07	1	3.060	Asbestos	PCME	EMSL	8/1/07	< 0.00088	No	No	
ASBETOS-ST14-7/31/07	030725926-0009	West Face - South end at corner (scaffolding level)	7/31/07	1	3.040	Asbestos	PCME	EMSL	8/1/07	< 0.00089	No	No	
ASBETOS-ST15-7/31/07	030725926-0010	South Face - East end at corner (scaffolding level)	7/31/07	1	2.970	Asbestos	SEM	EMSL	8/1/07	< 0.00060	No	No	
ASBETOS-ST16-7/31/07	030725926-0011	East Face - North end at corner (scaffolding level)	7/31/07	1	3.040	Asbestos	PCME	EMSL	8/1/07	< 0.00089	No	No	
ASBETOS-ST17-7/31/07	030725926-0012	North Face - West end at corner (scaffolding level)	7/31/07	1	3.060	Asbestos	PCME	EMSL	8/1/07	< 0.00086	No	No	