

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-1/5/2007	030700614-0001	Southwest Area (sidewalk bridge level)	1/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST2-1/5/2007	030700614-0002	Southeast Area (sidewalk bridge level)	1/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST4-1/5/2007	030700614-0003	Northwest Area (street-level)	1/5/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST5-1/5/2007	030700614-0004	Firehouse #10 (roof level)	1/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST10-1/5/2007	030700614-0005	North Side Sidewalk Bridge	1/5/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST100-1/5/2007	030700614-0013	Station 10 Field Duplicate	1/5/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST11-1/5/2007	030700614-0006	90 Trinity Place (roof level)	1/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST12-1/5/2007	030700614-0007	110 Greenwich Street (roof level)	1/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST13-1/5/2007	030700614-0008	Marriott Hotel, 38th Floor (roof level)	1/5/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST14-1/5/2007	030700614-0009	West Face - South end at corner (scaffolding level)	1/5/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST15-1/5/2007	030700614-0010	South Face - East end at corner (scaffolding level)	1/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST16-1/5/2007	030700614-0011	East Face - North end at corner (scaffolding level)	1/5/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST17-1/5/2007	030700614-0012	North Face - West end at corner (scaffolding level)	1/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST1-1/6/07	030700613-0001	Southwest Area (sidewalk bridge level)	1/6/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST2-1/6/07	030700613-0002	Southeast Area (sidewalk bridge level)	1/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST4-1/6/07	030700613-0003	Northwest Area (street-level)	1/6/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST5-1/6/07	030700613-0004	Firehouse #10 (roof level)	1/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST10-1/6/07	030700613-0005	North Side Sidewalk Bridge	1/6/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST11-1/6/07	030700613-0006	90 Trinity Place (roof level)	1/6/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST12-1/6/07	030700613-0007	110 Greenwich Street (roof level)	1/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST13-1/6/07	030700613-0008	Marriott Hotel, 38th Floor (roof level)	1/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST14-1/6/07	030700613-0009	West Face - South end at corner (scaffolding level)	1/6/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST15-1/6/07	030700613-0010	South Face - East end at corner (scaffolding level)	1/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST16-1/6/07	030700613-0011	East Face - North end at corner (scaffolding level)	1/6/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST17-1/6/07	030700613-0012	North Face - West end at corner (scaffolding level)	1/6/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST1-1/7/07	030700615-0001	Southwest Area (sidewalk bridge level)	1/7/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST2-1/7/07	030700615-0002	Southeast Area (sidewalk bridge level)	1/7/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST4-1/7/07	030700615-0003	Northwest Area (street-level)	1/7/07	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST5-1/7/07	030700615-0004	Firehouse #10 (roof level)	1/7/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST10-1/7/07	030700615-0005	North Side Sidewalk Bridge	1/7/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST11-1/7/07	030700615-0006	90 Trinity Place (roof level)	1/7/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST12-1/7/07	030700615-0007	110 Greenwich Street (roof level)	1/7/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST13-1/7/07	030700615-0008	Marriott Hotel, 38th Floor (roof level)	1/7/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST14-1/7/07	030700615-0009	West Face - South end at corner (scaffolding level)	1/7/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 13.00	No	No	
ASBESTOS-ST15-1/7/07	030700615-0010	South Face - East end at corner (scaffolding level)	1/7/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST16-1/7/07	030700615-0011	East Face - North end at corner (scaffolding level)	1/7/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST17-1/7/07	030700615-0012	North Face - West end at corner (scaffolding level)	1/7/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/8/07	< 15.00	No	No	
ASBESTOS-ST1-1/8/07	030700702-0001	Southwest Area (sidewalk bridge level)	1/8/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 15.00	No	No	
ASBESTOS-ST2-1/8/07	030700702-0002	Southeast Area (sidewalk bridge level)	1/8/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 13.00	No	No	
ASBESTOS-ST4-1/8/07	030700702-0003	Northwest Area (street-level)	1/8/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 13.00	No	No	
ASBESTOS-ST5-1/8/07	030700702-0004	Firehouse #10 (roof level)	1/8/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 13.00	No	No	
ASBESTOS-ST10-1/8/07	030700702-0005	North Side Sidewalk Bridge	1/8/07	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 15.00	No	No	
ASBESTOS-ST11-1/8/07	030700702-0006	90 Trinity Place (roof level)	1/8/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 15.00	No	No	
ASBESTOS-ST12-1/8/07	030700702-0007	110 Greenwich Street (roof level)	1/8/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 15.00	No	No	
ASBESTOS-ST13-1/8/07	030700702-0008	Marriott Hotel, 38th Floor (roof level)	1/8/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 13.00	No	No	
ASBESTOS-ST14-1/8/07	030700702-0009	West Face - South end at corner (scaffolding level)	1/8/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 13.00	No	No	
ASBESTOS-ST15-1/8/07	030700702-0010	South Face - East end at corner (scaffolding level)	1/8/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 13.00	No	No	
ASBESTOS-ST16-1/8/07	030700702-0011	East Face - North end at corner (scaffolding level)	1/8/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 13.00	No	No	
ASBESTOS-ST17-1/8/07	030700702-0012	North Face - West end at corner (scaffolding level)	1/8/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/07	< 13.00	No	No	