

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-1/20/06	030602172-0001	Southwest Area (sidewalk bridge level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST2-1/20/06	030602172-0002	Southeast Area (sidewalk bridge level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST4-1/20/06	030602172-0003	Northwest Area (street-level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST5-1/20/06	030602172-0004	Firehouse #10 (roof level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST10-1/20/06	030602172-0005	North Side Sidewalk Bridge	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST11-1/20/06	030602172-0006	90 Trinity Place (roof level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST12-1/20/06	030602172-0007	110 Greenwich Street (roof level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST13-1/20/06	030602172-0008	Marriott Hotel, 38th Floor (roof level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST14-1/20/06	030602172-0009	West Face - South end at corner (scaffolding level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST15-1/20/06	030602172-0010	South Face - East end at corner (scaffolding level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST16-1/20/06	030602172-0011	East Face - North end at corner (scaffolding level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST17-1/20/06	030602172-0012	North Face - West end at corner (scaffolding level)	1/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST1-1/21/06	030602165-0001	Southwest Area (sidewalk bridge level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST2-1/21/06	030602165-0002	Southeast Area (sidewalk bridge level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST4-1/21/06	030602165-0003	Northwest Area (street-level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST5-1/21/06	030602165-0004	Firehouse #10 (roof level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST10-1/21/06	030602165-0005	North Side Sidewalk Bridge	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST11-1/21/06	030602165-0006	90 Trinity Place (roof level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST12-1/21/06	030602165-0007	110 Greenwich Street (roof level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST13-1/21/06	030602165-0008	Marriott Hotel, 38th Floor (roof level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST14-1/21/06	030602165-0009	West Face - South end at corner (scaffolding level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST15-1/21/06	030602165-0010	South Face - East end at corner (scaffolding level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST16-1/21/06	030602165-0011	East Face - North end at corner (scaffolding level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST17-1/21/06	030602165-0012	North Face - West end at corner (scaffolding level)	1/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST1-1/22/06	030602174-0001	Southwest Area (sidewalk bridge level)	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST2-1/22/06	030602174-0002	Southeast Area (sidewalk bridge level)	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST4-1/22/06	030602174-0003	Northwest Area (street-level)	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST5-1/22/06	030602174-0004	Firehouse #10 (roof level)	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST10-1/22/06	030602174-0005	North Side Sidewalk Bridge	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST11-1/22/06	030602174-0006	90 Trinity Place (roof level)	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST12-1/22/06	030602174-0007	110 Greenwich Street (roof level)	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST13-1/22/06	030602174-0008	Marriott Hotel, 38th Floor (roof level)	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST15-1/22/06	030602174-0010	South Face - East end at corner (scaffolding level)	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST16-1/22/06	030602174-0011	East Face - North end at corner (scaffolding level)	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST17-1/22/06	030602174-0012	North Face - West end at corner (scaffolding level)	1/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/23/06	< 13.00	No	No	
ASBESTOS-ST1-1/23/06	030602300-0001	Southwest Area (sidewalk bridge level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST2-1/23/06	030602300-0002	Southeast Area (sidewalk bridge level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST4-1/23/06	030602300-0003	Northwest Area (street-level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST5-1/23/06	030602300-0004	Firehouse #10 (roof level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST10-1/23/06	030602300-0005	North Side Sidewalk Bridge	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST11-1/23/06	030602300-0006	90 Trinity Place (roof level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST12-1/23/06	030602300-0007	110 Greenwich Street (roof level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST13-1/23/06	030602300-0008	Marriott Hotel, 38th Floor (roof level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST14-1/23/06	030602300-0009	West Face - South end at corner (scaffolding level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST15-1/23/06	030602300-0010	South Face - East end at corner (scaffolding level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST16-1/23/06	030602300-0011	East Face - North end at corner (scaffolding level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	
ASBESTOS-ST17-1/23/06	030602300-0012	North Face - West end at corner (scaffolding level)	1/23/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/24/06	< 13.00	No	No	

Notes:

1. Asbestos sample at Station 14 (West Face – South end at corner [scaffolding level]) on January 22, 2006 was not available for analysis due to damaged filter.