

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels										70	Levels	Trigger Levels	
ASBESTOS-ST1-1/27/06	030602866-0001	Southwest Area (sidewalk bridge level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST2-1/27/06	030602866-0002	Southeast Area (sidewalk bridge level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST4-1/27/06	030602866-0003	Northwest Area (street-level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST5-1/27/06	030602866-0004	Firehouse #10 (roof level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST10-1/27/06	030602866-0005	North Side Sidewalk Bridge	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST11-1/27/06	030602866-0006	90 Trinity Place (roof level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST12-1/27/06	030602866-0007	110 Greenwich Street (roof level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST13-1/27/06	030602866-0008	Marriott Hotel, 38th Floor (roof level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST14-1/27/06	030602866-0009	West Face - South end at corner (scaffolding level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST15-1/27/06	030602866-0010	South Face - East end at corner (scaffolding level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST16-1/27/06	030602866-0011	East Face - North end at corner (scaffolding level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST17-1/27/06	030602866-0012	North Face - West end at corner (scaffolding level)	1/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST1-1/28/06	030602869-0001	Southwest Area (sidewalk bridge level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST2-1/28/06	030602869-0002	Southeast Area (sidewalk bridge level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST4-1/28/06	030602869-0003	Northwest Area (street-level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST5-1/28/06	030602869-0004	Firehouse #10 (roof level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST10-1/28/06	030602869-0005	North Side Sidewalk Bridge	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST11-1/28/06	030602869-0006	90 Trinity Place (roof level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST12-1/28/06	030602869-0007	110 Greenwich Street (roof level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST13-1/28/06	030602869-0008	Marriott Hotel, 38th Floor (roof level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST14-1/28/06	030602869-0009	West Face - South end at corner (scaffolding level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST15-1/28/06	030602869-0010	South Face - East end at corner (scaffolding level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST16-1/28/06	030602869-0011	East Face - North end at corner (scaffolding level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST17-1/28/06	030602869-0012	North Face - West end at corner (scaffolding level)	1/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST1-1/29/06	030602870-0001	Southwest Area (sidewalk bridge level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST2-1/29/06	030602870-0002	Southeast Area (sidewalk bridge level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST4-1/29/06	030602870-0003	Northwest Area (street-level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST5-1/29/06	030602870-0004	Firehouse #10 (roof level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST10-1/29/06	030602870-0005	North Side Sidewalk Bridge	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST11-1/29/06	030602870-0006	90 Trinity Place (roof level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST12-1/29/06	030602870-0007	110 Greenwich Street (roof level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST13-1/29/06	030602870-0008	Marriott Hotel, 38th Floor (roof level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST14-1/29/06	030602870-0009	West Face - South end at corner (scaffolding level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST15-1/29/06	030602870-0010	South Face - East end at corner (scaffolding level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST16-1/29/06	030602870-0011	East Face - North end at corner (scaffolding level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST17-1/29/06	030602870-0012	North Face - West end at corner (scaffolding level)	1/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/30/06	< 13.00	No	No	
ASBESTOS-ST1-1/30/2006	030602976-0001	Southwest Area (sidewalk bridge level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST2-1/30/2006	030602976-0002	Southeast Area (sidewalk bridge level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST4-1/30/2006	030602976-0003	Northwest Area (street-level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST5-1/30/2006	030602976-0004	Firehouse #10 (roof level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST10-1/30/2006	030602976-0005	North Side Sidewalk Bridge	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST11-1/30/2006	030602976-0006	90 Trinity Place (roof level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST12-1/30/2006	030602976-0007	110 Greenwich Street (roof level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST13-1/30/2006	030602976-0008	Marriott Hotel, 38th Floor (roof level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST14-1/30/2006	030602976-0009	West Face - South end at corner (scaffolding level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST15-1/30/2006	030602976-0010	South Face - East end at corner (scaffolding level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST16-1/30/2006	030602976-0011	East Face - North end at corner (scaffolding level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	
ASBESTOS-ST17-1/30/2006	030602976-0012	North Face - West end at corner (scaffolding level)	1/30/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/31/06	< 13.00	No	No	