

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-2/3/06	030603679-0001	Southwest Area (sidewalk bridge level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST2-2/3/06	030603679-0002	Southeast Area (sidewalk bridge level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST4-2/3/06	030603679-0003	Northwest Area (street-level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST5-2/3/06	030603679-0004	Firehouse #10 (roof level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST10-2/3/06	030603679-0005	North Side Sidewalk Bridge	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST11-2/3/06	030603679-0006	90 Trinity Place (roof level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST12-2/3/06	030603679-0007	110 Greenwich Street (roof level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST13-2/3/06	030603679-0008	Marriott Hotel, 38th Floor (roof level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST14-2/3/06	030603679-0009	West Face - South end at corner (scaffolding level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST15-2/3/06	030603679-0010	South Face - East end at corner (scaffolding level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST16-2/3/06	030603679-0011	East Face - North end at corner (scaffolding level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST17-2/3/06	030603679-0012	North Face - West end at corner (scaffolding level)	2/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST1-2/4/06	030603680-0001	Southwest Area (sidewalk bridge level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST2-2/4/06	030603680-0002	Southeast Area (sidewalk bridge level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST4-2/4/06	030603680-0003	Northwest Area (street-level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST5-2/4/06	030603680-0004	Firehouse #10 (roof level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST10-2/4/06	030603680-0005	North Side Sidewalk Bridge	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST11-2/4/06	030603680-0006	90 Trinity Place (roof level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST12-2/4/06	030603680-0007	110 Greenwich Street (roof level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST13-2/4/06	030603680-0008	Marriott Hotel, 38th Floor (roof level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST14-2/4/06	030603680-0009	West Face - South end at corner (scaffolding level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST15-2/4/06	030603680-0010	South Face - East end at corner (scaffolding level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST16-2/4/06	030603680-0011	East Face - North end at corner (scaffolding level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST17-2/4/06	030603680-0012	North Face - West end at corner (scaffolding level)	2/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST1-2/5/06	030603682-0001	Southwest Area (sidewalk bridge level)	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST2-2/5/06	030603682-0002	Southeast Area (sidewalk bridge level)	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST4-2/5/06	030603682-0003	Northwest Area (street-level)	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST5-2/5/06	030603682-0004	Firehouse #10 (roof level)	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST10-2/5/06	030603682-0005	North Side Sidewalk Bridge	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST11-2/5/06	030603682-0006	90 Trinity Place (roof level)	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST12-2/5/06	030603682-0007	110 Greenwich Street (roof level)	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST13-2/5/06	030603682-0008	Marriott Hotel, 38th Floor (roof level)	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST14-2/5/06	030603682-0009	West Face - South end at corner (scaffolding level)	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST16-2/5/06	030603682-0011	East Face - North end at corner (scaffolding level)	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST17-2/5/06	030603682-0012	North Face - West end at corner (scaffolding level)	2/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/06	< 13.00	No	No	
ASBESTOS-ST1-2/6/06	030603791-0001	Southwest Area (sidewalk bridge level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST2-2/6/06	030603791-0002	Southeast Area (sidewalk bridge level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST4-2/6/06	030603791-0003	Northwest Area (street-level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST5-2/6/06	030603791-0004	Firehouse #10 (roof level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST10-2/6/06	030603791-0005	North Side Sidewalk Bridge	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST11-2/6/06	030603791-0006	90 Trinity Place (roof level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST12-2/6/06	030603791-0007	110 Greenwich Street (roof level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST13-2/6/06	030603791-0008	Marriott Hotel, 38th Floor (roof level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST14-2/6/06	030603791-0009	West Face - South end at corner (scaffolding level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST15-2/6/06	030603791-0010	South Face - East end at corner (scaffolding level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST16-2/6/06	030603791-0011	East Face - North end at corner (scaffolding level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	
ASBESTOS-ST17-2/6/06	030603791-0012	North Face - West end at corner (scaffolding level)	2/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/06	< 13.00	No	No	

Notes:

1. Asbestos sample at Station 15 (South Face - East end at corner [scaffolding level]) on February 5, 2006 was not available for analysis due to damaged filter.