

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels											70	Levels	Trigger Levels	
ASBESTOS-ST1-2/4/09	030903400-0001	Southwest Area (sidewalk bridge level)	2/4/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST2-2/4/09	030903400-0002	Southeast Area (sidewalk bridge level)	2/4/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST4-2/4/09	030903400-0003	Northwest Area (street-level)	2/4/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST5-2/4/09	030903400-0004	Firehouse #10 (roof level)	2/4/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST10-2/4/09	030903400-0005	North Side Sidewalk Bridge	2/4/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST11-2/4/09	030903400-0006	90 Trinity Place (roof level)	2/4/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST12-2/4/09	030903400-0007	110 Greenwich Street (roof level)	2/4/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST13-2/4/09	030903400-0008	Marriott Hotel, 38th Floor (roof level)	2/4/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST14-2/4/09	030903400-0009	West Face - South end at corner (scaffolding level)	2/4/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST15-2/4/09	030903400-0010	South Face - East end at corner (scaffolding level)	2/4/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST16-2/4/09	030903400-0011	East Face - North end at corner (scaffolding level)	2/4/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST17-2/4/09	030903400-0012	North Face - West end at corner (scaffolding level)	2/4/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/09	< 13.00	No	No		
ASBESTOS-ST1-2/5/09	030903491-0001	Southwest Area (sidewalk bridge level)	2/5/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST2-2/5/09	030903491-0002	Southeast Area (sidewalk bridge level)	2/5/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST4-2/5/09	030903491-0003	Northwest Area (street-level)	2/5/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST5-2/5/09	030903491-0004	Firehouse #10 (roof level)	2/5/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST10-2/5/09	030903491-0005	North Side Sidewalk Bridge	2/5/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST11-2/5/09	030903491-0006	90 Trinity Place (roof level)	2/5/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST12-2/5/09	030903491-0007	110 Greenwich Street (roof level)	2/5/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST13-2/5/09	030903491-0008	Marriott Hotel, 38th Floor (roof level)	2/5/09	1	3.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST14-2/5/09	030903491-0009	West Face - South end at corner (scaffolding level)	2/5/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST15-2/5/09	030903491-0010	South Face - East end at corner (scaffolding level)	2/5/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST16-2/5/09	030903491-0011	East Face - North end at corner (scaffolding level)	2/5/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST17-2/5/09	030903491-0012	North Face - West end at corner (scaffolding level)	2/5/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/09	< 13.00	No	No		
ASBESTOS-ST1-2/6/09	030903551-0001	Southwest Area (sidewalk bridge level)	2/6/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST2-2/6/09	030903551-0002	Southeast Area (sidewalk bridge level)	2/6/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST4-2/6/09	030903551-0003	Northwest Area (street-level)	2/6/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST5-2/6/09	030903551-0004	Firehouse #10 (roof level)	2/6/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST10-2/6/09	030903551-0005	North Side Sidewalk Bridge	2/6/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST11-2/6/09	030903551-0006	90 Trinity Place (roof level)	2/6/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST12-2/6/09	030903551-0007	110 Greenwich Street (roof level)	2/6/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST13-2/6/09	030903551-0008	Marriott Hotel, 38th Floor (roof level)	2/6/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST14-2/6/09	030903551-0009	West Face - South end at corner (scaffolding level)	2/6/09	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST15-2/6/09	030903551-0010	South Face - East end at corner (scaffolding level)	2/6/09	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST16-2/6/09	030903551-0011	East Face - North end at corner (scaffolding level)	2/6/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST17-2/6/09	030903551-0012	North Face - West end at corner (scaffolding level)	2/6/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/7/09	< 13.00	No	No		
ASBESTOS-ST1-2/7/09	030903718-0001	Southwest Area (sidewalk bridge level)	2/7/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST2-2/7/09	030903718-0002	Southeast Area (sidewalk bridge level)	2/7/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST4-2/7/09	030903718-0003	Northwest Area (street-level)	2/7/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST5-2/7/09	030903718-0004	Firehouse #10 (roof level)	2/7/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST10-2/7/09	030903718-0005	North Side Sidewalk Bridge	2/7/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST11-2/7/09	030903718-0006	90 Trinity Place (roof level)	2/7/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST12-2/7/09	030903718-0007	110 Greenwich Street (roof level)	2/7/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST13-2/7/09	030903718-0008	Marriott Hotel, 38th Floor (roof level)	2/7/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST14-2/7/09	030903718-0009	West Face - South end at corner (scaffolding level)	2/7/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST15-2/7/09	030903718-0010	South Face - East end at corner (scaffolding level)	2/7/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST16-2/7/09	030903718-0011	East Face - North end at corner (scaffolding level)	2/7/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST17-2/7/09	030903718-0012	North Face - West end at corner (scaffolding level)	2/7/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST1-2/8/09	030903712-0001	Southwest Area (sidewalk bridge level)	2/8/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST2-2/8/09	030903712-0002	Southeast Area (sidewalk bridge level)	2/8/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST4-2/8/09	030903712-0003	Northwest Area (street-level)	2/8/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST5-2/8/09	030903712-0004	Firehouse #10 (roof level)	2/8/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST10-2/8/09	030903712-0005	North Side Sidewalk Bridge	2/8/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST11-2/8/09	030903712-0006	90 Trinity Place (roof level)	2/8/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST12-2/8/09	030903712-0007	110 Greenwich Street (roof level)	2/8/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST13-2/8/09	030903712-0008	Marriott Hotel, 38th Floor (roof level)	2/8/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST14-2/8/09	030903712-0009	West Face - South end at corner (scaffolding level)	2/8/09	1	3.310	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST15-2/8/09	030903712-0010	South Face - East end at corner (scaffolding level)	2/8/09	1	3.320	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST16-2/8/09	030903712-0011	East Face - North end at corner (scaffolding level)	2/8/09	1	3.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		
ASBESTOS-ST17-2/8/09	030903712-0012	North Face - West end at corner (scaffolding level)	2/8/09	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/9/09	< 13.00	No	No		