

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
										EPA Site Specific Trigger Levels				
ASBESTOS-ST1-2/9/07	030704426-0001	Southwest Area (sidewalk bridge level)	2/9/07	1	3.05	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST2-2/9/07	030704426-0002	Southeast Area (sidewalk bridge level)	2/9/07	1	3.04	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST4-2/9/07	030704426-0003	Northwest Area (street-level)	2/9/07	1	3.02	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST5-2/9/07	030704426-0004	Firehouse #10 (roof level)	2/9/07	1	3.01	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST10-2/9/07	030704426-0005	North Side Sidewalk Bridge	2/9/07	1	3.04	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST11-2/9/07	030704426-0006	90 Trinity Place (roof level)	2/9/07	1	3.04	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST12-2/9/07	030704426-0007	110 Greenwich Street (roof level)	2/9/07	1	3.07	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST13-2/9/07	030704426-0008	Marriott Hotel, 38th Floor (roof level)	2/9/07	1	3.07	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST14-2/9/07	030704426-0009	West Face - South end at corner (scaffolding level)	2/9/07	1	2.93	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST15-2/9/07	030704426-0010	South Face - East end at corner (scaffolding level)	2/9/07	1	3.04	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST16-2/9/07	030704426-0011	East Face - North end at corner (scaffolding level)	2/9/07	1	3.03	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST17-2/9/07	030704426-0012	North Face - West end at corner (scaffolding level)	2/9/07	1	2.93	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST1-2/10/07	030704424-0001	Southwest Area (sidewalk bridge level)	2/10/07	1	2.91	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST2-2/10/07	030704424-0002	Southeast Area (sidewalk bridge level)	2/10/07	1	3.04	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 15.00	No	No		
ASBESTOS-ST4-2/10/07	030704424-0003	Northwest Area (street-level)	2/10/07	1	3.21	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 15.00	No	No		
ASBESTOS-ST5-2/10/07	030704424-0004	Firehouse #10 (roof level)	2/10/07	1	3.03	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST10-2/10/07	030704424-0005	North Side Sidewalk Bridge	2/10/07	1	3.08	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 15.00	No	No		
ASBESTOS-ST11-2/10/07	030704424-0006	90 Trinity Place (roof level)	2/10/07	1	3.02	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST12-2/10/07	030704424-0007	110 Greenwich Street (roof level)	2/10/07	1	2.97	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST13-2/10/07	030704424-0008	Marriott Hotel, 38th Floor (roof level)	2/10/07	1	2.93	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST14-2/10/07	030704424-0009	West Face - South end at corner (scaffolding level)	2/10/07	1	3.04	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 15.00	No	No		
ASBESTOS-ST15-2/10/07	030704424-0010	South Face - East end at corner (scaffolding level)	2/10/07	1	3.01	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST16-2/10/07	030704424-0011	East Face - North end at corner (scaffolding level)	2/10/07	1	3.04	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 15.00	No	No		
ASBESTOS-ST17-2/10/07	030704424-0012	North Face - West end at corner (scaffolding level)	2/10/07	1	3.07	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 15.00	No	No		
ASBESTOS-ST1-2/11/07	030704425-0001	Southwest Area (sidewalk bridge level)	2/11/07	1	3.03	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST2-2/11/07	030704425-0002	Southeast Area (sidewalk bridge level)	2/11/07	1	3.04	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST4-2/11/07	030704425-0003	Northwest Area (street-level)	2/11/07	1	3.16	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST5-2/11/07	030704425-0004	Firehouse #10 (roof level)	2/11/07	1	3.02	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST10-2/11/07	030704425-0005	North Side Sidewalk Bridge	2/11/07	1	3.03	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST11-2/11/07	030704425-0006	90 Trinity Place (roof level)	2/11/07	1	3.02	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST12-2/11/07	030704425-0007	110 Greenwich Street (roof level)	2/11/07	1	3.07	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST13-2/11/07	030704425-0008	Marriott Hotel, 38th Floor (roof level)	2/11/07	1	3.05	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST14-2/11/07	030704425-0009	West Face - South end at corner (scaffolding level)	2/11/07	1	3.04	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST15-2/11/07	030704425-0010	South Face - East end at corner (scaffolding level)	2/11/07	1	3.02	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST16-2/11/07	030704425-0011	East Face - North end at corner (scaffolding level)	2/11/07	1	3.02	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST17-2/11/07	030704425-0012	North Face - West end at corner (scaffolding level)	2/11/07	1	3.07	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/12/07	< 13.00	No	No		
ASBESTOS-ST1-2/12/07	030704543-0001	Southwest Area (sidewalk bridge level)	2/12/07	1	3.11	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST2-2/12/07	030704543-0002	Southeast Area (sidewalk bridge level)	2/12/07	1	2.95	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST4-2/12/07	030704543-0003	Northwest Area (street-level)	2/12/07	1	2.95	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST5-2/12/07	030704543-0004	Firehouse #10 (roof level)	2/12/07	1	3.02	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST10-2/12/07	030704543-0005	North Side Sidewalk Bridge	2/12/07	1	3.10	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST11-2/12/07	030704543-0006	90 Trinity Place (roof level)	2/12/07	1	2.90	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST12-2/12/07	030704543-0007	110 Greenwich Street (roof level)	2/12/07	1	3.11	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST13-2/12/07	030704543-0008	Marriott Hotel, 38th Floor (roof level)	2/12/07	1	3.02	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST14-2/12/07	030704543-0009	West Face - South end at corner (scaffolding level)	2/12/07	1	3.02	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST15-2/12/07	030704543-0010	South Face - East end at corner (scaffolding level)	2/12/07	1	3.07	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST16-2/12/07	030704543-0011	East Face - North end at corner (scaffolding level)	2/12/07	1	3.02	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		
ASBESTOS-ST17-2/12/07	030704543-0012	North Face - West end at corner (scaffolding level)	2/12/07	1	3.04	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/07	< 13.00	No	No		