

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-2/20/09	030905015-0001	Southwest Area (sidewalk bridge level)	2/20/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST2-2/20/09	030905015-0002	Southeast Area (sidewalk bridge level)	2/20/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST4-2/20/09	030905015-0003	Northwest Area (street-level)	2/20/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST5-2/20/09	030905015-0004	Firehouse #10 (roof level)	2/20/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST10-2/20/09	030905015-0005	North Side Sidewalk Bridge	2/20/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST11-2/20/09	030905015-0006	90 Trinity Place (roof level)	2/20/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST12-2/20/09	030905015-0007	110 Greenwich Street (roof level)	2/20/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST13-2/20/09	030905015-0008	Marriott Hotel, 38th Floor (roof level)	2/20/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST14-2/20/09	030905015-0009	West Face - South end at corner (scaffolding level)	2/20/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST15-2/20/09	030905015-0010	South Face - East end at corner (scaffolding level)	2/20/09	1	2.860	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST16-2/20/09	030905015-0011	East Face - North end at corner (scaffolding level)	2/20/09	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST17-2/20/09	030905015-0012	North Face - West end at corner (scaffolding level)	2/20/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/09	< 13.00		No	No	
ASBESTOS-ST1-2/21/09	030905109-0001	Southwest Area (sidewalk bridge level)	2/21/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST2-2/21/09	030905109-0002	Southeast Area (sidewalk bridge level)	2/21/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST4-2/21/09	030905109-0003	Northwest Area (street-level)	2/21/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST5-2/21/09	030905109-0004	Firehouse #10 (roof level)	2/21/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST10-2/21/09	030905109-0005	North Side Sidewalk Bridge	2/21/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST11-2/21/09	030905109-0006	90 Trinity Place (roof level)	2/21/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST12-2/21/09	030905109-0007	110 Greenwich Street (roof level)	2/21/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST13-2/21/09	030905109-0008	Marriott Hotel, 38th Floor (roof level)	2/21/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST14-2/21/09	030905109-0009	West Face - South end at corner (scaffolding level)	2/21/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST15-2/21/09	030905109-0010	South Face - East end at corner (scaffolding level)	2/21/09	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST16-2/21/09	030905109-0011	East Face - North end at corner (scaffolding level)	2/21/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST17-2/21/09	030905109-0012	North Face - West end at corner (scaffolding level)	2/21/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST1-2/22/09	030905121-0001	Southwest Area (sidewalk bridge level)	2/22/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST2-2/22/09	030905121-0002	Southeast Area (sidewalk bridge level)	2/22/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST4-2/22/09	030905121-0003	Northwest Area (street-level)	2/22/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST5-2/22/09	030905121-0004	Firehouse #10 (roof level)	2/22/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST10-2/22/09	030905121-0005	North Side Sidewalk Bridge	2/22/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST11-2/22/09	030905121-0006	90 Trinity Place (roof level)	2/22/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST12-2/22/09	030905121-0007	110 Greenwich Street (roof level)	2/22/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST13-2/22/09	030905121-0008	Marriott Hotel, 38th Floor (roof level)	2/22/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST14-2/22/09	030905121-0009	West Face - South end at corner (scaffolding level)	2/22/09	1	3.340	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST15-2/22/09	030905121-0010	South Face - East end at corner (scaffolding level)	2/22/09	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST16-2/22/09	030905121-0011	East Face - North end at corner (scaffolding level)	2/22/09	1	3.220	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST17-2/22/09	030905121-0012	North Face - West end at corner (scaffolding level)	2/22/09	1	3.270	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST1-2/23/09	030905171-0001	Southwest Area (sidewalk bridge level)	2/23/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST2-2/23/09	030905171-0002	Southeast Area (sidewalk bridge level)	2/23/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST4-2/23/09	030905171-0003	Northwest Area (street-level)	2/23/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST5-2/23/09	030905171-0004	Firehouse #10 (roof level)	2/23/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST10-2/23/09	030905171-0005	North Side Sidewalk Bridge	2/23/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST11-2/23/09	030905171-0006	90 Trinity Place (roof level)	2/23/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST12-2/23/09	030905171-0007	110 Greenwich Street (roof level)	2/23/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST13-2/23/09	030905171-0008	Marriott Hotel, 38th Floor (roof level)	2/23/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST14-2/23/09	030905171-0009	West Face - South end at corner (scaffolding level)	2/23/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST15-2/23/09	030905171-0010	South Face - East end at corner (scaffolding level)	2/23/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST16-2/23/09	030905171-0011	East Face - North end at corner (scaffolding level)	2/23/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST17-2/23/09	030905171-0012	North Face - West end at corner (scaffolding level)	2/23/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/24/09	< 13.00		No	No	
ASBESTOS-ST1-2/24/09	030905273-0001	Southwest Area (sidewalk bridge level)	2/24/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 13.00		No	No	
ASBESTOS-ST2-2/24/09	030905273-0002	Southeast Area (sidewalk bridge level)	2/24/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 15.00		No	No	
ASBESTOS-ST4-2/24/09	030905273-0003	Northwest Area (street-level)	2/24/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 13.00		No	No	
ASBESTOS-ST5-2/24/09	030905273-0004	Firehouse #10 (roof level)	2/24/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 15.00		No	No	
ASBESTOS-ST10-2/24/09	030905273-0005	North Side Sidewalk Bridge	2/24/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 15.00		No	No	
ASBESTOS-ST11-2/24/09	030905273-0006	90 Trinity Place (roof level)	2/24/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 15.00		No	No	
ASBESTOS-ST12-2/24/09	030905273-0007	110 Greenwich Street (roof level)	2/24/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 13.00		No	No	
ASBESTOS-ST13-2/24/09	030905273-0008	Marriott Hotel, 38th Floor (roof level)	2/24/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 13.00		No	No	
ASBESTOS-ST14-2/24/09	030905273-0009	West Face - South end at corner (scaffolding level)	2/24/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 15.00		No	No	
ASBESTOS-ST15-2/24/09	030905273-0010	South Face - East end at corner (scaffolding level)	2/24/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 13.00		No	No	
ASBESTOS-ST16-2/24/09	030905273-0011	East Face - North end at corner (scaffolding level)	2/24/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 15.00		No	No	
ASBESTOS-ST17-2/24/09	030905273-0012	North Face - West end at corner (scaffolding level)	2/24/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/25/09	< 13.00		No	No	