

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
<b>Target Air Quality Levels</b>														
<b>EPA Site Specific Trigger Levels</b>														
ASBESTOS-ST1-2/26/08	030804918-0001	Southwest Area (sidewalk bridge level)	2/26/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST2-2/26/08	030804918-0002	Southeast Area (sidewalk bridge level)	2/26/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST4-2/26/08	030804918-0003	Northwest Area (street-level)	2/26/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST5-2/26/08	030804918-0004	Firehouse #10 (roof level)	2/26/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST10-2/26/08	030804918-0005	North Side Sidewalk Bridge	2/26/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST11-2/26/08	030804918-0006	90 Trinity Place (roof level)	2/26/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST12-2/26/08	030804918-0007	110 Greenwich Street (roof level)	2/26/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST13-2/26/08	030804918-0008	Marriott Hotel, 38th Floor (roof level)	2/26/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST14-2/26/08	030804918-0009	West Face - South end at corner (scaffolding level)	2/26/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST15-2/26/08	030804918-0010	South Face - East end at corner (scaffolding level)	2/26/08	1	2.640	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST16-2/26/08	030804918-0011	East Face - North end at corner (scaffolding level)	2/26/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST17-2/26/08	030804918-0012	North Face - West end at corner (scaffolding level)	2/26/08	1	3.260	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/27/08	< 13.00	No	No		
ASBESTOS-ST1-2/27/08	030805005-0001	Southwest Area (sidewalk bridge level)	2/27/08	1	2.770	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 13.00	No	No		
ASBESTOS-ST2-2/27/08	030805005-0002	Southeast Area (sidewalk bridge level)	2/27/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 15.00	No	No		
ASBESTOS-ST4-2/27/08	030805005-0003	Northwest Area (street-level)	2/27/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 13.00	No	No		
ASBESTOS-ST5-2/27/08	030805005-0004	Firehouse #10 (roof level)	2/27/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 15.00	No	No		
ASBESTOS-ST10-2/27/08	030805005-0005	North Side Sidewalk Bridge	2/27/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 15.00	No	No		
ASBESTOS-ST11-2/27/08	030805005-0006	90 Trinity Place (roof level)	2/27/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 15.00	No	No		
ASBESTOS-ST12-2/27/08	030805005-0007	110 Greenwich Street (roof level)	2/27/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 13.00	No	No		
ASBESTOS-ST13-2/27/08	030805005-0008	Marriott Hotel, 38th Floor (roof level)	2/27/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 13.00	No	No		
ASBESTOS-ST14-2/27/08	030805005-0009	West Face - South end at corner (scaffolding level)	2/27/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 13.00	No	No		
ASBESTOS-ST15-2/27/08	030805005-0010	South Face - East end at corner (scaffolding level)	2/27/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 15.00	No	No		
ASBESTOS-ST16-2/27/08	030805005-0011	East Face - North end at corner (scaffolding level)	2/27/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 15.00	No	No		
ASBESTOS-ST17-2/27/08	030805005-0012	North Face - West end at corner (scaffolding level)	2/27/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/28/08	< 13.00	No	No		
ASBESTOS-ST1-2/28/08	030805117-0001	Southwest Area (sidewalk bridge level)	2/28/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 15.00	No	No		
ASBESTOS-ST2-2/28/08	030805117-0002	Southeast Area (sidewalk bridge level)	2/28/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 13.00	No	No		
ASBESTOS-ST4-2/28/08	030805117-0003	Northwest Area (street-level)	2/28/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 13.00	No	No		
ASBESTOS-ST5-2/28/08	030805117-0004	Firehouse #10 (roof level)	2/28/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 13.00	No	No		
ASBESTOS-ST10-2/28/08	030805117-0005	North Side Sidewalk Bridge	2/28/08	1	3.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 15.00	No	No		
ASBESTOS-ST11-2/28/08	030805117-0006	90 Trinity Place (roof level)	2/28/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 15.00	No	No		
ASBESTOS-ST12-2/28/08	030805117-0007	110 Greenwich Street (roof level)	2/28/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 15.00	No	No		
ASBESTOS-ST13-2/28/08	030805117-0008	Marriott Hotel, 38th Floor (roof level)	2/28/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 15.00	No	No		
ASBESTOS-ST14-2/28/08	030805117-0009	West Face - South end at corner (scaffolding level)	2/28/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 13.00	No	No		
ASBESTOS-ST15-2/28/08	030805117-0010	South Face - East end at corner (scaffolding level)	2/28/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 15.00	No	No		
ASBESTOS-ST16-2/28/08	030805117-0011	East Face - North end at corner (scaffolding level)	2/28/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 13.00	No	No		
ASBESTOS-ST17-2/28/08	030805117-0012	North Face - West end at corner (scaffolding level)	2/28/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/29/08	< 13.00	No	No		
ASBESTOS-ST1-2/29/08	030805222-0001	Southwest Area (sidewalk bridge level)	2/29/08	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST2-2/29/08	030805222-0002	Southeast Area (sidewalk bridge level)	2/29/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST4-2/29/08	030805222-0003	Northwest Area (street-level)	2/29/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST5-2/29/08	030805222-0004	Firehouse #10 (roof level)	2/29/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST10-2/29/08	030805222-0005	North Side Sidewalk Bridge	2/29/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST11-2/29/08	030805222-0006	90 Trinity Place (roof level)	2/29/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST12-2/29/08	030805222-0007	110 Greenwich Street (roof level)	2/29/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST13-2/29/08	030805222-0008	Marriott Hotel, 38th Floor (roof level)	2/29/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST14-2/29/08	030805222-0009	West Face - South end at corner (scaffolding level)	2/29/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST15-2/29/08	030805222-0010	South Face - East end at corner (scaffolding level)	2/29/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST16-2/29/08	030805222-0011	East Face - North end at corner (scaffolding level)	2/29/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		
ASBESTOS-ST17-2/29/08	030805222-0012	North Face - West end at corner (scaffolding level)	2/29/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/1/08	< 13.00	No	No		