

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-2/28/09	030905689-0001	Southwest Area (sidewalk bridge level)	2/28/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST2-2/28/09	030905689-0002	Southeast Area (sidewalk bridge level)	2/28/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST4-2/28/09	030905689-0003	Northwest Area (street-level)	2/28/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST5-2/28/09	030905689-0004	Firehouse #10 (roof level)	2/28/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST10-2/28/09	030905689-0005	North Side Sidewalk Bridge	2/28/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST11-2/28/09	030905689-0006	90 Trinity Place (roof level)	2/28/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST12-2/28/09	030905689-0007	110 Greenwich Street (roof level)	2/28/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST13-2/28/09	030905689-0008	Marriott Hotel, 38th Floor (roof level)	2/28/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST14-2/28/09	030905689-0009	West Face - South end at corner (scaffolding level)	2/28/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST15-2/28/09	030905689-0010	South Face - East end at corner (scaffolding level)	2/28/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST16-2/28/09	030905689-0011	East Face - North end at corner (scaffolding level)	2/28/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST17-2/28/09	030905689-0012	North Face - West end at corner (scaffolding level)	2/28/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST1-3/1/09	030905687-0001	Southwest Area (sidewalk bridge level)	3/1/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST2-3/1/09	030905687-0002	Southeast Area (sidewalk bridge level)	3/1/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST4-3/1/09	030905687-0003	Northwest Area (street-level)	3/1/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST5-3/1/09	030905687-0004	Firehouse #10 (roof level)	3/1/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST10-3/1/09	030905687-0005	North Side Sidewalk Bridge	3/1/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST11-3/1/09	030905687-0006	90 Trinity Place (roof level)	3/1/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST12-3/1/09	030905687-0007	110 Greenwich Street (roof level)	3/1/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST13-3/1/09	030905687-0008	Marriott Hotel, 38th Floor (roof level)	3/1/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/2/09	< 13.00	No	No		
ASBESTOS-ST14-3/1/09	030905765-0001	West Face - South end at corner (scaffolding level)	3/1/09	1	6.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 19.00	No	No	Note 1	
ASBESTOS-ST15-3/1/09	030905765-0002	South Face - East end at corner (scaffolding level)	3/1/09	1	6.450	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 19.00	No	No	Note 1	
ASBESTOS-ST16-3/1/09	030905765-0003	East Face - North end at corner (scaffolding level)	3/1/09	1	6.330	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 19.00	No	No	Note 1	
ASBESTOS-ST17-3/1/09	030905765-0004	North Face - West end at corner (scaffolding level)	3/1/09	1	6.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 19.00	No	No	Note 1	
ASBESTOS-ST1-3/2/09	030905760-0001	Southwest Area (sidewalk bridge level)	3/2/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 13.00	No	No		
ASBESTOS-ST2-3/2/09	030905760-0002	Southeast Area (sidewalk bridge level)	3/2/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 13.00	No	No		
ASBESTOS-ST4-3/2/09	030905760-0003	Northwest Area (street-level)	3/2/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 13.00	No	No		
ASBESTOS-ST5-3/2/09	030905760-0004	Firehouse #10 (roof level)	3/2/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 13.00	No	No		
ASBESTOS-ST10-3/2/09	030905760-0005	North Side Sidewalk Bridge	3/2/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 13.00	No	No		
ASBESTOS-ST11-3/2/09	030905760-0006	90 Trinity Place (roof level)	3/2/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 15.00	No	No		
ASBESTOS-ST12-3/2/09	030905760-0007	110 Greenwich Street (roof level)	3/2/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 13.00	No	No		
ASBESTOS-ST13-3/02/09	030905760-0008	Marriott Hotel, 38th Floor (roof level)	3/2/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/3/09	< 13.00	No	No		
ASBESTOS-ST1-3/3/09	030905850-0001	Southwest Area (sidewalk bridge level)	3/3/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 15.00	No	No		
ASBESTOS-ST2-3/3/09	030905850-0002	Southeast Area (sidewalk bridge level)	3/3/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 15.00	No	No		
ASBESTOS-ST4-3/3/09	030905850-0003	Northwest Area (street-level)	3/3/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 13.00	No	No		
ASBESTOS-ST5-3/3/09	030905850-0004	Firehouse #10 (roof level)	3/3/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 13.00	No	No		
ASBESTOS-ST10-3/3/09	030905850-0005	North Side Sidewalk Bridge	3/3/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 13.00	No	No		
ASBESTOS-ST11-3/3/09	030905850-0006	90 Trinity Place (roof level)	3/3/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 13.00	No	No		
ASBESTOS-ST12-3/3/09	030905850-0007	110 Greenwich Street (roof level)	3/3/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 13.00	No	No		
ASBESTOS-ST13-3/3/09	030905850-0008	Marriott Hotel, 38th Floor (roof level)	3/3/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 13.00	No	No		
ASBESTOS-ST14-3/3/09	030905850-0009	West Face - South end at corner (scaffolding level)	3/3/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 13.00	No	No		
ASBESTOS-ST15-3/3/09	030905850-0010	South Face - East end at corner (scaffolding level)	3/3/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 13.00	No	No		
ASBESTOS-ST16-3/3/09	030905850-0011	East Face - North end at corner (scaffolding level)	3/3/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 13.00	No	No		
ASBESTOS-ST17-3/3/09	030905850-0012	North Face - West end at corner (scaffolding level)	3/3/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/4/09	< 13.00	No	No		

Note:

- The asbestos sample volumes at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on March 1, 2009 represent 2 consecutive 24-hour periods as samples could not be retrieved on March 2, 2009 due to hazardous conditions on the scaffolding posed by winter weather conditions.
- Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on March 2, 2009 were not accessible due to hazardous conditions on the scaffolding posed by winter weather conditions. Refer to samples collected on March 1, 2009 which reflect 2 consecutive 24-hour periods.