

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-4/7/06	030610791-0001	Southwest Area (sidewalk bridge level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST2-4/7/06	030610791-0002	Southeast Area (sidewalk bridge level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST4-4/7/06	030610791-0003	Northwest Area (street-level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST5-4/7/06	030610791-0004	Firehouse #10 (roof level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST10-4/7/06	030610791-0005	North Side Sidewalk Bridge	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST11-4/7/06	030610791-0006	90 Trinity Place (roof level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST12-4/7/06	030610791-0007	110 Greenwich Street (roof level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST13-4/7/06	030610791-0008	Marriott Hotel, 38th Floor (roof level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST14-4/7/06	030610791-0009	West Face - South end at corner (scaffolding level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST15-4/7/06	030610791-0010	South Face - East end at corner (scaffolding level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST16-4/7/06	030610791-0011	East Face - North end at corner (scaffolding level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST17-4/7/06	030610791-0012	North Face - West end at corner (scaffolding level)	4/7/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST1-4/8/06	030610789-0001	Southwest Area (sidewalk bridge level)	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST2-4/8/06	030610789-0002	Southeast Area (sidewalk bridge level)	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST4-4/8/06	030610789-0003	Northwest Area (street-level)	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST5-4/8/06	030610789-0004	Firehouse #10 (roof level)	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST10-4/8/06	030610789-0005	North Side Sidewalk Bridge	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST11-4/8/06	030610789-0006	90 Trinity Place (roof level)	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST12-4/8/06	030610789-0007	110 Greenwich Street (roof level)	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST13-4/8/06	030610789-0008	Marriott Hotel, 38th Floor (roof level)	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST14-4/8/06	030610789-0009	West Face - South end at corner (scaffolding level)	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST15-4/8/06	030610789-0010	South Face - East end at corner (scaffolding level)	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST17-4/8/06	030610789-0012	North Face - West end at corner (scaffolding level)	4/8/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST1-4/9/06	030610787-0001	Southwest Area (sidewalk bridge level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST2-4/9/06	030610787-0002	Southeast Area (sidewalk bridge level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST4-4/9/06	030610787-0003	Northwest Area (street-level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST5-4/9/06	030610787-0004	Firehouse #10 (roof level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST10-4/9/06	030610787-0005	North Side Sidewalk Bridge	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST11-4/9/06	030610787-0006	90 Trinity Place (roof level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST12-4/9/06	030610787-0007	110 Greenwich Street (roof level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST13-4/9/06	030610787-0008	Marriott Hotel, 38th Floor (roof level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST14-4/9/06	030610787-0009	West Face - South end at corner (scaffolding level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST15-4/9/06	030610787-0010	South Face - East end at corner (scaffolding level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST16-4/9/06	030610787-0011	East Face - North end at corner (scaffolding level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST17-4/9/06	030610787-0012	North Face - West end at corner (scaffolding level)	4/9/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/10/06	< 13.00		No	No	
ASBESTOS-ST1-4/10/06	030610933-0001	Southwest Area (sidewalk bridge level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST2-4/10/06	030610933-0002	Southeast Area (sidewalk bridge level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST4-4/10/06	030610933-0003	Northwest Area (street-level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST5-4/10/06	030610933-0004	Firehouse #10 (roof level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST10-4/10/06	030610933-0005	North Side Sidewalk Bridge	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST11-4/10/06	030610933-0006	90 Trinity Place (roof level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST12-4/10/06	030610933-0007	110 Greenwich Street (roof level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST13-4/10/06	030610933-0008	Marriott Hotel, 38th Floor (roof level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST14-4/10/06	030610933-0009	West Face - South end at corner (scaffolding level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST15-4/10/06	030610933-0010	South Face - East end at corner (scaffolding level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST16-4/10/06	030610933-0011	East Face - North end at corner (scaffolding level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	
ASBESTOS-ST17-4/10/06	030610933-0012	North Face - West end at corner (scaffolding level)	4/10/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/11/06	< 13.00		No	No	

Note:

1. Asbestos sample at Station 16 (East Face - North end at corner [scaffolding level]) on April 8, 2006 was not available for analysis on account of filter damage.