

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA			
										70			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-4/10/09	030909327-0001	Southwest Area (sidewalk bridge level)	4/10/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST2-4/10/09	030909327-0002	Southeast Area (sidewalk bridge level)	4/10/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST4-4/10/09	030909327-0003	Northwest Area (street-level)	4/10/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST5-4/10/09	030909327-0004	Firehouse #10 (roof level)	4/10/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST10-4/10/09	030909327-0005	North Side Sidewalk Bridge	4/10/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST11-4/10/09	030909327-0006	90 Trinity Place (roof level)	4/10/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST12-4/10/09	030909327-0007	110 Greenwich Street (roof level)	4/10/09	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST13-4/10/09	030909327-0008	Marriott Hotel, 38th Floor (roof level)	4/10/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 15.00	No	No	
ASBESTOS-ST14-4/10/09	030909327-0009	West Face - South end at corner (scaffolding level)	4/10/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST15-4/10/09	030909327-0010	South Face - East end at corner (scaffolding level)	4/10/09	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST16-4/10/09	030909327-0011	East Face - North end at corner (scaffolding level)	4/10/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST17-4/10/09	030909327-0012	North Face - West end at corner (scaffolding level)	4/10/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST1-4/11/09	030909329-0001	Southwest Area (sidewalk bridge level)	4/11/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST2-4/11/09	030909329-0002	Southeast Area (sidewalk bridge level)	4/11/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST4-4/11/09	030909329-0003	Northwest Area (street-level)	4/11/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST5-4/11/09	030909329-0004	Firehouse #10 (roof level)	4/11/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST10-4/11/09	030909329-0005	North Side Sidewalk Bridge	4/11/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST11-4/11/09	030909329-0006	90 Trinity Place (roof level)	4/11/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST12-4/11/09	030909329-0007	110 Greenwich Street (roof level)	4/11/09	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST13-4/11/09	030909329-0008	Marriott Hotel, 38th Floor (roof level)	4/11/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST14-4/11/09	030909329-0009	West Face - South end at corner (scaffolding level)	4/11/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST15-4/11/09	030909329-0010	South Face - East end at corner (scaffolding level)	4/11/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST16-4/11/09	030909329-0011	East Face - North end at corner (scaffolding level)	4/11/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST17-4/11/09	030909329-0012	North Face - West end at corner (scaffolding level)	4/11/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST1-4/12/09	030909332-0001	Southwest Area (sidewalk bridge level)	4/12/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST2-4/12/09	030909332-0002	Southeast Area (sidewalk bridge level)	4/12/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST4-4/12/09	030909332-0003	Northwest Area (street-level)	4/12/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST5-4/12/09	030909332-0004	Firehouse #10 (roof level)	4/12/09	1	3.240	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST10-4/12/09	030909332-0005	North Side Sidewalk Bridge	4/12/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST11-4/12/09	030909332-0006	90 Trinity Place (roof level)	4/12/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST12-4/12/09	030909332-0007	110 Greenwich Street (roof level)	4/12/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST13-4/12/09	030909332-0008	Marriott Hotel, 38th Floor (roof level)	4/12/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST14-4/12/09	030909332-0009	West Face - South end at corner (scaffolding level)	4/12/09	1	3.200	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST15-4/12/09	030909332-0010	South Face - East end at corner (scaffolding level)	4/12/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST16-4/12/09	030909332-0011	East Face - North end at corner (scaffolding level)	4/12/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	
ASBESTOS-ST17-4/12/09	030909332-0012	North Face - West end at corner (scaffolding level)	4/12/09	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/13/09	< 13.00	No	No	