

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels											Air Quality Levels	Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels													
											NA		
											70		
ASBESTOS-ST1-4/28/09	030910801-0001	Southwest Area (sidewalk bridge level)	4/28/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST2-4/28/09	030910801-0002	Southeast Area (sidewalk bridge level)	4/28/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST4-4/28/09	030910801-0003	Northwest Area (street-level)	4/28/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST5-4/28/09	030910801-0004	Firehouse #10 (roof level)	4/28/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST10-4/28/09	030910801-0005	North Side Sidewalk Bridge	4/28/09	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST11-4/28/09	030910801-0006	90 Trinity Place (roof level)	4/28/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST12-4/28/09	030910801-0007	110 Greenwich Street (roof level)	4/28/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST13-4/28/09	030910801-0008	Marriott Hotel, 38th Floor (roof level)	4/28/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST14-4/28/09	030910801-0009	West Face - South end at corner (scaffolding level)	4/28/09	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	13.00	No	No	
ASBESTOS-ST15-4/28/09	030910801-0010	South Face - East end at corner (scaffolding level)	4/28/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST16-4/28/09	030910801-0011	East Face - North end at corner (scaffolding level)	4/28/09	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST17-4/28/09	030910801-0012	North Face - West end at corner (scaffolding level)	4/28/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/29/09	< 13.00	No	No	
ASBESTOS-ST1-4/29/09	030910948-0001	Southwest Area (sidewalk bridge level)	4/29/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	13.00	No	No	
ASBESTOS-ST2-4/29/09	030910948-0002	Southeast Area (sidewalk bridge level)	4/29/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST4-4/29/09	030910948-0003	Northwest Area (street-level)	4/29/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST5-4/29/09	030910948-0004	Firehouse #10 (roof level)	4/29/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST10-4/29/09	030910948-0005	North Side Sidewalk Bridge	4/29/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST11-4/29/09	030910948-0006	90 Trinity Place (roof level)	4/29/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST12-4/29/09	030910948-0007	110 Greenwich Street (roof level)	4/29/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST13-4/29/09	030910948-0008	Marriott Hotel, 38th Floor (roof level)	4/29/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST14-4/29/09	030910948-0009	West Face - South end at corner (scaffolding level)	4/29/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST15-4/29/09	030910948-0010	South Face - East end at corner (scaffolding level)	4/29/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST16-4/29/09	030910948-0011	East Face - North end at corner (scaffolding level)	4/29/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST17-4/29/09	030910948-0012	North Face - West end at corner (scaffolding level)	4/29/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/09	< 13.00	No	No	
ASBESTOS-ST1-4/30/09	030911082-0001	Southwest Area (sidewalk bridge level)	4/30/09	1	3.270	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 15.00	No	No	
ASBESTOS-ST2-4/30/09	030911082-0002	Southeast Area (sidewalk bridge level)	4/30/09	1	3.220	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 15.00	No	No	
ASBESTOS-ST4-4/30/09	030911082-0003	Northwest Area (street-level)	4/30/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 13.00	No	No	
ASBESTOS-ST5-4/30/09	030911082-0004	Firehouse #10 (roof level)	4/30/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 13.00	No	No	
ASBESTOS-ST10-4/30/09	030911082-0005	North Side Sidewalk Bridge	4/30/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 13.00	No	No	
ASBESTOS-ST11-4/30/09	030911082-0006	90 Trinity Place (roof level)	4/30/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 13.00	No	No	
ASBESTOS-ST12-4/30/09	030911082-0007	110 Greenwich Street (roof level)	4/30/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 15.00	No	No	
ASBESTOS-ST13-4/30/09	030911082-0008	Marriott Hotel, 38th Floor (roof level)	4/30/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 13.00	No	No	
ASBESTOS-ST14-4/30/09	030911082-0009	West Face - South end at corner (scaffolding level)	4/30/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 15.00	No	No	
ASBESTOS-ST15-4/30/09	030911082-0010	South Face - East end at corner (scaffolding level)	4/30/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 13.00	No	No	
ASBESTOS-ST16-4/30/09	030911082-0011	East Face - North end at corner (scaffolding level)	4/30/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 13.00	No	No	
ASBESTOS-ST17-4/30/09	030911082-0012	North Face - West end at corner (scaffolding level)	4/30/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/09	< 13.00	No	No	
ASBESTOS-ST1-5/1/09	030911107-0001	Southwest Area (sidewalk bridge level)	5/1/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST2-5/1/09	030911107-0002	Southeast Area (sidewalk bridge level)	5/1/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST4-5/1/09	030911107-0003	Northwest Area (street-level)	5/1/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST5-5/1/09	030911107-0004	Firehouse #10 (roof level)	5/1/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST10-5/1/09	030911107-0005	North Side Sidewalk Bridge	5/1/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST11-5/1/09	030911107-0006	90 Trinity Place (roof level)	5/1/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST12-5/1/09	030911107-0007	110 Greenwich Street (roof level)	5/1/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST13-5/1/09	030911107-0008	Marriott Hotel, 38th Floor (roof level)	5/1/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST14-5/1/09	030911107-0009	West Face - South end at corner (scaffolding level)	5/1/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST15-5/1/09	030911107-0010	South Face - East end at corner (scaffolding level)	5/1/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST16-5/1/09	030911107-0011	East Face - North end at corner (scaffolding level)	5/1/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	
ASBESTOS-ST17-5/1/09	030911107-0012	North Face - West end at corner (scaffolding level)	5/1/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/09	< 13.00	No	No	