

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-4/29/08	030813077-0001	Southwest Area (sidewalk bridge level)	4/29/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 15.00	No	No	
ASBESTOS-ST4-4/29/08	030813077-0003	Northwest Area (street-level)	4/29/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 13.00	No	No	
ASBESTOS-ST5-4/29/08	030813077-0004	Firehouse #10 (roof level)	4/29/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 15.00	No	No	
ASBESTOS-ST10-4/29/08	030813077-0005	North Side Sidewalk Bridge	4/29/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 15.00	No	No	
ASBESTOS-ST11-4/29/08	030813077-0006	90 Trinity Place (roof level)	4/29/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 13.00	No	No	
ASBESTOS-ST12-4/29/08	030813077-0007	110 Greenwich Street (roof level)	4/29/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 15.00	No	No	
ASBESTOS-ST13-4/29/08	030813077-0008	Marriott Hotel, 38th Floor (roof level)	4/29/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 13.00	No	No	
ASBESTOS-ST14-4/29/08	030813077-0009	West Face - South end at corner (scaffolding level)	4/29/08	1	2.890	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 13.00	No	No	
ASBESTOS-ST15-4/29/08	030813077-0010	South Face - East end at corner (scaffolding level)	4/29/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 15.00	No	No	
ASBESTOS-ST16-4/29/08	030813077-0011	East Face - North end at corner (scaffolding level)	4/29/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 15.00	No	No	
ASBESTOS-ST17-4/29/08	030813077-0012	North Face - West end at corner (scaffolding level)	4/29/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/30/08	< 13.00	No	No	
ASBESTOS-ST1-4/30/08	030813220-0001	Southwest Area (sidewalk bridge level)	4/30/08	1	3.350	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST2-4/30/08	030813220-0002	Southeast Area (sidewalk bridge level)	4/30/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST4-4/30/08	030813220-0003	Northwest Area (street-level)	4/30/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST5-4/30/08	030813220-0004	Firehouse #10 (roof level)	4/30/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST10-4/30/08	030813220-0005	North Side Sidewalk Bridge	4/30/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST11-4/30/08	030813220-0006	90 Trinity Place (roof level)	4/30/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST12-4/30/08	030813220-0007	110 Greenwich Street (roof level)	4/30/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST13-4/30/08	030813220-0008	Marriott Hotel, 38th Floor (roof level)	4/30/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST14-4/30/08	030813220-0009	West Face - South end at corner (scaffolding level)	4/30/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST15-4/30/08	030813220-0010	South Face - East end at corner (scaffolding level)	4/30/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST16-4/30/08	030813220-0011	East Face - North end at corner (scaffolding level)	4/30/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	
ASBESTOS-ST17-4/30/08	030813220-0012	North Face - West end at corner (scaffolding level)	4/30/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/08	< 13.00	No	No	

Note:

- Asbestos sample at Station 2 (Southeast Area [sidewalk bridge level]) on April 29, 2008 was not available for analysis. The sample was reported missing by the laboratory.