

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality Levels	Site Specific Trigger Levels	
										70			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-4/30/07	030713536-0001	Southwest Area (sidewalk bridge level)	4/30/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 15.00	No	No	
ASBESTOS-ST2-4/30/07	030713536-0002	Southeast Area (sidewalk bridge level)	4/30/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 13.00	No	No	
ASBESTOS-ST4-4/30/07	030713536-0003	Northwest Area (street-level)	4/30/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 15.00	No	No	
ASBESTOS-ST5-4/30/07	030713536-0004	Firehouse #10 (roof level)	4/30/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 13.00	No	No	
ASBESTOS-ST10-4/30/07	030713536-0005	North Side Sidewalk Bridge	4/30/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 13.00	No	No	
ASBESTOS-ST11-4/30/07	030713536-0006	90 Trinity Place (roof level)	4/30/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 15.00	No	No	
ASBESTOS-ST12-4/30/07	030713536-0007	110 Greenwich Street (roof level)	4/30/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 13.00	No	No	
ASBESTOS-ST13-4/30/07	030713536-0008	Marriott Hotel, 38th Floor (roof level)	4/30/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 15.00	No	No	
ASBESTOS-ST14-4/30/07	030713536-0009	West Face - South end at corner (scaffolding level)	4/30/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 15.00	No	No	
ASBESTOS-ST15-4/30/07	030713536-0010	South Face - East end at corner (scaffolding level)	4/30/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 15.00	No	No	
ASBESTOS-ST16-4/30/07	030713536-0011	East Face - North end at corner (scaffolding level)	4/30/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 13.00	No	No	
ASBESTOS-ST17-4/30/07	030713536-0012	North Face - West end at corner (scaffolding level)	4/30/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/1/07	< 15.00	No	No	
ASBESTOS-ST1-5/1/07	030713726-0001	Southwest Area (sidewalk bridge level)	5/1/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	
ASBESTOS-ST2-5/1/07	030713726-0002	Southeast Area (sidewalk bridge level)	5/1/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	
ASBESTOS-ST4-5/1/07	030713726-0003	Northwest Area (street-level)	5/1/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	
ASBESTOS-ST5-5/1/07	030713726-0004	Firehouse #10 (roof level)	5/1/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	
ASBESTOS-ST10-5/1/07	030713726-0005	North Side Sidewalk Bridge	5/1/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	
ASBESTOS-ST11-5/1/07	030713726-0006	90 Trinity Place (roof level)	5/1/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	
ASBESTOS-ST12-5/1/07	030713726-0007	110 Greenwich Street (roof level)	5/1/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	
ASBESTOS-ST14-5/1/07	030713726-0009	West Face - South end at corner (scaffolding level)	5/1/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	
ASBESTOS-ST15-5/1/07	030713726-0010	South Face - East end at corner (scaffolding level)	5/1/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	
ASBESTOS-ST16-5/1/07	030713726-0011	East Face - North end at corner (scaffolding level)	5/1/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	
ASBESTOS-ST17-5/1/07	030713726-0012	North Face - West end at corner (scaffolding level)	5/1/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/2/07	< 13.00	No	No	

Note:

- Asbestos sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on May 1, 2007 was not available for analysis on account of media damage.