

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality Levels	Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels											70			
ASBESTOS-ST1-6/5/06	030617157-0001	Southwest Area (sidewalk bridge level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST2-6/5/06	030617157-0002	Southeast Area (sidewalk bridge level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST4-6/5/06	030617157-0003	Northwest Area (street-level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST5-6/5/06	030617157-0004	Firehouse #10 (roof level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST10-6/5/06	030617157-0005	North Side Sidewalk Bridge	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST11-6/5/06	030617157-0006	90 Trinity Place (roof level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST12-6/5/06	030617157-0007	110 Greenwich Street (roof level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST13-6/5/06	030617157-0008	Marriott Hotel, 38th Floor (roof level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST14-6/5/06	030617157-0009	West Face - South end at corner (scaffolding level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST15-6/5/06	030617157-0010	South Face - East end at corner (scaffolding level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST16-6/5/06	030617157-0011	East Face - North end at corner (scaffolding level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST17-6/5/06	030617157-0012	North Face - West end at corner (scaffolding level)	6/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/6/06	< 13.00	No	No		
ASBESTOS-ST1-6/6/06	030617265-0001	Southwest Area (sidewalk bridge level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST2-6/6/06	030617265-0002	Southeast Area (sidewalk bridge level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST4-6/6/06	030617265-0003	Northwest Area (street-level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST5-6/6/06	030617265-0004	Firehouse #10 (roof level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST10-6/6/06	030617265-0005	North Side Sidewalk Bridge	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST11-6/6/06	030617265-0006	90 Trinity Place (roof level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST12-6/6/06	030617265-0007	110 Greenwich Street (roof level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST13-6/6/06	030617265-0008	Marriott Hotel, 38th Floor (roof level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST14-6/6/06	030617265-0009	West Face - South end at corner (scaffolding level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST15-6/6/06	030617265-0010	South Face - East end at corner (scaffolding level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST16-6/6/06	030617265-0011	East Face - North end at corner (scaffolding level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST17-6/6/06	030617265-0012	North Face - West end at corner (scaffolding level)	6/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/06	< 13.00	No	No		
ASBESTOS-ST1-6/7/06	030617455-0001	Southwest Area (sidewalk bridge level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST2-6/7/06	030617455-0002	Southeast Area (sidewalk bridge level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST4-6/7/06	030617455-0003	Northwest Area (street-level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST5-6/7/06	030617455-0004	Firehouse #10 (roof level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST10-6/7/06	030617455-0005	North Side Sidewalk Bridge	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST11-6/7/06	030617455-0006	90 Trinity Place (roof level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST12-6/7/06	030617455-0007	110 Greenwich Street (roof level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST13-6/7/06	030617455-0008	Marriott Hotel, 38th Floor (roof level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST14-6/7/06	030617455-0009	West Face - South end at corner (scaffolding level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST15-6/7/06	030617455-0010	South Face - East end at corner (scaffolding level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST16-6/7/06	030617455-0011	East Face - North end at corner (scaffolding level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		
ASBESTOS-ST17-6/7/06	030617455-0012	North Face - West end at corner (scaffolding level)	6/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/06	< 13.00	No	No		