

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-6/29/09	030916274-0001	Southwest Area (sidewalk bridge level)	6/29/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/30/09	< 15.00	No	No	
ASBESTOS-ST2-6/29/09	030916274-0002	Southeast Area (sidewalk bridge level)	6/29/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/30/09	< 15.00	No	No	
ASBESTOS-ST4-6/29/09	030916274-0003	Northwest Area (street-level)	6/29/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/30/09	< 13.00	No	No	
ASBESTOS-ST5-6/29/09	030916274-0004	Firehouse #10 (roof level)	6/29/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/30/09	< 15.00	No	No	
ASBESTOS-ST10-6/29/09	030916274-0005	North Side Sidewalk Bridge	6/29/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/30/09	< 15.00	No	No	
ASBESTOS-ST11-6/29/09	030916274-0006	90 Trinity Place (roof level)	6/29/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/30/09	< 13.00	No	No	
ASBESTOS-ST12-6/29/09	030916274-0007	110 Greenwich Street (roof level)	6/29/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/30/09	< 13.00	No	No	
ASBESTOS-ST13-6/29/09	030916274-0008	Marriott Hotel, 38th Floor (roof level)	6/29/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/30/09	< 13.00	No	No	
ASBESTOS-ST1-6/30/09	030916429-0001	Southwest Area (sidewalk bridge level)	6/30/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/1/09	< 13.00	No	No	
ASBESTOS-ST2-6/30/09	030916429-0002	Southeast Area (sidewalk bridge level)	6/30/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/1/09	< 13.00	No	No	
ASBESTOS-ST4-6/30/09	030916429-0003	Northwest Area (street-level)	6/30/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/1/09	< 13.00	No	No	
ASBESTOS-ST5-6/30/09	030916429-0004	Firehouse #10 (roof level)	6/30/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/1/09	< 13.00	No	No	
ASBESTOS-ST10-6/30/09	030916429-0005	North Side Sidewalk Bridge	6/30/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/1/09	< 13.00	No	No	
ASBESTOS-ST11-6/30/09	030916429-0006	90 Trinity Place (roof level)	6/30/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/1/09	< 13.00	No	No	
ASBESTOS-ST12-6/30/09	030916429-0007	110 Greenwich Street (roof level)	6/30/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/1/09	< 13.00	No	No	
ASBESTOS-ST13-6/30/09	030916429-0008	Marriott Hotel, 38th Floor (roof level)	6/30/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/1/09	< 13.00	No	No	
ASBESTOS-ST1-7/1/09	030916566-0001	Southwest Area (sidewalk bridge level)	7/1/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/09	< 13.00	No	No	
ASBESTOS-ST2-7/1/09	030916566-0002	Southeast Area (sidewalk bridge level)	7/1/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/09	< 13.00	No	No	
ASBESTOS-ST4-7/1/09	030916566-0003	Northwest Area (street-level)	7/1/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/09	< 13.00	No	No	
ASBESTOS-ST5-7/1/09	030916566-0004	Firehouse #10 (roof level)	7/1/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/09	< 13.00	No	No	
ASBESTOS-ST10-7/1/09	030916566-0005	North Side Sidewalk Bridge	7/1/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/09	< 13.00	No	No	
ASBESTOS-ST100-7/1/09	030916566-0009	Station 10 Field Duplicate	7/1/09	1	3.250	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/09	< 13.00	No	No	
ASBESTOS-ST11-7/1/09	030916566-0006	90 Trinity Place (roof level)	7/1/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/09	< 13.00	No	No	
ASBESTOS-ST12-7/1/09	030916566-0007	110 Greenwich Street (roof level)	7/1/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/09	< 13.00	No	No	
ASBESTOS-ST13-7/1/09	030916566-0008	Marriott Hotel, 38th Floor (roof level)	7/1/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/2/09	< 13.00	No	No	
ASBESTOS-ST1-7/2/09	030916634-0001	Southwest Area (sidewalk bridge level)	7/2/09	1	2.200	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/09	< 9.60	No	No	Note 1
ASBESTOS-ST2-7/2/09	030916634-0002	Southeast Area (sidewalk bridge level)	7/2/09	1	2.270	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/09	< 9.60	No	No	Note 2
ASBESTOS-ST4-7/2/09	030916634-0003	Northwest Area (street-level)	7/2/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/09	< 13.00	No	No	
ASBESTOS-ST5-7/2/09	030916634-0004	Firehouse #10 (roof level)	7/2/09	1	2.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/09	< 9.60	No	No	Note 2
ASBESTOS-ST10-7/2/09	030916634-0005	North Side Sidewalk Bridge	7/2/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/09	< 13.00	No	No	
ASBESTOS-ST11-7/2/09	030916634-0006	90 Trinity Place (roof level)	7/2/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/09	< 13.00	No	No	
ASBESTOS-ST12-7/2/09	030916634-0007	110 Greenwich Street (roof level)	7/2/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/09	< 13.00	No	No	
ASBESTOS-ST13-7/2/09	030916634-0008	Marriott Hotel, 38th Floor (roof level)	7/2/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/3/09	< 13.00	No	No	

Note:

1. The asbestos sample from Station 1 (Southwest Area [sidewalk bridge level]) on July 2, 2009 has a reduced volume due to a 380 minute planned power outage.
2. The asbestos samples from Station 2 (Southeast Area [sidewalk bridge level]) and Station 5 (Firehouse #10 [roof level]) on July 2, 2009 have a reduced volume due to a 360 minute planned power outage.