

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels											70	Levels	Trigger Levels	
ASBESTOS-ST1-7/12/06	030621562-0001	Southwest Area (sidewalk bridge level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST2-7/12/06	030621562-0002	Southeast Area (sidewalk bridge level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST4-7/12/06	030621562-0003	Northwest Area (street-level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST5-7/12/06	030621562-0004	Firehouse #10 (roof level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST6-7/12/06	030621564-0001	Southwest Area (roof level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST7-7/12/06	030621564-0002	Southeast Area (roof level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST8-7/12/06	030621564-0003	Northeast Area (roof level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST9-7/12/06	030621564-0004	Northwest Area (roof level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST10-7/12/06	030621562-0005	North Side Sidewalk Bridge	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST11-7/12/06	030621562-0006	90 Trinity Place (roof level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST12-7/12/06	030621562-0007	110 Greenwich Street (roof level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST13-7/12/06	030621562-0008	Marriott Hotel, 38th Floor (roof level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST14-7/12/06	030621562-0009	West Face - South end at corner (scaffolding level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST15-7/12/06	030621562-0010	South Face - East end at corner (scaffolding level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST16-7/12/06	030621562-0011	East Face - North end at corner (scaffolding level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST17-7/12/06	030621562-0012	North Face - West end at corner (scaffolding level)	7/12/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/13/06	< 13.00	No	No		
ASBESTOS-ST1-7/13/06	030621717-0001	Southwest Area (sidewalk bridge level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST2-7/13/06	030621717-0002	Southeast Area (sidewalk bridge level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST4-7/13/06	030621717-0003	Northwest Area (street-level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST5-7/13/06	030621717-0004	Firehouse #10 (roof level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST6-7/13/06	030621719-0001	Southwest Area (roof level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST7-7/13/06	030621719-0002	Southeast Area (roof level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST8-7/13/06	030621719-0003	Northeast Area (roof level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST9-7/13/06	030621719-0004	Northwest Area (roof level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST10-7/13/06	030621717-0005	North Side Sidewalk Bridge	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST100-7/13/06	030621717-0013	Station 10 Field Duplicate	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST11-7/13/06	030621717-0006	90 Trinity Place (roof level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST12-7/13/06	030621717-0007	110 Greenwich Street (roof level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST13-7/13/06	030621717-0008	Marriott Hotel, 38th Floor (roof level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST14-7/13/06	030621717-0009	West Face - South end at corner (scaffolding level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST15-7/13/06	030621717-0010	South Face - East end at corner (scaffolding level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST16-7/13/06	030621717-0011	East Face - North end at corner (scaffolding level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		
ASBESTOS-ST17-7/13/06	030621717-0012	North Face - West end at corner (scaffolding level)	7/13/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/06	< 13.00	No	No		