

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target | Exceeds EPA | Comments |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|--------------------|------------------------------|----------|
| | | | | | | | | | | NA | Air Quality Levels | Site Specific Trigger Levels | |
| | | | | | | | | | | 70 | | | |
| Target Air Quality Levels | | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | | | |
| ASBESTOS-ST1-8/5/09 | 030920294-0001 | Southwest Area (sidewalk bridge level) | 8/5/09 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/6/09 | < 13.00 | No | No | |
| ASBESTOS-ST2-8/5/09 | 030920294-0002 | Southeast Area (sidewalk bridge level) | 8/5/09 | 1 | 3.110 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/6/09 | < 13.00 | No | No | |
| ASBESTOS-ST4-8/5/09 | 030920294-0003 | Northwest Area (street-level) | 8/5/09 | 1 | 2.920 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/6/09 | < 13.00 | No | No | |
| ASBESTOS-ST5-8/5/09 | 030920294-0004 | Firehouse #10 (roof level) | 8/5/09 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/6/09 | < 13.00 | No | No | |
| ASBESTOS-ST10-8/5/09 | 030920294-0005 | North Side Sidewalk Bridge | 8/5/09 | 1 | 3.070 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/6/09 | < 13.00 | No | No | |
| ASBESTOS-ST11-8/5/09 | 030920294-0006 | 90 Trinity Place (roof level) | 8/5/09 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/6/09 | < 13.00 | No | No | |
| ASBESTOS-ST12-8/5/09 | 030920294-0007 | 110 Greenwich Street (roof level) | 8/5/09 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/6/09 | < 13.00 | No | No | |
| ASBESTOS-ST13-8/5/09 | 030920294-0008 | Marriott Hotel, 38th Floor (roof level) | 8/5/09 | 1 | 3.080 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/6/09 | < 13.00 | No | No | |
| ASBESTOS-ST1-8/6/09 | 030920434-0001 | Southwest Area (sidewalk bridge level) | 8/6/09 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/7/09 | < 13.00 | No | No | |
| ASBESTOS-ST2-8/6/09 | 030920434-0002 | Southeast Area (sidewalk bridge level) | 8/6/09 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/7/09 | < 13.00 | No | No | |
| ASBESTOS-ST4-8/6/09 | 030920434-0003 | Northwest Area (street-level) | 8/6/09 | 1 | 2.980 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/7/09 | < 13.00 | No | No | |
| ASBESTOS-ST10-8/6/09 | 030920434-0004 | North Side Sidewalk Bridge | 8/6/09 | 1 | 2.960 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/7/09 | < 13.00 | No | No | |
| ASBESTOS-ST11-8/6/09 | 030920434-0005 | 90 Trinity Place (roof level) | 8/6/09 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/7/09 | < 13.00 | No | No | |
| ASBESTOS-ST12-8/6/09 | 030920434-0006 | 110 Greenwich Street (roof level) | 8/6/09 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/7/09 | < 13.00 | No | No | |
| ASBESTOS-ST13-8/6/09 | 030920434-0007 | Marriott Hotel, 38th Floor (roof level) | 8/6/09 | 1 | 3.080 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/7/09 | < 13.00 | No | No | |
| ASBESTOS-ST1-8/7/09 | 030920503-0001 | Southwest Area (sidewalk bridge level) | 8/7/09 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/8/09 | < 13.00 | No | No | |
| ASBESTOS-ST2-8/7/09 | 030920503-0002 | Southeast Area (sidewalk bridge level) | 8/7/09 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/8/09 | < 13.00 | No | No | |
| ASBESTOS-ST4-8/7/09 | 030920503-0003 | Northwest Area (street-level) | 8/7/09 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/8/09 | < 13.00 | No | No | |
| ASBESTOS-ST5-8/7/09 | 030920503-0004 | Firehouse #10 (roof level) | 8/7/09 | 1 | 3.100 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/8/09 | < 13.00 | No | No | |
| ASBESTOS-ST10-8/7/09 | 030920503-0005 | North Side Sidewalk Bridge | 8/7/09 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/8/09 | < 13.00 | No | No | |
| ASBESTOS-ST11-8/7/09 | 030920503-0006 | 90 Trinity Place (roof level) | 8/7/09 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/8/09 | < 13.00 | No | No | |
| ASBESTOS-ST12-8/7/09 | 030920503-0007 | 110 Greenwich Street (roof level) | 8/7/09 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/8/09 | < 13.00 | No | No | |
| ASBESTOS-ST13-8/7/09 | 030920503-0008 | Marriott Hotel, 38th Floor (roof level) | 8/7/09 | 1 | 3.120 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 8/8/09 | < 13.00 | No | No | |

Note:

1. The asbestos sample from Station 5 (Firehouse #10 [roof level]) on August 6, 2009 was not available for analysis on account of pump failure.