

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA	70			
Target Air Quality Levels											Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments	
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-8/18/06	030627220-0001	Southwest Area (sidewalk bridge level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST2-8/18/06	030627220-0002	Southeast Area (sidewalk bridge level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST4-8/18/06	030627220-0003	Northwest Area (street-level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST5-8/18/06	030627220-0004	Firehouse #10 (roof level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST6-8/18/06	030627221-0001	Southwest Area (roof level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST7-8/18/06	030627221-0002	Southeast Area (roof level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST8-8/18/06	030627221-0003	Northeast Area (roof level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST9-8/18/06	030627221-0004	Northwest Area (roof level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST10-8/18/06	030627220-0005	North Side Sidewalk Bridge	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST11-8/18/06	030627220-0006	90 Trinity Place (roof level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST12-8/18/06	030627220-0007	110 Greenwich Street (roof level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST13-8/18/06	030627220-0008	Marriott Hotel, 38th Floor (roof level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST14-8/18/06	030627220-0009	West Face - South end at corner (scaffolding level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST15-8/18/06	030627220-0010	South Face - East end at corner (scaffolding level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST16-8/18/06	030627220-0011	East Face - North end at corner (scaffolding level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST17-8/18/06	030627220-0012	North Face - West end at corner (scaffolding level)	8/18/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST1-8/19/06	030627222-0001	Southwest Area (sidewalk bridge level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST2-8/19/06	030627222-0002	Southeast Area (sidewalk bridge level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST4-8/19/06	030627222-0003	Northwest Area (street-level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST5-8/19/06	030627222-0004	Firehouse #10 (roof level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST6-8/19/06	030627223-0001	Southwest Area (roof level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST7-8/19/06	030627223-0002	Southeast Area (roof level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST9-8/19/06	030627223-0003	Northwest Area (roof level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST10-8/19/06	030627222-0005	North Side Sidewalk Bridge	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST11-8/19/06	030627222-0006	90 Trinity Place (roof level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST12-8/19/06	030627222-0007	110 Greenwich Street (roof level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST13-8/19/06	030627222-0008	Marriott Hotel, 38th Floor (roof level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST14-8/19/06	030627222-0009	West Face - South end at corner (scaffolding level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST15-8/19/06	030627222-0010	South Face - East end at corner (scaffolding level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST16-8/19/06	030627222-0011	East Face - North end at corner (scaffolding level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST17-8/19/06	030627222-0012	North Face - West end at corner (scaffolding level)	8/19/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST1-8/20/06	030627224-0001	Southwest Area (sidewalk bridge level)	8/20/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST2-8/20/06	030627224-0002	Southeast Area (sidewalk bridge level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST4-8/20/06	030627224-0003	Northwest Area (street-level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST5-8/20/06	030627224-0004	Firehouse #10 (roof level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST6-8/20/06	030627225-0001	Southwest Area (roof level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST7-8/20/06	030627225-0002	Southeast Area (roof level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST8-8/20/06	030627225-0003	Northeast Area (roof level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST9-8/20/06	030627225-0004	Northwest Area (roof level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST10-8/20/06	030627224-0005	North Side Sidewalk Bridge	8/20/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST11-8/20/06	030627224-0006	90 Trinity Place (roof level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST12-8/20/06	030627224-0007	110 Greenwich Street (roof level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST13-8/20/06	030627224-0008	Marriott Hotel, 38th Floor (roof level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST14-8/20/06	030627224-0009	West Face - South end at corner (scaffolding level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST15-8/20/06	030627224-0010	South Face - East end at corner (scaffolding level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST16-8/20/06	030627224-0011	East Face - North end at corner (scaffolding level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	
ASBESTOS-ST17-8/20/06	030627224-0012	North Face - West end at corner (scaffolding level)	8/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/21/06	< 13.00		No	No	

Note:

- Asbestos sample at Station 8 (Northeast Area [roof level]) on August 19, 2006 was not available for analysis on account of temporary power failure.