

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-8/30/08	030830513-0001	Southwest Area (sidewalk bridge level)	8/30/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST2-8/30/08	030830513-0002	Southeast Area (sidewalk bridge level)	8/30/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST4-8/30/08	030830513-0003	Northwest Area (street-level)	8/30/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST5-8/30/08	030830513-0004	Firehouse #10 (roof level)	8/30/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST10-8/30/08	030830513-0005	North Side Sidewalk Bridge	8/30/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST11-8/30/08	030830513-0006	90 Trinity Place (roof level)	8/30/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST12-8/30/08	030830513-0007	110 Greenwich Street (roof level)	8/30/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST13-8/30/08	030830513-0008	Marriott Hotel, 38th Floor (roof level)	8/30/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST14-8/30/08	030830513-0009	West Face - South end at corner (scaffolding level)	8/30/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST15-8/30/08	030830513-0010	South Face - East end at corner (scaffolding level)	8/30/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST16-8/30/08	030830513-0011	East Face - North end at corner (scaffolding level)	8/30/08	1	2.860	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST17-8/30/08	030830513-0012	North Face - West end at corner (scaffolding level)	8/30/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST1-8/31/08	030830514-0001	Southwest Area (sidewalk bridge level)	8/31/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 15.00	No	No		
ASBESTOS-ST2-8/31/08	030830514-0002	Southeast Area (sidewalk bridge level)	8/31/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST4-8/31/08	030830514-0003	Northwest Area (street-level)	8/31/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST5-8/31/08	030830514-0004	Firehouse #10 (roof level)	8/31/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST10-8/31/08	030830514-0005	North Side Sidewalk Bridge	8/31/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 15.00	No	No		
ASBESTOS-ST11-8/31/08	030830514-0006	90 Trinity Place (roof level)	8/31/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST12-8/31/08	030830514-0007	110 Greenwich Street (roof level)	8/31/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 15.00	No	No		
ASBESTOS-ST13-8/31/08	030830514-0008	Marriott Hotel, 38th Floor (roof level)	8/31/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 15.00	No	No		
ASBESTOS-ST14-8/31/08	030830514-0009	West Face - South end at corner (scaffolding level)	8/31/08	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 15.00	No	No		
ASBESTOS-ST15-8/31/08	030830514-0010	South Face - East end at corner (scaffolding level)	8/31/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 15.00	No	No		
ASBESTOS-ST16-8/31/08	030830514-0011	East Face - North end at corner (scaffolding level)	8/31/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST17-8/31/08	030830514-0012	North Face - West end at corner (scaffolding level)	8/31/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 15.00	No	No		
ASBESTOS-ST1-9/1/08	030830526-0001	Southwest Area (sidewalk bridge level)	9/1/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST2-9/1/08	030830526-0002	Southeast Area (sidewalk bridge level)	9/1/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST4-9/1/08	030830526-0003	Northwest Area (street-level)	9/1/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST5-9/1/08	030830526-0004	Firehouse #10 (roof level)	9/1/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST10-9/1/08	030830526-0005	North Side Sidewalk Bridge	9/1/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST11-9/1/08	030830526-0006	90 Trinity Place (roof level)	9/1/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST12-9/1/08	030830526-0007	110 Greenwich Street (roof level)	9/1/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST13-9/1/08	030830526-0008	Marriott Hotel, 38th Floor (roof level)	9/1/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST14-9/1/08	030830526-0009	West Face - South end at corner (scaffolding level)	9/1/08	1	3.220	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST15-9/1/08	030830526-0010	South Face - East end at corner (scaffolding level)	9/1/08	1	3.260	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST16-9/1/08	030830526-0011	East Face - North end at corner (scaffolding level)	9/1/08	1	3.270	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST17-9/1/08	030830526-0012	North Face - West end at corner (scaffolding level)	9/1/08	1	3.250	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/2/08	< 13.00	No	No		
ASBESTOS-ST1-9/2/08	030830687-0001	Southwest Area (sidewalk bridge level)	9/2/08	1	3.200	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 15.00	No	No		
ASBESTOS-ST2-9/2/08	030830687-0002	Southeast Area (sidewalk bridge level)	9/2/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 15.00	No	No		
ASBESTOS-ST4-9/2/08	030830687-0003	Northwest Area (street-level)	9/2/08	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 15.00	No	No		
ASBESTOS-ST5-9/2/08	030830687-0004	Firehouse #10 (roof level)	9/2/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 15.00	No	No		
ASBESTOS-ST10-9/2/08	030830687-0005	North Side Sidewalk Bridge	9/2/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 13.00	No	No		
ASBESTOS-ST11-9/2/08	030830687-0006	90 Trinity Place (roof level)	9/2/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 13.00	No	No		
ASBESTOS-ST12-9/2/08	030830687-0007	110 Greenwich Street (roof level)	9/2/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 13.00	No	No		
ASBESTOS-ST13-9/2/08	030830687-0008	Marriott Hotel, 38th Floor (roof level)	9/2/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 13.00	No	No		
ASBESTOS-ST14-9/2/08	030830687-0009	West Face - South end at corner (scaffolding level)	9/2/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 13.00	No	No		
ASBESTOS-ST15-9/2/08	030830687-0010	South Face - East end at corner (scaffolding level)	9/2/08	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 15.00	No	No		
ASBESTOS-ST16-9/2/08	030830687-0011	East Face - North end at corner (scaffolding level)	9/2/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 15.00	No	No		
ASBESTOS-ST17-9/2/08	030830687-0012	North Face - West end at corner (scaffolding level)	9/2/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/3/08	< 15.00	No	No		