

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target | Exceeds EPA | Comments |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|----------------|----------------|----------|
| Target Air Quality Levels | | | | | | | | | | NA | Air Quality | Site Specific | Comments |
| EPA Site Specific Trigger Levels | | | | | | | | | | 70 | Levels | Trigger Levels | |
| ASBESTOS-ST1-9/1/07 | 030730134-0001 | Southwest Area (sidewalk bridge level) | 9/1/07 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |
| ASBESTOS-ST2-9/1/07 | 030730134-0002 | Southeast Area (sidewalk bridge level) | 9/1/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | 13.00 | No | No | |
| ASBESTOS-ST4-9/1/07 | 030730134-0003 | Northwest Area (street-level) | 9/1/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |
| ASBESTOS-ST5-9/1/07 | 030730134-0004 | Firehouse #10 (roof level) | 9/1/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |
| ASBESTOS-ST10-9/1/07 | 030730134-0005 | North Side Sidewalk Bridge | 9/1/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |
| ASBESTOS-ST11-9/1/07 | 030730134-0006 | 90 Trinity Place (roof level) | 9/1/07 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |
| ASBESTOS-ST12-9/1/07 | 030730134-0007 | 110 Greenwich Street (roof level) | 9/1/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |
| ASBESTOS-ST13-9/1/07 | 030730134-0008 | Marriott Hotel, 38th Floor (roof level) | 9/1/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |
| ASBESTOS-ST14-9/1/07 | 030730134-0009 | West Face - South end at corner (scaffolding level) | 9/1/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |
| ASBESTOS-ST15-9/1/07 | 030730134-0010 | South Face - East end at corner (scaffolding level) | 9/1/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |
| ASBESTOS-ST16-9/1/07 | 030730134-0011 | East Face - North end at corner (scaffolding level) | 9/1/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |
| ASBESTOS-ST17-9/1/07 | 030730134-0012 | North Face - West end at corner (scaffolding level) | 9/1/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/2/07 | < 13.00 | No | No | |