

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target | Exceeds EPA | Comments | |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|----------------|-------------|----------------|----------|
| Target Air Quality Levels | | | | | | | | | | | NA | Air Quality | Site Specific | Comments |
| EPA Site Specific Trigger Levels | | | | | | | | | | | 70 | Levels | Trigger Levels | |
| ASBESTOS-ST1-9/18/06 | 030630687-0001 | Southwest Area (sidewalk bridge level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST2-9/18/06 | 030630687-0002 | Southeast Area (sidewalk bridge level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST4-9/18/06 | 030630687-0003 | Northwest Area (street-level) | 9/18/06 | 1 | 3.150 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST5-9/18/06 | 030630687-0004 | Firehouse #10 (roof level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST6-9/18/06 | 030630700-0001 | Southwest Area (roof level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST7-9/18/06 | 030630700-0002 | Southeast Area (roof level) | 9/18/06 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST8-9/18/06 | 030630700-0003 | Northeast Area (roof level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST9-9/18/06 | 030630700-0004 | Northwest Area (roof level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST10-9/18/06 | 030630687-0005 | North Side Sidewalk Bridge | 9/18/06 | 1 | 3.090 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST11-9/18/06 | 030630687-0006 | 90 Trinity Place (roof level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST12-9/18/06 | 030630687-0007 | 110 Greenwich Street (roof level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST13-9/18/06 | 030630687-0008 | Marriott Hotel, 38th Floor (roof level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST14-9/18/06 | 030630687-0009 | West Face - South end at corner (scaffolding level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST14-9/18/06 | 030630687-0010 | West Face - South end at corner (scaffolding level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST16-9/18/06 | 030630687-0011 | East Face - North end at corner (scaffolding level) | 9/18/06 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST17-9/18/06 | 030630687-0012 | North Face - West end at corner (scaffolding level) | 9/18/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/19/06 | < 13.00 | No | No | | |
| ASBESTOS-ST1-9/19/06 | 030630806-0001 | Southwest Area (sidewalk bridge level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST2-9/19/06 | 030630806-0002 | Southeast Area (sidewalk bridge level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST4-9/19/06 | 030630806-0003 | Northwest Area (street-level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST5-9/19/06 | 030630806-0004 | Firehouse #10 (roof level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST6-9/19/06 | 030630807-0001 | Southwest Area (roof level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST7-9/19/06 | 030630807-0002 | Southeast Area (roof level) | 9/19/06 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST8-9/19/06 | 030630807-0003 | Northeast Area (roof level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST9-9/19/06 | 030630807-0004 | Northwest Area (roof level) | 9/19/06 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST10-9/19/06 | 030630806-0005 | North Side Sidewalk Bridge | 9/19/06 | 1 | 2.960 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST100-9/19/06 | 030630806-0013 | Station 10 Field Duplicate | 9/19/06 | 1 | 3.400 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | Note 1. | |
| ASBESTOS-ST11-9/19/06 | 030630806-0006 | 90 Trinity Place (roof level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST12-9/19/06 | 030630806-0007 | 110 Greenwich Street (roof level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST13-9/19/06 | 030630806-0008 | Marriott Hotel, 38th Floor (roof level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST14-9/19/06 | 030630806-0009 | West Face - South end at corner (scaffolding level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST15-9/19/06 | 030630806-0010 | South Face - East end at corner (scaffolding level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST16-9/19/06 | 030630806-0011 | East Face - North end at corner (scaffolding level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |
| ASBESTOS-ST17-9/19/06 | 030630806-0012 | North Face - West end at corner (scaffolding level) | 9/19/06 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 9/20/06 | < 13.00 | No | No | | |

Note:

1. Due to flow rate RPD exceedance (22.2%) for asbestos at Station 100 (Station 10 Field Duplicate) on September 19, 2006, the sample volume and subsequent sample result are estimated.