

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality Levels	Site Specific Trigger Levels	
										70			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-9/29/07	030732618-0001	Southwest Area (sidewalk bridge level)	9/29/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	
ASBESTOS-ST2-9/29/07	030732618-0002	Southeast Area (sidewalk bridge level)	9/29/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	
ASBESTOS-ST4-9/29/07	030732618-0003	Northwest Area (street-level)	9/29/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	
ASBESTOS-ST5-9/29/07	030732618-0004	Firehouse #10 (roof level)	9/29/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	
ASBESTOS-ST10-9/29/07	030732618-0005	North Side Sidewalk Bridge	9/29/07	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	
ASBESTOS-ST12-9/29/07	030732618-0006	110 Greenwich Street (roof level)	9/29/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST13-9/29/07	030732618-0007	Marriott Hotel, 38th Floor (roof level)	9/29/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	
ASBESTOS-ST14-9/29/07	030732618-0008	West Face - South end at corner (scaffolding level)	9/29/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	
ASBESTOS-ST15-9/29/07	030732618-0009	South Face - East end at corner (scaffolding level)	9/29/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	
ASBESTOS-ST16-9/29/07	030732618-0010	East Face - North end at corner (scaffolding level)	9/29/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST17-9/29/07	030732618-0011	North Face - West end at corner (scaffolding level)	9/29/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST1-9/30/07	030732627-0001	Southwest Area (sidewalk bridge level)	9/30/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST2-9/30/07	030732627-0002	Southeast Area (sidewalk bridge level)	9/30/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST4-9/30/07	030732627-0003	Northwest Area (street-level)	9/30/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST5-9/30/07	030732627-0004	Firehouse #10 (roof level)	9/30/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST10-9/30/07	030732627-0005	North Side Sidewalk Bridge	9/30/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST12-9/30/07	030732627-0006	110 Greenwich Street (roof level)	9/30/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST13-9/30/07	030732627-0007	Marriott Hotel, 38th Floor (roof level)	9/30/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST14-9/30/07	030732627-0008	West Face - South end at corner (scaffolding level)	9/30/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	
ASBESTOS-ST15-9/30/07	030732627-0009	South Face - East end at corner (scaffolding level)	9/30/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	
ASBESTOS-ST16-9/30/07	030732627-0010	East Face - North end at corner (scaffolding level)	9/30/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 15.00	No	No	
ASBESTOS-ST17-9/30/07	030732627-0011	North Face - West end at corner (scaffolding level)	9/30/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/1/07	< 13.00	No	No	

Note:

1. Asbestos sample at Station 11 (90 Trinity Place [roof level]) on September 29, 2007 was not available for analysis on account of timer malfunction.
2. Asbestos sample at Station 11 (90 Trinity Place [roof level]) on September 30, 2007 was not available for analysis on account of operator error.