

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										Target Air Quality Levels				
										NA	70			
ASBESTOS-ST1-10/1/08	030834791-0001	Southwest Area (sidewalk bridge level)	10/1/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST2-10/1/08	030834791-0002	Southeast Area (sidewalk bridge level)	10/1/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST4-10/1/08	030834791-0003	Northwest Area (street-level)	10/1/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST5-10/1/08	030834791-0004	Firehouse #10 (roof level)	10/1/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST10-10/1/08	030834791-0005	North Side Sidewalk Bridge	10/1/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST100-10/1/08	030834791-0013	Station 10 Field Duplicate	10/1/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST11-10/1/08	030834791-0006	90 Trinity Place (roof level)	10/1/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST12-10/1/08	030834791-0007	110 Greenwich Street (roof level)	10/1/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST13-10/1/08	030834791-0008	Marriott Hotel, 38th Floor (roof level)	10/1/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST14-10/1/08	030834791-0009	West Face - South end at corner (scaffolding level)	10/1/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST15-10/1/08	030834791-0010	South Face - East end at corner (scaffolding level)	10/1/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST16-10/1/08	030834791-0011	East Face - North end at corner (scaffolding level)	10/1/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST17-10/1/08	030834791-0012	North Face - West end at corner (scaffolding level)	10/1/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/08	< 13.00		No	No	
ASBESTOS-ST1-10/2/08	030834977-0001	Southwest Area (sidewalk bridge level)	10/2/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST2-10/2/08	030834977-0002	Southeast Area (sidewalk bridge level)	10/2/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST4-10/2/08	030834977-0003	Northwest Area (street-level)	10/2/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST5-10/2/08	030834977-0004	Firehouse #10 (roof level)	10/2/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST10-10/2/08	030834977-0005	North Side Sidewalk Bridge	10/2/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST11-10/2/08	030834977-0006	90 Trinity Place (roof level)	10/2/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST12-10/2/08	030834977-0007	110 Greenwich Street (roof level)	10/2/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST13-10/2/08	030834977-0008	Marriott Hotel, 38th Floor (roof level)	10/2/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST14-10/2/08	030834977-0009	West Face - South end at corner (scaffolding level)	10/2/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST15-10/2/08	030834977-0010	South Face - East end at corner (scaffolding level)	10/2/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST16-10/2/08	030834977-0011	East Face - North end at corner (scaffolding level)	10/2/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST17-10/2/08	030834977-0012	North Face - West end at corner (scaffolding level)	10/2/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/08	< 13.00		No	No	
ASBESTOS-ST1-10/3/08	030835101-0001	Southwest Area (sidewalk bridge level)	10/3/08	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST2-10/3/08	030835101-0002	Southeast Area (sidewalk bridge level)	10/3/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST4-10/3/08	030835101-0003	Northwest Area (street-level)	10/3/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST5-10/3/08	030835101-0004	Firehouse #10 (roof level)	10/3/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST10-10/3/08	030835101-0005	North Side Sidewalk Bridge	10/3/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST11-10/3/08	030835101-0006	90 Trinity Place (roof level)	10/3/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST12-10/3/08	030835101-0007	110 Greenwich Street (roof level)	10/3/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST13-10/3/08	030835101-0008	Marriott Hotel, 38th Floor (roof level)	10/3/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST14-10/3/08	030835101-0009	West Face - South end at corner (scaffolding level)	10/3/08	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST15-10/3/08	030835101-0010	South Face - East end at corner (scaffolding level)	10/3/08	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST16-10/3/08	030835101-0011	East Face - North end at corner (scaffolding level)	10/3/08	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST17-10/3/08	030835101-0012	North Face - West end at corner (scaffolding level)	10/3/08	1	2.810	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/08	< 13.00		No	No	
ASBESTOS-ST1-10/4/08	030835288-0001	Southwest Area (sidewalk bridge level)	10/4/08	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST2-10/4/08	030835288-0002	Southeast Area (sidewalk bridge level)	10/4/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST4-10/4/08	030835288-0003	Northwest Area (street-level)	10/4/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST5-10/4/08	030835288-0004	Firehouse #10 (roof level)	10/4/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST10-10/4/08	030835288-0005	North Side Sidewalk Bridge	10/4/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST11-10/4/08	030835288-0006	90 Trinity Place (roof level)	10/4/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST12-10/4/08	030835288-0007	110 Greenwich Street (roof level)	10/4/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST13-10/4/08	030835288-0008	Marriott Hotel, 38th Floor (roof level)	10/4/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST14-10/4/08	030835288-0009	West Face - South end at corner (scaffolding level)	10/4/08	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST15-10/4/08	030835288-0010	South Face - East end at corner (scaffolding level)	10/4/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST16-10/4/08	030835288-0011	East Face - North end at corner (scaffolding level)	10/4/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	
ASBESTOS-ST17-10/4/08	030835288-0012	North Face - West end at corner (scaffolding level)	10/4/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/08	< 13.00		No	No	