

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels											70	Levels	Trigger Levels	
ABESTOS-ST1-10/13/06	030633889-0001	Southwest Area (sidewalk bridge level)	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST2-10/13/06	030633889-0002	Southeast Area (sidewalk bridge level)	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST4-10/13/06	030633889-0003	Northwest Area (street-level)	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST5-10/13/06	030633889-0004	Firehouse #10 (roof level)	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST10-10/13/06	030633889-0005	North Side Sidewalk Bridge	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST100-10/13/06	030633889-0013	Station 10 Field Duplicate	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST11-10/13/06	030633889-0006	90 Trinity Place (roof level)	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST12-10/13/06	030633889-0007	110 Greenwich Street (roof level)	10/13/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST13-10/13/06	030633889-0008	Marriott Hotel, 38th Floor (roof level)	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST14-10/13/06	030633889-0009	West Face - South end at corner (scaffolding level)	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST15-10/13/06	030633889-0010	South Face - East end at corner (scaffolding level)	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST16-10/13/06	030633889-0011	East Face - North end at corner (scaffolding level)	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ABESTOS-ST17-10/13/06	030633889-0012	North Face - West end at corner (scaffolding level)	10/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST1-10/14/06	030633890-0001	Southwest Area (sidewalk bridge level)	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST2-10/14/06	030633890-0002	Southeast Area (sidewalk bridge level)	10/14/06	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST4-10/14/06	030633890-0003	Northwest Area (street-level)	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST5-10/14/06	030633890-0004	Firehouse #10 (roof level)	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST10-10/14/06	030633890-0005	North Side Sidewalk Bridge	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST11-10/14/06	030633890-0006	90 Trinity Place (roof level)	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST12-10/14/06	030633890-0007	110 Greenwich Street (roof level)	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST13-10/14/06	030633890-0008	Marriott Hotel, 38th Floor (roof level)	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST14-10/14/06	030633890-0009	West Face - South end at corner (scaffolding level)	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST15-10/14/06	030633890-0010	South Face - East end at corner (scaffolding level)	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST16-10/14/06	030633890-0011	East Face - North end at corner (scaffolding level)	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST17-10/14/06	030633890-0012	North Face - West end at corner (scaffolding level)	10/14/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST1-10/15/06	030633887-0001	Southwest Area (sidewalk bridge level)	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST2-10/15/06	030633887-0002	Southeast Area (sidewalk bridge level)	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST4-10/15/06	030633887-0003	Northwest Area (street-level)	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST5-10/15/06	030633887-0004	Firehouse #10 (roof level)	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST10-10/15/06	030633887-0005	North Side Sidewalk Bridge	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST11-10/15/06	030633887-0006	90 Trinity Place (roof level)	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST12-10/15/06	030633887-0007	110 Greenwich Street (roof level)	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST13-10/15/06	030633887-0008	Marriott Hotel, 38th Floor (roof level)	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST14-10/15/06	030633887-0009	West Face - South end at corner (scaffolding level)	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST15-10/15/06	030633887-0010	South Face - East end at corner (scaffolding level)	10/15/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST16-10/15/06	030633887-0011	East Face - North end at corner (scaffolding level)	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST17-10/15/06	030633887-0012	North Face - West end at corner (scaffolding level)	10/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/16/06	< 13.00	No	No		
ASBESTOS-ST1-10/16/06	030634025-0001	Southwest Area (sidewalk bridge level)	10/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST2-10/16/06	030634025-0002	Southeast Area (sidewalk bridge level)	10/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST4-10/16/06	030634025-0003	Northwest Area (street-level)	10/16/06	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST5-10/16/06	030634025-0004	Firehouse #10 (roof level)	10/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST10-10/16/06	030634025-0005	North Side Sidewalk Bridge	10/16/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST11-10/16/06	030634025-0006	90 Trinity Place (roof level)	10/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST12-10/16/06	030634025-0007	110 Greenwich Street (roof level)	10/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST13-10/16/06	030634025-0008	Marriott Hotel, 38th Floor (roof level)	10/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST14-10/16/06	030634025-0009	West Face - South end at corner (scaffolding level)	10/16/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST15-10/16/06	030634025-0010	South Face - East end at corner (scaffolding level)	10/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST16-10/16/06	030634025-0011	East Face - North end at corner (scaffolding level)	10/16/06	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		
ASBESTOS-ST17-10/16/06	030634025-0012	North Face - West end at corner (scaffolding level)	10/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/17/06	< 13.00	No	No		