

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA	70			
										EPA Site Specific Trigger Levels				
ASBESTOS-ST1-10/28/05	030532499-0001	Southwest Area (street-level)	10/28/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST2-10/28/05	030532499-0002	Southeast Area (sidewalk bridge level)	10/28/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST4-10/28/05	030532499-0003	Northwest Area (street-level)	10/28/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST5-10/28/05	030532499-0004	Firehouse #10 (roof level)	10/28/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST10-10/28/05	030532499-0005	North Side Sidewalk Bridge	10/28/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST11-10/28/05	030532499-0006	90 Trinity Place (roof level)	10/28/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST12-10/28/05	030532499-0007	110 Greenwich Street (roof level)	10/28/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST13-10/28/05	030532499-0008	Marriott Hotel, 38th Floor (roof level)	10/28/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST1-10/29/05	030532486-0001	Southwest Area (street-level)	10/29/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST2-10/29/05	030532486-0002	Southeast Area (sidewalk bridge level)	10/29/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST4-10/29/05	030532486-0003	Northwest Area (street-level)	10/29/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST5-10/29/05	030532486-0004	Firehouse #10 (roof level)	10/29/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST10-10/29/05	030532486-0005	North Side Sidewalk Bridge	10/29/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST11-10/29/05	030532486-0006	90 Trinity Place (roof level)	10/29/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST12-10/29/05	030532486-0007	110 Greenwich Street (roof level)	10/29/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST13-10/29/05	030532486-0008	Marriott Hotel, 38th Floor (roof level)	10/29/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 13.00		No	No	
ASBESTOS-ST1-10/30/05	030532497-0001	Southwest Area (street-level)	10/30/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST2-10/30/05	030532497-0002	Southeast Area (sidewalk bridge level)	10/30/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST4-10/30/05	030532497-0003	Northwest Area (street-level)	10/30/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST5-10/30/05	030532497-0004	Firehouse #10 (roof level)	10/30/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST10-10/30/05	030532497-0005	North Side Sidewalk Bridge	10/30/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST11-10/30/05	030532497-0006	90 Trinity Place (roof level)	10/30/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST12-10/30/05	030532497-0007	110 Greenwich Street (roof level)	10/30/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST13-10/30/05	030532497-0008	Marriott Hotel, 38th Floor (roof level)	10/30/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/31/2005	< 15.00		No	No	
ASBESTOS-ST1-10/31/05	030532613-0001	Southwest Area (street-level)	10/31/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/1/2005	< 13.00		No	No	
ASBESTOS-ST2-10/31/05	030532613-0002	Southeast Area (sidewalk bridge level)	10/31/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/1/2005	< 13.00		No	No	
ASBESTOS-ST4-10/31/05	030532613-0003	Northwest Area (street-level)	10/31/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/1/2005	< 13.00		No	No	
ASBESTOS-ST5-10/31/05	030532613-0004	Firehouse #10 (roof level)	10/31/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/1/2005	< 13.00		No	No	
ASBESTOS-ST10-10/31/05	030532613-0005	North Side Sidewalk Bridge	10/31/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/1/2005	< 13.00		No	No	
ASBESTOS-ST11-10/31/05	030532613-0006	90 Trinity Place (roof level)	10/31/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/1/2005	< 13.00		No	No	
ASBESTOS-ST12-10/31/05	030532613-0007	110 Greenwich Street (roof level)	10/31/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/1/2005	< 13.00		No	No	
ASBESTOS-ST13-10/31/05	030532613-0008	Marriott Hotel, 38th Floor (roof level)	10/31/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/1/2005	< 13.00		No	No	
ASBESTOS-ST1-11/1/05	030532732-0001	Southwest Area (street-level)	11/1/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/2/2005	< 13.00		No	No	
ASBESTOS-ST2-11/1/05	030532732-0002	Southeast Area (sidewalk bridge level)	11/1/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/2/2005	< 13.00		No	No	
ASBESTOS-ST4-11/1/05	030532732-0003	Northwest Area (street-level)	11/1/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/2/2005	< 13.00		No	No	
ASBESTOS-ST5-11/1/05	030532732-0004	Firehouse #10 (roof level)	11/1/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/2/2005	< 13.00		No	No	
ASBESTOS-ST10-11/1/05	030532732-0005	North Side Sidewalk Bridge	11/1/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/2/2005	< 13.00		No	No	
ASBESTOS-ST100-11/1/05	030532732-0009	Station 10 Field Duplicate	11/1/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/2/2005	< 13.00		No	No	
ASBESTOS-ST11-11/1/05	030532732-0006	90 Trinity Place (roof level)	11/1/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/2/2005	< 13.00		No	No	
ASBESTOS-ST12-11/1/05	030532732-0007	110 Greenwich Street (roof level)	11/1/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/2/2005	< 13.00		No	No	
ASBESTOS-ST13-11/1/05	030532732-0008	Marriott Hotel, 38th Floor (roof level)	11/1/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/2/2005	< 13.00		No	No	