

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels											70	Levels	Trigger Levels	
ASBESTOS-ST1-11/8/08	030839931-0001	Southwest Area (sidewalk bridge level)	11/8/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST2-11/8/08	030839931-0002	Southeast Area (sidewalk bridge level)	11/8/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST4-11/8/08	030839931-0003	Northwest Area (street-level)	11/8/08	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST5-11/8/08	030839931-0004	Firehouse #10 (roof level)	11/8/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST10-11/8/08	030839931-0005	North Side Sidewalk Bridge	11/8/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST11-11/8/08	030839931-0006	90 Trinity Place (roof level)	11/8/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST12-11/8/08	030839931-0007	110 Greenwich Street (roof level)	11/8/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST13-11/8/08	030839931-0008	Marriott Hotel, 38th Floor (roof level)	11/8/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST14-11/8/08	030839931-0009	West Face - South end at corner (scaffolding level)	11/8/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST15-11/8/08	030839931-0010	South Face - East end at corner (scaffolding level)	11/8/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST16-11/8/08	030839931-0011	East Face - North end at corner (scaffolding level)	11/8/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST17-11/8/08	030839931-0012	North Face - West end at corner (scaffolding level)	11/8/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST1-11/9/08	030839933-0001	Southwest Area (sidewalk bridge level)	11/9/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST2-11/9/08	030839933-0002	Southeast Area (sidewalk bridge level)	11/9/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST4-11/9/08	030839933-0003	Northwest Area (street-level)	11/9/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST5-11/9/08	030839933-0004	Firehouse #10 (roof level)	11/9/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST10-11/9/08	030839933-0005	North Side Sidewalk Bridge	11/9/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST11-11/9/08	030839933-0006	90 Trinity Place (roof level)	11/9/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST12-11/9/08	030839933-0007	110 Greenwich Street (roof level)	11/9/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST13-11/9/08	030839933-0008	Marriott Hotel, 38th Floor (roof level)	11/9/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST14-11/9/08	030839933-0009	West Face - South end at corner (scaffolding level)	11/9/08	1	3.320	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST15-11/9/08	030839933-0010	South Face - East end at corner (scaffolding level)	11/9/08	1	3.310	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST16-11/9/08	030839933-0011	East Face - North end at corner (scaffolding level)	11/9/08	1	3.340	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST17-11/9/08	030839933-0012	North Face - West end at corner (scaffolding level)	11/9/08	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/10/08	< 13.00	No	No		
ASBESTOS-ST1-11/10/08	030840125-0001	Southwest Area (sidewalk bridge level)	11/10/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST2-11/10/08	030840125-0002	Southeast Area (sidewalk bridge level)	11/10/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST4-11/10/08	030840125-0003	Northwest Area (street-level)	11/10/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST5-11/10/08	030840125-0004	Firehouse #10 (roof level)	11/10/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST10-11/10/08	030840125-0005	North Side Sidewalk Bridge	11/10/08	1	2.830	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST11-11/10/08	030840125-0006	90 Trinity Place (roof level)	11/10/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST12-11/10/08	030840125-0007	110 Greenwich Street (roof level)	11/10/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST13-11/10/08	030840125-0008	Marriott Hotel, 38th Floor (roof level)	11/10/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST14-11/10/08	030840125-0009	West Face - South end at corner (scaffolding level)	11/10/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST15-11/10/08	030840125-0010	South Face - East end at corner (scaffolding level)	11/10/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST16-11/10/08	030840125-0011	East Face - North end at corner (scaffolding level)	11/10/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST17-11/10/08	030840125-0012	North Face - West end at corner (scaffolding level)	11/10/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/08	< 13.00	No	No		
ASBESTOS-ST1-11/11/08	030840263-0001	Southwest Area (sidewalk bridge level)	11/11/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST2-11/11/08	030840263-0002	Southeast Area (sidewalk bridge level)	11/11/08	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST4-11/11/08	030840263-0003	Northwest Area (street-level)	11/11/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST5-11/11/08	030840263-0004	Firehouse #10 (roof level)	11/11/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST10-11/11/08	030840263-0005	North Side Sidewalk Bridge	11/11/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST11-11/11/08	030840263-0006	90 Trinity Place (roof level)	11/11/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST12-11/11/08	030840263-0007	110 Greenwich Street (roof level)	11/11/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST13-11/11/08	030840263-0008	Marriott Hotel, 38th Floor (roof level)	11/11/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST14-11/11/08	030840263-0009	West Face - South end at corner (scaffolding level)	11/11/08	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST15-11/11/08	030840263-0010	South Face - East end at corner (scaffolding level)	11/11/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST16-11/11/08	030840263-0011	East Face - North end at corner (scaffolding level)	11/11/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		
ASBESTOS-ST17-11/11/08	030840263-0012	North Face - West end at corner (scaffolding level)	11/11/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/12/08	< 13.00	No	No		

Note:

1. Due to a final flow rate below 2.0 lpm for asbestos at Station 10 (North Side Sidewalk Bridge) on November 9, 2008, the sample volume and subsequent sample result are estimated.